statements by participants and encourage all interested parties to share their views on issues affecting this rulemaking. Each participant will be allowed to make a general statement (within time limits determined by DOE), before the discussion of specific topics. DOE will permit, as time permits, other participants to comment briefly on any general statements.

At the end of all prepared statements on a topic, DOE will permit participants to clarify their statements briefly. Participants should be prepared to answer questions by DOE and by other participants concerning these issues. DOE representatives may also ask questions of participants concerning other matters relevant to this rulemaking. The official conducting the webinar will accept additional comments or questions from those attending, as time permits. The presiding official will announce any further procedural rules or modification of the above procedures that may be needed for the proper conduct of the webinar.

A transcript of the webinar will be included in the docket, which can be viewed as described in the Docket section at the beginning of this document. In addition, any person may buy a copy of the transcript from the transcribing reporter.

Signing Authority

This document of the Department of Energy was signed on February 3, 2022, by Kelly J. Speakes-Backman, Principal Deputy Assistant Secretary for Energy Efficiency and Renewable Energy, pursuant to delegated authority from the Secretary of Energy. That document with the original signature and date is maintained by DOE. For administrative purposes only, and in compliance with requirements of the Office of the Federal Register, the undersigned DOE Federal Register Liaison Officer has been authorized to sign and submit the document in electronic format for publication, as an official document of the Department of Energy. This administrative process in no way alters the legal effect of this document upon publication in the Federal Register.

Signed in Washington, DC, on February 4, 2022.

Treena V. Garrett,

Federal Register Liaison Officer, U.S. Department of Energy.

[FR Doc. 2022-02713 Filed 2-8-22; 8:45 am]

BILLING CODE 6450-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0086; Project Identifier MCAI-2021-01035-T]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking

(NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2021–13–06, which applies to certain Airbus SAS Model A350–941 and –1041 airplanes. AD 2021-13-06 requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. Since the FAA issued AD 2021-13-06, the FAA has determined that new or more restrictive airworthiness limitations are necessary. This proposed AD would continue to require the actions in AD 2021-13-06 and require revising the existing maintenance or inspection program, as applicable, to incorporate additional new or more restrictive airworthiness limitations, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by March 28, 2022. **ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to https://www.regulations.gov. Follow the instructions for submitting comments.
 - Fax: 202-493-2251.
- *Mail*: U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- Hand Delivery: U.S. Department of Transportation, Docket Operations, M— 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material that will be incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@* easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at https://ad.easa.europa.eu. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket on the internet at https://www.regulations.gov by searching for and locating Docket No. FAA–2022–0086.

Examining the AD Docket

You may examine the AD docket on the internet at https://www.regulations.gov by searching for and locating Docket No. FAA-2022-0086; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3225; email dan.rodina@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under ADDRESSES. Include "Docket No. FAA-2022-0086; Project Identifier MCAI-2021-01035-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to https://www.regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this proposed AD.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3225; email dan.rodina@ faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Discussion

The FAA issued AD 2021-13-06, Amendment 39-21611 (86 FR 40934, July 30, 2021) (AD 2021-13-06), for certain Airbus SAS Model A350-941 and -1041 airplanes. AD 2021-13-06 requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA issued AD 2021–13–06 to address hazardous or catastrophic airplane system failures. AD 2021-13-06 specifies that accomplishing the actions required by AD 2021-13-06 terminates the repetitive greasing task for batch 02 group of affected thrust reverser actuators required by paragraph (g) of AD 2019-20-01, Amendment 39-19754 (84 FR 55495, October 17, 2019) (AD 2019-20-01).

Actions Since AD 2021–13–06 Was Issued

Since the FAA issued AD 2021–13–06, the FAA has determined that new or more restrictive airworthiness limitations are necessary.

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021–0208, dated September 15, 2021 (EASA AD 2021–0208) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all Airbus SAS

Model A350–941 and –1041 airplanes. Airplanes with an original airworthiness certificate or original export certificate of airworthiness issued after July 20, 2021 must comply with the airworthiness limitations specified as part of the approved type design and referenced on the type certificate data sheet; this proposed AD therefore does not include those airplanes in the applicability.

This proposed AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is proposing this AD to address hazardous or catastrophic airplane system failures. See the MCAI for additional background information.

Related Service Information Under 1 CFR Part 51

EASA AD 2021–0208 describes new or more restrictive airworthiness limitations for airplane structures and safe life limits.

This proposed AD would also require EASA AD 2020–0211, dated October 5, 2020, and EASA AD 2021–0026, dated January 20, 2021, which the Director of the Federal Register approved for incorporation by reference as of September 3, 2021 (86 FR 40934, July 30, 2021).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the FAA has evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Proposed AD Requirements

This proposed AD would retain the requirements of AD 2021–13–06. This proposed AD would also require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, which are specified in EASA AD 2021–0208 described previously, as incorporated by reference. Any differences with EASA AD 2021–0208 are identified as

exceptions in the regulatory text of this AD.

This proposed AD would require revisions to certain operator maintenance documents to include new actions (e.g., inspections). Compliance with these actions is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this proposed AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (n)(1) of this proposed AD.

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2021-0208 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2021–0208 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2021-0208 does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times,' compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in EASA AD 2021-0208. Service information required by EASA AD 2021-0208 for compliance will be available at https://www.regulations.gov by searching for and locating Docket No. FAA-2022-0086 after the FAA final rule is published.

Airworthiness Limitation ADs Using the New Process

The FAA's process of incorporating by reference MCAI ADs as the primary source of information for compliance with corresponding FAA ADs has been limited to certain MCAI ADs (primarily those with service bulletins as the primary source of information for accomplishing the actions required by the FAA AD). However, the FAA is now expanding the process to include MCAI ADs that require a change to

airworthiness limitation documents, such as airworthiness limitation sections.

For these ADs that incorporate by reference an MCAI AD that changes airworthiness limitations, the FAA requirements are unchanged. Operators must revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in the new airworthiness limitation document. The airworthiness limitations must be followed according to 14 CFR 91.403(c) and 91.409(e).

The previous format of the airworthiness limitation ADs included a paragraph that specified that no alternative actions (e.g., inspections) or intervals may be used unless the actions and intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in the AMOCs paragraph under "Other FAA Provisions." This new format includes a "New Provisions for Alternative Actions and Intervals" paragraph that does not specifically refer to AMOCs, but operators may still request an AMOC to use an alternative action or interval.

Costs of Compliance

The FAA estimates that this proposed AD affects 27 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

The FAA estimates the total cost per operator for the retained actions from AD 2021–13–06 to be \$7,650 (90 workhours \times \$85 per work-hour).

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 workhours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate.

The FAA estimates the total cost per operator for the new proposed actions to be \$7,650 (90 work-hours \times \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§39.13 [Amended]

- 2. The FAA amends § 39.13 by:
- a. Removing Airworthiness Directive (AD) 2021–13–06, Amendment 39–21611 (86 FR 40934, July 30, 2021); and
- b. Adding the following new AD:

Airbus SAS: Docket No. FAA-2022-0086; Project Identifier MCAI-2021-01035-T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by March 28, 2022.

(b) Affected ADs

- (1) This AD replaces AD 2021–13–06, Amendment 39–21611 (86 FR 40934, July 30, 2021) (AD 2021–13–06).
- (2) This AD affects AD 2019–20–01, Amendment 39–19754 (84 FR 55495, October 17, 2019) (AD 2019–20–01).

(c) Applicability

This AD applies to Airbus SAS Model A350–941 and -1041 airplanes, certificated in any category, with an original airworthiness certificate or original export certificate of airworthiness issued on or before July 20, 2021.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address hazardous or catastrophic airplane system failures.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done

(g) Retained Maintenance or Inspection Program Revision, With No Changes

This paragraph restates the requirements of paragraph (g) of AD 2021-13-06, with no changes. For airplanes with an original airworthiness certificate or original export certificate of airworthiness issued on or before July 22, 2020: Except as specified in paragraph (h) of this AD, comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2020-0211, dated October 5, 2020 (EASA AD 2020-0211); and EASA AD 2021-0026, dated January 20, 2021 (EASA AD 2021-0026). Where EASA AD 2021-0026 affects the same airworthiness limitations (tasks and life limits) as those in EASA AD 2020–0211, the airworthiness limitations referenced in EASA AD 2021-0026 prevail. Accomplishing the revision of the existing maintenance or inspection program required by paragraph (j) of this AD terminates the requirements of this paragraph.

(h) Retained Exceptions to EASA AD 2020–0211 and EASA AD 2021–0026, With No Changes

This paragraph restates the requirements of paragraph (h) of AD 2021–13–06, with no changes. For airplanes with an original airworthiness certificate or original export certificate of airworthiness issued on or before July 22, 2020:

- (1) Where EASA AD 2020–0211 and EASA AD 2021–0026 refers to its effective date, this AD requires using September 3, 2021 (the effective date of AD 2021–13–06).
- (2) The requirements specified in paragraphs (1) and (2) of EASA AD 2020–0211 and EASA AD 2021–0026 do not apply to this AD.
- (3) Paragraph (3) of EASA AD 2020–0211 and EASA AD 2021–0026 specifies revising

"the approved AMP [aircraft maintenance program]" within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, to incorporate the "limitations, tasks and associated thresholds and intervals" specified in paragraph (3) of EASA AD 2020–0211 and EASA AD 2021–0026 within 90 days after September 3, 2021 (the effective date of AD 2021–13–06).

- (4) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2020–0211 and EASA AD 2021–0026 is at the applicable "thresholds" as incorporated by the requirements of paragraph (3) of EASA AD 2020–0211 and EASA AD 2021–0026, or within 90 days after September 3, 2021 (the effective date of AD 2021–13–06), whichever occurs later.
- (5) The provisions specified in paragraphs (4) and (5) of EASA AD 2020–0211 do not apply to this AD.
- (6) The provisions specified in paragraph (4) of EASA AD 2021–0026 do not apply to this AD.
- (7) The "Remarks" section of EASA AD 2020–0211 and EASA AD 2021–0026 does not apply to this AD.

(i) Retained Provisions for Alternative Actions and Intervals, With a New Exception

This paragraph restates the requirements of paragraph (i) of AD 2021–13–06, with a new exception. For airplanes with an original airworthiness certificate or original export certificate of airworthiness issued on or before July 22, 2020: Except as required by paragraph (j) of this AD, after the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) and intervals are allowed unless they are approved as specified in the provisions of the "Ref. Publications" section of EASA AD 2020–0211 or EASA AD 2021–0026.

(j) New Maintenance or Inspection Program Revision

Except as specified in paragraph (k) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021–0208, dated September 15, 2021. Accomplishing the revision of the existing maintenance or inspection program required by this paragraph terminates the requirements of paragraph (g) of this AD.

(k) Exceptions to EASA AD 2021-0208

- (1) Where EASA AD 2021–0208 refers to its effective date, this AD requires using the effective date of this AD.
- (2) The requirements specified in paragraphs (1) and (2) of EASA AD 2021–0208 do not apply to this AD.
- (3) Paragraph (3) of EASA AD 2021–0208 specifies to revise "the AMP" within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after the effective date of this AD.
- (4) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2021–0208 is at the applicable "limitations" as incorporated by the requirements of paragraph (3) of EASA AD 2021–0208, or within 90 days after the

- effective date of this AD, whichever occurs later.
- (5) The provisions specified in paragraphs (4) and (5) of EASA AD 2021–0208 do not apply to this AD.
- (6) The "Remarks" section of EASA AD 2021–0208 does not apply to this AD.
- (7) Where EASA AD 2021–0208 refers to Airbus A350 Airworthiness Limitations Section (ALS) Part 4, Revision 6 and Variation 6.1, replace the text "Airbus A350 Airworthiness Limitations Section (ALS) Part 4, Revision 6 and Variation 6.1," with "Airbus A350 Airworthiness Limitations Section (ALS) Part 4, Revision 6 and Variation 6.1; for any airworthiness limitations (tasks and life limits) that are in both documents, the airworthiness limitations (tasks and life limits) specified in Variation 6.1 prevail."

(l) New Provisions for Alternative Actions and Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (j) of this AD, no alternative actions (e.g., inspections) and intervals are allowed unless they are approved as specified in the provisions of the "Ref. Publications" section of EASA AD 2021–0208.

(m) Terminating Action for Certain Requirements of AD 2019–20–01

Accomplishing the actions required by paragraph (g) or (j) of this AD terminates the repetitive greasing task for batch 02 group of affected thrust reverser actuators required by paragraph (g) of AD 2019–20–01.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (o)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(o) Related Information

(1) For the EASA ADs identified in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@ easa.europa.eu; internet www.easa.europa.eu. You may find these EASA ADs on the EASA website at https://ad.easa.europa.eu. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at https://www.regulations.gov by searching for and locating Docket No. FAA–2022–0086.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3225; email dan.rodina@faa.gov.

Issued on January 31, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–02317 Filed 2–8–22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2022-0038; Airspace Docket No. 22-AEA-1]

RIN 2120-AA66

Proposed Amendment of Class E Airspace; Greenville, PA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend the Class E airspace at Greenville, PA. The FAA is proposing this action as the result of an airspace review caused by the decommissioning of the Youngstown VHF omnidirectional range (VOR) navigation aids as part of the VOR Minimum Operational Network (MON) Program. **DATES:** Comments must be received on or before March 28, 2022.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590; telephone (202) 366–9826, or (800) 647–5527. You must identify FAA Docket No. FAA–2022–0038/Airspace Docket No. 22–AEA–1, at the beginning of your comments. You may also submit comments through the internet at https://www.regulations.gov. You may review the public docket containing the proposal, any comments