

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Leonardo S.p.a.: Docket No. FAA–2022–1419; Project Identifier MCAI–2022–01002–R.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by December 27, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Leonardo S.p.a. Model AB139 and AW139 helicopters, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6400, Tail Rotor System.

(e) Unsafe Condition

This AD was prompted by a report of a damaged tail rotor duplex bearing (TRDB) that was improperly installed on a sliding control assembly. The FAA is issuing this AD to ensure the proper installation of a TRDB and prevent a TRDB from remaining in service beyond its life limit. The unsafe condition, if not detected and corrected, could lead to structural failure of the TRDB, possibly resulting in loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) Emergency AD 2022–0182–E, dated August 30, 2022 (EASA AD 2022–0182–E).

(h) Exceptions to EASA AD 2022–0182–E

(1) Where EASA AD 2022–0182–E requires compliance in terms of flight hours, this AD requires using hours time-in-service (TIS).

(2) Where EASA AD 2022–0182–E refers to July 28, 2022 (the effective date of EASA AD 2022–0152–E, dated July 26, 2022) and its effective date, this AD requires using the effective date of this AD.

(3) Where the service information referenced in EASA AD 2022–0182–E specifies discarding certain parts, this AD requires removing those parts from service.

(4) Where the service information referenced in EASA AD 2022–0182–E specifies returning a part to the manufacturer, this AD does not require that action.

(5) The “Remarks” section of EASA AD 2022–0182–E does not apply to this AD.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2022–0182–E specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Additional Information

(1) Refer to EASA AD 2022–0182–E for related information. This EASA AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–1419.

(2) For more information about this AD, contact Dan McCully, Program Manager, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1701 Columbia Ave., Mail Stop: ACO, College Park, GA 30337; telephone (404) 474–5548; email william.mccully@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) Emergency AD 2022–0182–E, dated August 30, 2022.

(ii) Reserved.

(3) For EASA AD 2022–0182–E, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu. You may find

this material on the EASA website at ad.easa.europa.eu.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on November 3, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–24430 Filed 11–9–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2022–0396; Project Identifier MCAI–2021–01050–T]

RIN 2120–AA64

Airworthiness Directives; ATR–GIE Avions de Transport Régional Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Supplemental notice of proposed rulemaking (SNPRM).

SUMMARY: The FAA proposes to revise a notice of proposed rulemaking (NPRM) to supersede Airworthiness Directive (AD) 2021–09–13, which applies to certain ATR–GIE Avions de Transport Régional Model ATR42–500 airplanes. This action revises the NPRM by including additional new or more restrictive airworthiness limitations. The FAA is proposing this AD to address the unsafe condition on these products. Since this action would impose an additional burden over those in the NPRM, the FAA is reopening the comment period to allow the public the chance to comment on these changes.

DATES: The FAA must receive comments on this SNPRM by December 27, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- *Fax:* 202–493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–

30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–0396; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, this SNPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For material that is proposed for incorporation by reference in this SNPRM, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–0396.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

FOR FURTHER INFORMATION CONTACT:

Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3220; email shahram.daneshmandi@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2022–0396; Project Identifier MCAI–2021–01050–T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments

received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this SNPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this SNPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this SNPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this SNPRM. Submissions containing CBI should be sent to Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3220; email shahram.daneshmandi@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2021–09–13, Amendment 39–21527 (86 FR 27031, May 19, 2021) (AD 2021–09–13), for certain ATR–GIE Avions de Transport Régional Model ATR42–500 airplanes. AD 2021–09–13 requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA issued AD 2021–09–13 to prevent reduced structural integrity of the airplane.

The FAA issued an NPRM to amend 14 CFR part 39 by adding an AD to supersede AD 2021–09–13 that would apply to certain ATR–GIE Avions de Transport Régional Model ATR42–500 airplanes. The NPRM published in the **Federal Register** on April 8, 2022 (87 FR 20783) (the NPRM). The NPRM was prompted by MCAI originated by the European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union. EASA issued AD 2021–0212, dated September 17, 2021 (EASA AD 2021–0212), to correct an unsafe condition. The NPRM proposed to

retain the requirements of AD 2021–09–13. The NPRM also proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations.

Actions Since the NPRM Was Issued

Since the FAA issued the NPRM, EASA superseded EASA AD 2021–0212 and issued EASA AD 2022–0063, dated April 8, 2022 (EASA AD 2022–0063). EASA AD 2022–0063 was issued because ATR–GIE Avions de Transport published Revision 16 of the ATR 42–400/–500 Time Limits Document (TLD), which included new or more restrictive maintenance tasks and airworthiness limitations. EASA subsequently superseded EASA AD 2022–0063 and issued EASA AD 2022–0200, dated September 26, 2022 (EASA AD 2022–0200) (also referred to after this as the MCAI). EASA AD 2022–0200 states that since EASA AD 2022–0063 was issued, ATR–GIE Avions de Transport published Revision 17 of the ATR 42–400/–500 TLD, which includes new or more restrictive maintenance tasks and airworthiness limitations.

EASA AD 2022–0200 applies to all ATR–GIE Avions de Transport Régional Model ATR42–400 and –500 airplanes. Model ATR42–400 airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this proposed AD therefore does not include those airplanes in the applicability. Airplanes with an original airworthiness certificate or original export certificate of airworthiness issued after July 29, 2022, must comply with the airworthiness limitations specified as part of the approved type design and referenced on the type certificate data sheet; this proposed AD therefore does not include those airplanes in the applicability.

The FAA is proposing this AD to prevent reduced structural integrity of the airplane. You may examine EASA AD 2022–0200 in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–0396.

Comments

The FAA received a comment from The Air Line Pilots Association, International (ALPA), who supported the NPRM without change.

Related Service Information Under 1 CFR Part 51

EASA AD 2022–0200 describes new or more restrictive maintenance tasks and airworthiness limitations for airplane structures and for safe life limits of the components.

This proposed AD would also require EASA AD 2020–0263, dated December 1, 2020, which the Director of the Federal Register approved for incorporation by reference as of June 23, 2021 (86 FR 27031, May 19, 2021).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI described above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of these same type designs.

Certain changes described above expand the scope of the NPRM. As a result, it is necessary to reopen the comment period to provide additional opportunity for the public to comment on this SNPRM.

Proposed AD Requirements in This SNPRM

This proposed AD would retain the requirements of AD 2021–09–13. This proposed AD would also require revising the existing maintenance or inspection program, as applicable, to incorporate additional new or more restrictive maintenance tasks and airworthiness limitations, which are specified in EASA AD 2022–0200 described previously, as proposed for incorporation by reference. Any differences with EASA AD 2022–0200 are identified as exceptions in the regulatory text of this AD.

This proposed AD would require revisions to certain operator maintenance documents to include new actions (e.g., inspections) and Critical Design Configuration Control Limitations (CDCCLs). Compliance with these actions and CDCCLs is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this proposed AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance (AMOC) according to paragraph (m)(1) of this proposed AD.

Costs of Compliance

The FAA estimates that this proposed AD affects 9 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

The FAA estimates the total cost per operator for the retained actions from AD 2021–09–13 to be \$7,650 (90 work-hours × \$85 per work-hour).

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate.

The FAA estimates the total cost per operator for the new proposed actions to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
- a. Removing Airworthiness Directive (AD) 2021–09–13, Amendment 39–21527 (86 FR 27031, May 19, 2021); and
 - b. Adding the following new AD:

ATR–GIE Avions de Transport Régional:
Docket No. FAA–2022–0396; Project Identifier MCAI–2021–01050–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by December 27, 2022.

(b) Affected ADs

This AD replaces AD 2021–09–13, Amendment 39–21527 (86 FR 27031, May 19, 2021) (AD 2021–09–13).

(c) Applicability

This AD applies to ATR–GIE Avions de Transport Régional Model ATR42–500 airplanes, certificated in any category, with an original airworthiness certificate or original export certificate of airworthiness issued on or before July 29, 2022.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Unsafe Condition

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to prevent reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Revision of the Existing Maintenance or Inspection Program, With a New Terminating Action

This paragraph restates the requirements of paragraph (j) of AD 2021–09–13, with a new

terminating action. For airplanes with an original airworthiness certificate or original export certificate of airworthiness dated on or before July 7, 2020: Except as specified in paragraph (h) of this AD, comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2020–0263, dated December 1, 2020 (EASA AD 2020–0263). Accomplishing the revision of the existing maintenance or inspection program required by paragraph (j) of this AD terminates the requirements of this paragraph.

(h) Retained Exceptions to EASA AD 2020–0263, With No Changes

This paragraph restates the exceptions specified in paragraph (k) of AD 2021–09–13, with no changes. For airplanes with an original airworthiness certificate or original export certificate of airworthiness dated on or before July 7, 2020, the following exceptions apply:

(1) The requirements specified in paragraphs (1) and (2) of EASA AD 2020–0263 do not apply to this AD.

(2) Paragraph (3) of EASA AD 2020–0263 specifies revising “the approved AMP [Aircraft Maintenance Program]” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after June 23, 2021 (the effective date of AD 2021–09–13).

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA 2020–0263 is at the applicable “thresholds” as incorporated by the requirements of paragraph (3) of EASA AD 2020–0263, or within 90 days after June 23, 2021 (the effective date of AD 2021–09–13), whichever occurs later.

(4) The provisions specified in paragraphs (4) and (5) of EASA AD 2020–0263 do not apply to this AD.

(5) The “Remarks” section of EASA AD 2020–0263 does not apply to this AD.

(i) Retained Restrictions on Alternative Actions, Intervals, and Critical Design Configuration Control Limitations (CDCCLs), With a New Exception

This paragraph restates the requirements of paragraph (l) of AD 2021–09–13, with a new exception. Except as required by paragraph (j) of this AD, after the maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, and CDCCLs are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2020–0263.

(j) New Revision of the Existing Maintenance or Inspection Program

Except as specified in paragraph (k) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2022–0200, dated September 26, 2022 (EASA AD 2022–0200). Accomplishing the revision of the existing maintenance or inspection program required by this paragraph terminates the requirements of paragraph (g) of this AD.

(k) Exceptions to EASA AD 2022–0200

(1) The requirements specified in paragraph (1) and (2) of EASA AD 2022–0200 do not apply to this AD.

(2) Paragraph (3) of EASA AD 2022–0200 specifies revising “the approved AMP” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2022–0200 is at the applicable “limitations” and “associated thresholds” as incorporated by the requirements of paragraph (3) of EASA AD 2022–0200, or within 90 days after the effective date of this AD, whichever occurs later.

(4) The provisions specified in paragraphs (4) and (5) of EASA AD 2022–0200 do not apply to this AD.

(5) The “Remarks” section of EASA AD 2022–0200 does not apply to this AD.

(l) New Provisions for Alternative Actions, Intervals, and CDCCLs

After the existing maintenance or inspection program has been revised as required by paragraph (j) of this AD, no alternative actions (e.g., inspections), intervals, and CDCCLs are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2022–0200.

(m) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (n) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or ATR–GIE Avions de Transport Régional’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(n) Additional Information

For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3220; email shahram.daneshmandi@faa.gov.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on December 15, 2022.

(i) European Union Aviation Safety Agency (EASA) AD 2022–0200, dated September 26, 2022.

(ii) [Reserved]

(4) The following service information was approved for IBR on June 23, 2021 (86 FR 27031, May 19, 2021).

(i) EASA AD 2020–0263, dated December 1, 2020.

(ii) [Reserved]

(5) For EASA ADs 2022–0200 and 2020–0263, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu.

(6) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on November 5, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–24542 Filed 11–9–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2022–1308; Project Identifier MCAI–2022–00532–T]

RIN 2120–AA64

Airworthiness Directives; Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Airplanes

Editorial Note: Proposed rule document 2022–23012 was originally published on pages 65538 through 65541 in the issue of Monday, October 31, 2022. In that publication on page 65541, in the second column, under the “(m) Material Incorporated by Reference” heading, paragraph “(3)”, “December 5, 2022” should read “[DATE 35 DAYS AFTER