This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-1206; Project Identifier MCAI-2023-00068-T]

RIN 2120-AA64

Airworthiness Directives; ATR–GIE Avions de Transport Régional Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all ATR-GIE Avions de Transport Régional Model ATR42 and ATR72 airplanes. This proposed AD was prompted by a determination that some batches of nose landing gear (NLG) drag brace panels (DBP) having certain part numbers were affected by a quality deficiency that was not detected in production. This proposed AD would require a measurement of the affected part and, depending on findings, accomplishment of applicable corrective actions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). This proposed AD would also prohibit the installation of affected parts. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by July 24, 2023. **ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

• *Federal eRulemaking Portal:* Go to *regulations.gov.* Follow the instructions for submitting comments.

• *Fax:* 202–493–2251.

• *Mail:* U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA–2023–1206; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference: • For EASA material that is proposed for IBR in this NPRM, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@easa.europa.eu;* website *easa.europa.eu*. You may find this material on the EASA website at *ad.easa.europa.eu*. It is also available at *regulations.gov* under Docket No. FAA– 2023–1206.

• For Safran Landing Systems SAS service information identified in this NPRM, contact Safran Landing Systems SAS, Inovel Parc Sud—7, rue Général Valérie André, 78140 VELIZY-VILLACOUBLAY—FRANCE; telephone +33 (0) 1 46 29 81 00, website *safranlanding-systems.com*.

• You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3220; email *shahram.daneshmandi@faa.gov.*

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA–2023–1206; Project Identifier MCAI–2023–00068–T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Federal Register Vol. 88, No. 110

Thursday, June 8, 2023

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3220; email shahram.daneshmandi@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2023–0010, dated January 17, 2023 (EASA AD 2023–0010) (also referred to as the MCAI), to correct an unsafe condition for all ATR–GIE Avions de Transport Régional Model ATR 42–200, ATR 42– 300, ATR 42–320, ATR 42–400, ATR 42–500, ATR 72–101, ATR 72–102, ATR 72–201, ATR 72–202, ATR 72–211, ATR 72–212, and ATR 72–212A airplanes. Model ATR 42–400 airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this proposed AD therefore does not include those airplanes in the applicability.

¹ The MCAI states that it has been determined that some batches of NLG DBP having part number (P/N) D63757 and P/N D69085 were affected by a quality deficiency that was not detected in production. Consequently, this issue could lead to NLG DBP dissymmetry at the lower area, which might affect the structural strength of the NLG DBP. This condition, if not addressed, could lead to NLG DBP structural fatigue failure and subsequent collapse of the NLG, possibly resulting in damage to the airplane and injury to occupants.

The FAA is proposing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2023–1206.

Related Service Information Under 1 CFR Part 51

EASA AD 2023–0010 specifies procedures for measuring the affected part and, depending on findings, accomplishing applicable corrective actions. Corrective actions could include obtaining and carrying out repair instructions, or replacing the affected part with a serviceable part. EASA AD 2033–0010 also specifies procedures for reporting measurement findings to ATR–GIE and prohibits the installation of affected parts.

Safran Landing Systems SAS Service Bulletin 631–32–286, dated October 28, 2022, provides the list of affected parts and specifies measurement procedures.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

FAA's Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2023–0010 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD

ESTIMATED COSTS FOR REQUIRED ACTIONS

process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2023–0010 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2023-0010 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2023–0010 does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times,' compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in EASA AD 2023-0010. Service information required by EASA AD 2023–0010 for compliance will be available at regulations.gov under Docket No. FAA-2023-1206 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 73 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

Labor costParts costCost per
productCost on U.S.
operators2 work-hours × \$85 per hour = \$170\$0\$170\$12,410

The FAA has received no definitive data on which to base the cost estimates for the on-condition actions specified in this proposed AD.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to take approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177–1524.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

 (1) Is not a "significant regulatory action" under Executive Order 12866,
(2) Would not affect intrastate

aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

ATR-GIE Avions de Transport Régional: Docket No. FAA–2023–1206; Project Identifier MCAI–2023–00068–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by July 24, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all ATR–GIE Avions de Transport Régional Model ATR42–200, –300, –320, and –500; and ATR72–101, –102, –201, –202, –211, –212, and –212A airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Unsafe Condition

This AD was prompted by a determination that some batches of nose landing gear (NLG) drag brace panels (DBP) having part number (P/N) D63757 and P/N D69085 were affected by a quality deficiency that was not detected in production. The FAA is issuing this AD to address the possibility of a resulting NLG DBP dissymmetry at the lower area, which might affect the structural strength of the NLG DBP. This condition, if not addressed, could lead to NLG DBP structural fatigue failure and subsequent collapse of the NLG, possibly resulting in damage to the airplane and injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2023–0010, dated January 17, 2023 (EASA AD 2023–0010).

(h) Exceptions to EASA AD 2023-0010

(1) Where EASA AD 2023–0010 refers to its effective date, this AD requires using the effective date of this AD.

(2) This AD does not adopt the "Remarks" section of EASA AD 2023–0010.

(3) Where EASA AD 2023–0010 defines "the SB," for this AD, operators must use Safran Landing Systems SAS Service Bulletin 631–32–286, dated October 28, 2022.

(4) Paragraph (2) of EASA AD 2023–0010 specifies to report measurement results to Safran Landing Systems SAS within a certain compliance time. For this AD, report inspection results at the applicable time specified in paragraph (h)(4)(i) or (ii) of this AD, but do not exceed the compliance time specified in Table 1 of EASA AD 2023–0010.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or ATR–GIE Avions

de Transport Régional's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Additional Information

For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3220; email shahram.daneshmandi@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2023–0010, dated January 17, 2023.

(ii) Safran Landing Systems SAS Service Bulletin 631–32–286, dated October 28, 2022.

(3) For EASA AD 2023–0010, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@easa.europa.eu;* website *easa.europa.eu.* You may find this EASA AD on the EASA website at *ad.easa.europa.eu.*

(4) For service information identified in this AD, contact Safran Landing Systems SAS, Inovel Parc Sud-7, rue Général Valérie André, 78140 VELIZY-VILLACOUBLAY-FRANCE; telephone +33 (0) 1 46 29 81 00, website *safran-landing-systems.com*.

(5) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email *fr.inspection@nara.gov*, or go to: *www.archives.gov/federal-register/cfr/ibrlocations.html.*

Issued on June 2, 2023.

Michael Linegang,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service. [FR Doc. 2023–12156 Filed 6–7–23; 8:45 am]

BILLING CODE 4910-13-P