

CATEGORIES AND REGULATIONS ADDRESSED IN THE SECOND FEDERAL REGISTER NOTICE—Continued

| Subject  | National banks             | State member banks                 | State non-member banks      | Federal savings associations | State savings associations  | BHCs & FHCs<br>-----<br>SLHCs                 |
|--|----------------------------|------------------------------------|-----------------------------|------------------------------|-----------------------------|---|
| <b>FDIC Regulations</b>                        |                            |                                    |                             |                              |                             |   |
| Golden Parachute and Indemnification Payments. | 12 CFR part 359.           | 12 CFR part 359.                   | 12 CFR part 359.            | 12 CFR part 359.             | 12 CFR part 359 .....       | 12 CFR part 359.<br>-----<br>12 CFR part 359. |
| <b>Money Laundering</b>                        |                            |                                    |                             |                              |                             |   |
| <b>Interagency Regulations</b>                 |                            |                                    |                             |                              |                             |   |
| Bank Secrecy Act Compliance .....              | 12 CFR part 21, subpart C. | 12 CFR 208.63 [Reg. H].            | 12 CFR part 326, subpart B. | 12 CFR part 21, subpart C.   | 12 CFR part 326, subpart B. |   |
| Reports of Crimes or Suspected Crimes.         | 12 CFR part 21, subpart B. | 12 CFR 208.62 and 208.63 [Reg. H]. | 12 CFR part 353.            | 12 CFR 163.180(d).           | 12 CFR part 353 .....       | 12 CFR 225.4(f) [Reg. Y].                     |

<sup>1</sup> Regulations for which rulemaking authority has transferred to the CFPB are not included in this Consumer Protection category. As described in the **SUPPLEMENTARY INFORMATION** section of this document, the CFPB is required to review its significant rules and publish a report of its review no later than five years after they take effect in a process separate from the EGRPRA process.

**Michael J. Hsu,**  
*Acting Comptroller of the Currency.*

By order of the Board of Governors of the Federal Reserve System.

**Ann E. Misback,**  
*Secretary of the Board.*

Federal Deposit Insurance Corporation.

By order of the Board of Directors.

Dated at Washington, DC, on June 20, 2024.

**James P. Sheesley,**  
*Assistant Executive Secretary.*

[FR Doc. 2024-16729 Filed 7-31-24; 8:45 am]

**BILLING CODE 4810-33-P; 6210-01-P; 6714-01-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA-2024-2008; Project Identifier AD-2024-00122-T]

RIN 2120-AA64

**Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all The Boeing Company Model 787-8, 787-9, and 787-10 airplanes. This proposed AD was prompted by a report that during manufacture of drag brace lower lock link assemblies for the main landing gear (MLG), a certain required inspection was not performed. This proposed AD would require doing a check of maintenance records or an inspection to determine if certain drag

brace lower lock link assemblies are installed, and applicable on-condition actions. This proposed AD would also prohibit the installation of affected parts. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by September 16, 2024.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at *regulations.gov* under Docket No. FAA-2024-2008; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference:*

- For the material identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone

562-797-1717; website *myboeingfleet.com*.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at *regulations.gov* under Docket No. FAA-2024-2008.

**FOR FURTHER INFORMATION CONTACT:** Joseph Hodgin, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3962; email: *joseph.j.hodgin@faa.gov*.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2024-2008; Project Identifier AD-2024-00122-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

**Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Joseph Hodgin, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3962; email: [joseph.j.hodgin@faa.gov](mailto:joseph.j.hodgin@faa.gov). Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Background**

The FAA has received a report from Boeing that during manufacture of four drag brace lower lock link assemblies for the MLG, a fluorescent penetrant inspection was not performed. The subsequent investigation determined that the quality escape was caused by human error and has been isolated to a single technician. Undetected cracks

could lead to fracture of the drag brace lower lock link assembly. This condition, if not addressed, could lead to MLG collapse, which could result in loss of directional control while the airplane is on the ground, with the potential for off-runway excursion or penetration of the wing box fuel tank.

**FAA’s Determination**

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

**Material Incorporated by Reference Under 1 CFR Part 51**

The FAA reviewed Boeing Alert Requirements Bulletin B787-81205-SB320048-00 RB, Issue 001, dated November 20, 2023. This material specifies procedures for doing a check of maintenance records or an inspection of the drag brace lower lock link assembly on the right and left MLG for affected serial numbers and applicable on-condition actions. On-condition actions include replacing any affected drag brace lower lock link assembly on the MLG with a serviceable drag brace lower lock link assembly. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**Proposed AD Requirements in This NPRM**

This proposed AD would require accomplishing the actions specified in

the material already described, except as discussed under “Differences Between this Proposed AD and the Referenced Material,” and except for any differences identified as exceptions in the regulatory text of this proposed AD. This proposed AD would also prohibit the installation of affected parts. For information on the procedures and compliance times, see this material at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-2008.

**Differences Between This Proposed AD and the Referenced Material**

The effectivity of Boeing Alert Requirements Bulletin B787-81205-SB320048-00 RB, Issue 001, dated November 20, 2023, is limited to Model 787-8, 787-9, and 787-10 airplanes, line numbers 6 through 1168 inclusive. However, the applicability of this proposed AD includes all The Boeing Company Model 787-8, 787-9, and 787-10 airplanes. Because the affected drag brace lower lock link assemblies are rotatable parts, the FAA has determined that these parts could later be installed on airplanes that were initially delivered with acceptable drag brace lower lock link assemblies, thereby subjecting those airplanes to the unsafe condition.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 156 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

| Action                            | Labor cost                               | Parts cost | Cost per product | Cost on U.S. operators |
|-----------------------------------|--|------------|------------------|------------------------|
| Inspection or records check ..... | 1 work-hour × \$85 per hour = \$85 ..... | \$0        | \$85             | \$13,260               |

The FAA estimates the following costs to do any necessary replacement that would be required based on the

results of the proposed inspection. The agency has no way of determining the

number of aircraft that might need this replacement:

**ON-CONDITION COSTS**

| Action  | Labor cost                                    | Parts cost | Cost per product |
|---|---|------------|------------------|
| Replacement of one drag brace lower lock link assembly. | 18 work-hours × \$85 per hour = \$1,530 ..... | \$39,119   | \$40,649         |

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this proposed AD may be covered under warranty, thereby

reducing the cost impact on affected operators.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue

rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**The Boeing Company:** Docket No. FAA–2024–2008; Project Identifier AD–2024–00122–T.

#### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by September 16, 2024.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all The Boeing Company Model 787–8, 787–9, and 787–10 airplanes, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

#### (e) Unsafe Condition

This AD was prompted by a report that during manufacture of drag brace lower lock link assemblies for the main landing gear (MLG), a certain inspection was not performed. The FAA is issuing this AD to address undetected cracks that could lead to fracture of the drag brace lower lock link assembly. The unsafe condition, if not addressed, could result in MLG collapse, which could result in loss of directional control while the airplane is on the ground, with the potential for off-runway excursion or penetration of the wing box fuel tank.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

For airplanes with an original airworthiness certificate or original export certificate of airworthiness issued on or before the effective date of this AD: Except as specified by paragraph (h) of this AD, at the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin B787–81205–SB320048–00 RB, Issue 001, dated November 20, 2023, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin B787–81205–SB320048–00 RB, Issue 001, dated November 20, 2023. The actions specified in Boeing Alert Requirements Bulletin B787–81205–SB320048–00 RB, Issue 001, dated November 20, 2023, apply to airplanes not listed in Boeing Alert Requirements Bulletin B787–81205–SB320048–00 RB, Issue 001, dated November 20, 2023.

**Note 1 to paragraph (g):** Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin B787–81205–SB320048–00, Issue 001, dated November 20, 2023, which is referred to in Boeing Alert Requirements Bulletin B787–81205–SB320048–00 RB, Issue 001, dated November 20, 2023.

#### (h) Exceptions to Service Information Specifications

Where the Compliance Time column of the table in the “Compliance” paragraph of Boeing Alert Requirements Bulletin B787–81205–SB320048–00 RB, Issue 001, dated November 20, 2023, refers to the Issue 001 date of Requirements Bulletin B787–81205–SB320048–00 RB, this AD requires using the effective date of this AD.

#### (i) Parts Installation Prohibition

As of the effective date of this AD, no person may install a drag brace lower lock

link assembly, part number 531Z2010–501 and serial number 19ZHQ00772, 19ZHQ00773, 19ZHQ00890, or 19ZHQ00891, on any airplane.

#### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: [AMOC@faa.gov](mailto:AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

#### (k) Related Information

(1) For more information about this AD, contact Joseph Hodgin, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3962; email: [joseph.j.hodgin@faa.gov](mailto:joseph.j.hodgin@faa.gov).

(2) Material identified in this AD that is not incorporated by reference is available at the address specified in paragraph (l)(3) of this AD.

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin B787–81205–SB320048–00 RB, Issue 001, dated November 20, 2023.

(ii) [Reserved]

(3) For the material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website [myboeingfleet.com](http://myboeingfleet.com).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA,

visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on July 26, 2024.

**Peter A. White,**

*Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.*

[FR Doc. 2024–16975 Filed 7–31–24; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 73

[Docket No. FAA–2024–1993; Airspace Docket No. 23–AEA–7]

RIN 2120–AA66

#### Amendment of Restricted Area R–5801 and Revocation of R–5803; Chambersburg, PA

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to amend restricted area R–5801 and revoke R–5803 at United States (U.S.) Army, Letterkenny Army Depot (LEAD), Chambersburg, PA. The purpose of this proposal is to extend the time of designation for R–5801 to include Saturdays from 0800–1600 local time, and to return R–5803 to the National Airspace System (NAS).

**DATES:** Comments must be received on or before September 16, 2024.

**ADDRESSES:** Send comments identified by FAA Docket No. FAA–2024–1993 and Airspace Docket No. 23–AEA–7 using any of the following methods:

\* *Federal eRulemaking Portal:* Go to [www.regulations.gov](http://www.regulations.gov) and follow the online instructions for sending your comments electronically.

\* *Mail:* Send comments to Docket Operations, M–30; U.S. Department of Transportation, 1200 New Jersey Avenue SE, Room W12–140, West Building Ground Floor, Washington, DC 20590–0001.

\* *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

\* *Fax:* Fax comments to Docket Operations at (202) 493–2251.

*Docket:* Background documents or comments received may be read at [www.regulations.gov](http://www.regulations.gov) at any time. Follow the online instructions for

accessing the docket or go to the Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**FOR FURTHER INFORMATION CONTACT:**

Brian Vidis, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

**SUPPLEMENTARY INFORMATION:**

**Authority for This Rulemaking**

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends restricted area airspace at Chambersburg, PA, to enhance aviation safety and accommodate essential U.S. Army activities.

**Comments Invited**

The FAA invites interested persons to participate in this rulemaking by submitting written comments, data, or views. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should submit only one time if comments are filed electronically, or commenters should send only one copy of written comments if comments are filed in writing.

The FAA will file in the docket all comments it receives, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, the FAA will consider all comments it receives on or before the closing date for comments. The FAA will consider comments filed after the comment period has closed if it is possible to do so without incurring

expense or delay. The FAA may change this proposal in light of the comments it receives.

*Privacy:* In accordance with 5 U.S.C. 553(c), DOT solicits comments from the public to better inform its rulemaking process. DOT posts these comments, without edit, including any personal information the commenter provides, to [www.regulations.gov](http://www.regulations.gov), as described in the system of records notice (DOT/ALL–14 FDMS), which can be reviewed at [www.dot.gov/privacy](http://www.dot.gov/privacy).

**Availability of Rulemaking Documents**

An electronic copy of this document may be downloaded through the internet at [www.regulations.gov](http://www.regulations.gov). Recently published rulemaking documents can also be accessed through the FAA’s web page at [www.faa.gov/air\\_traffic/publications/airspace\\_amendments/](http://www.faa.gov/air_traffic/publications/airspace_amendments/).

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address, phone number, and hours of operation). An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation Administration, Room 210, 1701 Columbia Avenue, College Park, GA 30337.

**Background**

The U.S. Army submitted a proposal to the FAA to amend the time of designation for existing restricted area R–5801 to include Saturdays from 0800–1600 local time, and to revoke restricted area R–5803 at U.S. Army, Letterkenny Army Depot (LEAD), Chambersburg, PA. Restricted areas R–5801 and R–5803 are currently used for the open detonation of obsolete ammunition and explosives for the U.S. Army. Restricted area R–5803 is defined as a circular area with a 5,500-foot radius centered at lat. 40°02’29” N, long. 77°44’19” W from the surface to 4,000 feet mean sea level (MSL). Restricted area R–5803 has a time of designation from 0800 to 1600 local time, Monday–Friday.

This proposal would consolidate open detonations to R–5801 and return restricted area R–5803 to the NAS which would improve scheduling, activation, and utilization efficiency of restricted area R–5801 while reducing the overall restricted airspace near the Chambersburg, PA area.

**The Proposal**

The FAA is proposing an amendment to 14 CFR part 73 to amend restricted area R–5801 and revoke restricted area