

speed flight or during surface operations. Alternatively, airflow over the windshield may be disturbed during such critical times as the approach to land, where the airplane is at a higher-than-normal pitch attitude. In these cases, areas of airflow disturbance or separation on the windshield could cause failure to maintain a clear vision area on the windshield.

In addition to potentially depending on airflow to function effectively, hydrophobic coatings may also be dependent on water-droplet size for effective precipitation removal. For example, precipitation in the form of a light mist may not be sufficient for the coating's properties to result in maintaining a clear area of vision.

The current regulations identify speed and precipitation rate requirements that represent limiting conditions for windshield wipers and blowers, but not for hydrophobic coatings. Likewise, it is necessary to issue special conditions to maintain the level of safety represented by the current regulations.

These special conditions provide an appropriate safety standard for the hydrophobic-coating technology as the means to maintain a clear area of vision by requiring coating to be effective at low speeds and low precipitation rates, as well as at the higher speeds and precipitation rates identified in the current regulation.

These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

### Applicability

As discussed above, these special conditions are applicable to the Textron Model 560XL airplane. Should Textron apply at a later date for a change to the type certificate to include another model incorporating the same novel or unusual design feature, these special conditions would apply to that model as well.

### Conclusion

This action affects only a certain novel or unusual design feature on the Textron Model 560XL airplane. It is not a rule of general applicability.

### List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

### Authority Citation

The authority citation for these special conditions is as follows:

**Authority:** 49 U.S.C. 106(f), 106(g), 40113, 44701, 44702, and 44704.

### The Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the type certification basis for Textron Model 560XL.

The airplane must have a means to maintain a clear portion of the windshield, during precipitation conditions, enough for both pilots to have a sufficiently extensive view along the ground or flight path in normal taxi and flight altitudes of the airplane. This means must be designed to function, without continuous attention on the part of the crew, in conditions from light misting precipitation to heavy rain, at speeds from fully stopped in still air, to 1.6  $V_s$  with lift and drag devices retracted.

Issued in Kansas City, Missouri, on August 8, 2024.

**Patrick R. Mullen,**

*Manager, Technical Policy Branch, Policy and Standards Division, Aircraft Certification Service.*

[FR Doc. 2024–18425 Filed 8–15–24; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA–2024–0383; Airspace Docket No. 24–ASO–2]

RIN 2120–AA66

#### Amendment of Class D Airspace; Fort Liberty, NC; Correction

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** The FAA is correcting a final rule that was published in the **Federal Register** on July 18, 2024. The final rule amended Class D airspace extending upward from the surface for Fort Liberty, NC. This action corrects errors in the Class D legal description.

**DATES:** Effective 0901 UTC, October 31, 2024. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order JO 7400.11H, Airspace Designations, and Reporting Points, and subsequent amendments can be viewed online at [https://www.faa.gov/air\\_traffic/publications/](https://www.faa.gov/air_traffic/publications/). For further information, you can contact

the Rules and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

#### FOR FURTHER INFORMATION CONTACT:

Justin T. Rhodes, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Avenue, College Park, GA 30337; telephone: (404) 305–5478.

#### SUPPLEMENTARY INFORMATION:

#### History

The FAA published a final rule in the **Federal Register** on July 18, 2024 (89 FR 58262) for Docket No. FAA–2024–0383, updating the Class D airspace for Fort Liberty, NC, by excluding 1,400 feet MSL from the vertical limits (previously “including”), updating the airport’s geographic coordinates, replacing “Notice to Airmen” with “Notice to Air Missions” in the description, and updating the reference to “Chart Supplement” (previously “Airport Facility Directory”). After publication, the FAA found updates to the FAA’s database rendering the Airport Reference Point (ARP) data incorrect, which, as dependent upon the ARP, rendered other airspace description information incorrect. This action corrects these errors.

#### Correction to the Final Rule

In FR Doc 2024–15483 at 58262, published in the **Federal Register** on July 18, 2024, the FAA makes the following corrections:

On page 58263, in the second column, correct the ASO NC D description for Fort Liberty, NC, to read as follows:

\* \* \* \* \*

#### ASO NC D Simmons AAF, NC [Corrected]

Simmons AAF, NC  
(Lat. 35°07’56” N, long. 78°56’07” W)

That airspace extending upward from the surface to but not including 1,400 feet MSL within a 3.9-mile radius of Simmons AAF, excluding the portion northwest of a line extending from lat. 35°11’48” N, long. 78°55’35” W; to lat. 35°06’19” N, long. 79°00’27” W, excluding the portion within the Fayetteville, NC, Class C airspace area. This Class D airspace area is effective during the specific dates and times established in advance by a Notice to Air Missions. The effective date and time will thereafter be continuously published in the Chart Supplement.

\* \* \* \* \*

Issued in College Park, Georgia, on August 12, 2024

**Andrese C. Davis,**

*Manager, Airspace & Procedures Team South, Eastern Service Center, Air Traffic Organization.*

[FR Doc. 2024–18298 Filed 8–15–24; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 129

#### International Aviation Safety Assessment (IASA) Program

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Suspension of policy statement.

**SUMMARY:** On September 28, 2022, the FAA published a Policy Statement in the **Federal Register** that described policy changes to the FAA's International Aviation Safety Assessment (IASA) program as well as clarification or restatement of prior policy to “enhance engagement with civil aviation authorities (CAAs) through pre- and post-IASA assessment and to promote greater transparency.” After receiving inquiries and questions about the changes described in that policy statement, the FAA is suspending implementation of the September 28, 2022, Policy Statement while the agency reassesses the policy. The policy statement published March 8, 2013, remains active.

**DATES:** The policy statement published at 87 FR 58725 (September 28, 2022) is suspended as of August 16, 2024.

**FOR FURTHER INFORMATION CONTACT:** Rolandos Lazaris, Division Manager, International Program Division (AFS–50), Flight Standards Service, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; (202) 267–3719.

#### SUPPLEMENTARY INFORMATION:

##### Background

The IASA program is the means by which the FAA determines whether another country's oversight of its air carriers that (1) operate, or seek to operate, services to/from the United States using their own aircraft and crews, or (2) seek to display the code of a U.S. air carrier on any services, complies with safety standards established by the International Civil Aviation Organization (ICAO). The published IASA results of a country's placement in Category 1 or Category 2

is the notification to the U.S. traveling public as to whether a foreign air carrier's homeland civil aviation authority meets ICAO safety standards. A Category 1 rating indicates that the civil aviation authority meets ICAO safety standards for these operations, and a Category 2 rating indicates that the civil aviation authority does not meet ICAO safety standards. The IASA program was established by a document published in the **Federal Register** in 1992. Subsequent published documents in the **Federal Register** notified of the program's evolution. These **Federal Register** documents are as follows:

- August 24, 1992—Established the FAA Procedures for Examining and Monitoring Foreign Air Carriers (57 FR 38342).

- September 8, 1994—Established the Public Disclosure of the Results of Foreign Civil Aviation Authority Assessments, through a three-category numbered rating system (59 FR 46332).

- October 31, 1995—DOT Notice Clarification Concerning Examination of Foreign Carriers' Request for Expanded Economic Authority, clarified the Department's licensing policy regarding requests for expanded economic authority from foreign air carriers whose CAA's safety oversight capability has been assessed by the FAA as conditional (Category II) or unacceptable (Category III) (60 FR 55408).

- May 25, 2000—Changes to the International Aviation Safety Assessment program removed the Category 3 rating and combined it with Category 2 (65 FR 33751).

- March 8, 2013—Changes to the International Aviation Safety Assessment program removed inactive countries (countries with no air carrier operations to the United States or code-shares with U.S. air carrier for four years and no significant interaction between the country's CAA and the FAA) from the IASA Category list (78 FR 14912).

Through the IASA program, the FAA seeks continuous improvement to global aviation safety. As noted in the above-referenced policy statement of September 8, 1994, initial IASA assessments found that two-thirds of the assessed CAAs were deficient in meeting their safety oversight obligations under the Convention on International Civil Aviation.

The September 28, 2022, Policy Statement (87 FR 58725) (now suspended) announced certain changes to the IASA program and provided clarification to other aspects of the IASA policy. Since that publication, the FAA and DOT have received inquiries and questions that warrant reassessment of those changes and clarifications, and an

opportunity for public comment before they are adopted permanently. As noted above, the FAA is suspending implementation of the September 28, 2022, Policy Statement while the agency reassesses the policy and considers public comments. Public comment is invited on the matters and issues described in the companion document published elsewhere in this issue of the **Federal Register**.

Issued in Washington, DC.

**Jodi L. Baker,**

*Deputy Administrator for Aviation Safety.*

[FR Doc. 2024–16954 Filed 8–15–24; 8:45 am]

**BILLING CODE 4910–13–P**

## FEDERAL TRADE COMMISSION

### 16 CFR Part 1

**RIN 3084–AB79**

#### Horseracing Integrity and Safety Authority Oversight

**AGENCY:** Federal Trade Commission.

**ACTION:** Final rule.

**SUMMARY:** The Federal Trade Commission (“FTC” or “Commission”) is issuing a final rule (“Final Rule”) regarding oversight of the Horseracing Integrity and Safety Authority (“Authority”). The Final Rule includes new oversight provisions to ensure that the Authority remains publicly accountable and operates in a fiscally prudent, safe, and effective manner.

**DATES:** This rule is effective on September 16, 2024.

**FOR FURTHER INFORMATION CONTACT:** Sarah Botha, (202) 326–2036, [sbotha@ftc.gov](mailto:sbotha@ftc.gov), Office of the Executive Director, Federal Trade Commission.

**SUPPLEMENTARY INFORMATION:** This document states the basis and purpose for the Commission's decision to adopt the Final Rule addressing the Commission's oversight of the Authority. The new oversight provisions were proposed and published for public comment in the **Federal Register** on February 8, 2024, in a notice of proposed rulemaking (“NPRM”).<sup>1</sup> After careful review and consideration of the entire record on the issues presented in this rulemaking proceeding, including 10 comments submitted by interested parties, the Commission has decided to adopt, with a few modifications, the proposed new oversight rule.

<sup>1</sup> FTC, Horseracing Integrity and Safety Authority Oversight, Proposed Rule, 89 FR 8578 (Feb. 8, 2024).