

Rules and Regulations

Federal Register

Vol. 90, No. 28

Wednesday, February 12, 2025

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

DEPARTMENT OF AGRICULTURE

Rural Housing Service

7 CFR Part 3555

[Docket No. RHS-24-SFH-0001]

RIN 0575-AD28

Single Family Housing Guaranteed Loan Program Changes Related to Special Servicing Options; Correction

AGENCY: Rural Housing Service, U.S. Department of Agriculture (USDA).

ACTION: Final rule; correction.

SUMMARY: The Rural Housing Service (RHS or Agency), a Rural Development (RD) agency of USDA, published a final rule on August 15, 2024, to amend the current regulations regarding Special Servicing Options and adjust the Mortgage Recovery Advance (MRA) process. The February 11, 2025, effective date of that final rule is being deferred to April 14, 2025.

DATES: Effective February 11, 2025.

FOR FURTHER INFORMATION CONTACT: Ticia Weare, Finance and Loan Analyst, Single Family Housing Guaranteed Loan Division, Rural Development, U.S. Department of Agriculture, STOP 0784, South Agriculture Building, 1400 Independence Avenue SW, Washington, DC 20250-0784. Telephone: (314) 679-6919; or email: ticia.weare@usda.gov.

SUPPLEMENTARY INFORMATION:

Correction

In FR Doc. 2024-18291 (Docket No. RHS-24-SFH-0001) appearing at 89 FR 66189 in the **Federal Register** of August 15, 2024, in the first column on page 66189, correct the **DATES** caption to read:

DATES: Effective April 14, 2025.

Christine Mechtly,

Acting Administrator, Rural Housing Service.

[FR Doc. 2025-02551 Filed 2-10-25; 8:45 am]

BILLING CODE 3410-XV-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2024-2016; Project Identifier MCAI-2024-00111-T; Amendment 39-22948; AD 2025-02-15]

RIN 2120-AA64

Airworthiness Directives; Saab AB Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2017-21-05, which applied to certain Saab AB Model 340A (SAAB/SF340A) and SAAB 340B airplanes. AD 2017-21-05 required revising the existing maintenance or inspection program, as applicable, to incorporate airworthiness limitations, including new inspection tasks for the drag brace support fitting of the main landing gear (MLG) and tasks related to the corrosion prevention and control program (CPCP). This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This AD continues to require the actions in AD 2017-21-05 and requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference (IBR). The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 19, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 19, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of November 27, 2017 (82 FR 48917, October 23, 2017).

ADDRESSES:

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-2016; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket

contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADS@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- For Saab AB material identified in this AD, contact Saab AB, SE-581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email saab340techsupport@saabgroup.com; website saab.com/products/air/regional-aircraft.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-2016.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206-231-3220; email Shahram.Daneshmandi@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2017-21-05, Amendment 39-19076 (82 FR 48917, October 23, 2017) (AD 2017-21-05). AD 2017-21-05 applied to certain Saab AB Model 340A (SAAB/SF340A) and SAAB 340B airplanes. AD 2017-21-05 required revising the maintenance or inspection program, as applicable, to incorporate airworthiness limitations, including new inspection tasks for the drag brace support fitting of the MLG and to implement CPCP-related tasks. The FAA issued AD 2017-21-05 to prevent reduced structural integrity of the airplane.

The NPRM published in the **Federal Register** on August 12, 2024 (89 FR 65568). The NPRM was prompted by