by this AD, unless the AD specifies otherwise.

- (1) The Director of the Federal Register approves the incorporation by reference of Airbus Service Bulletin A320-53-1032, Revision 02, dated December 5, 2001, in accordance with 5 U.S.C. 552(a) and 1 CFR
- (2) On February 12, 1999 (64 FR 1114. January 8, 1999), the Director of the Federal Register approved the incorporation by reference of Airbus Service Bulletin A320-53-1032, Revision 01, dated January 15,
- (3) For copies of the service information, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. For information on the availability of this material at the National Archives and Records Administration (NARA), call (202) 741-6030, or go to http://www.archives.gov/ federal\_register/code\_of\_federal\_regulations/ ibr\_locations.html. You may view the AD docket at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Nassif Building, Washington, DC.

Issued in Renton, Washington, on December 29, 2004.

#### Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 05-282 Filed 1-5-05; 8:45 am]

BILLING CODE 4910-13-P

#### DEPARTMENT OF TRANSPORTATION

#### **Federal Aviation Administration**

# 14 CFR Part 97

[Docket No. 30434; Amdt. No. 3113]

## Standard Instrument Approach Procedures; Miscellaneous **Amendments**

**AGENCY: Federal Aviation** Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment establishes. amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective January 6, 2005. The compliance date for each

SIAP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of January 6,

**ADDRESSES:** Availability of matters incorporated by reference in the amendment is as follows:

For Examination—

- 1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;
- 2. The FAA Regional Office of the region in which the affected airport is located:
- 3. The Flight Inspection Area Office which originated the SIAP; or,
- 4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/ federal\_register/ code\_of\_federal\_regulations/ ibr\_locations.html.

For Purchase—Individual SIAP copies may be obtained from:

- 1. FAA Public Inquiry Center (APA– 200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or
- 2. The FAA Regional Office of the region in which the affected airport is located.

By Subscription—Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

#### FOR FURTHER INFORMATION CONTACT:

Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monronev Aeronautical Center, 6500 South MacArthur Blvd. Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK 73125) telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description of each SIAP is contained in official FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation Regulations (FAR). The applicable FAA Forms are identified as FAA Forms 8260-3, 8260-4, and 8260-5. Materials incorporated

by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the Federal Register expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

#### The Rule

This amendment to part 97 is effective upon publication of each separate SIAP as contained in the transmittal. Some SIAP amendments may have been previously issued by the FAA in a National Flight Data Center (NFDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for some SIAP amendments may require making them effective in less than 30 days. For the remaining SIAPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for **Terminal Instrument Procedures** (TERPS). In developing these SIAPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and, where applicable, that good cause exists for making some SIAPs effective in less than 30 days.

# Conclusion

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT

Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 97

Air Traffic Control, Airports, Incorporation by reference, and Navigation (Air).

Issued in Washington, DC on December 3, 2004.

#### James J. Ballough,

Director, Flight Standards Service.

## Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me, part 97 of the Federal Aviation Regulations (14 CFR part 97) is amended by establishing, amending, suspending, or revoking Standard Instrument Approach Procedures, effective at 0901 UTC on the dates specified, as follows:

# PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

■ 1. The authority citation for part 97 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44701, 44719, 44721–44722.

- 2. Part 97 is amended to read as follows:
- \* \* \* Effective 17 February 2005

Orange, MA, Orange Muni, NDB Rwy 1, Orig-

\* \* \* Effective 17 March 2005

Beaver, AK, Beaver, RNAV (GPS) Rwy 5, Orig Beaver, AK, Beaver, RNAV (GPS) Rwy 23, Orig

Marksville, LA, Marksville Municipal, RNAV (GPS) Rwy 4, Orig

Marksville, LA, Marksville Municipal, NDB Rwv 4, Amdt 2

Marksville, LA, Marksville Municipal, VOR/ DME–A, Amdt 4

Marksville, LA, Marksville Municipal, GPS Rwy 4, Orig, Cancelled

Cheboygan, MI, Cheboygan County, VOR Rwy 9, Amdt 8A

Cheboygan, MI, Cheboygan County, RNAV (GPS) Rwy 9, Amdt 1

Eveleth, MN, Eveleth-Virginia Muni, VOR Rwy 27, Orig

Eveleth, MN, Eveleth-Virginia Muni, VOR Rwy 27, Amdt 11A, Cancelled

Bennettsville, SC, Marlboro County Jetport-H.E. Avent Field, RNAV (GPS) Rwy 6, Orig Bennettsville, SC, Marlboro County Jetport-H.E. Avent Field, RNAV (GPS) Rwy 24, Orig

Bennettsville, SC, Marlboro County Jetport-H.E. Avent Field, NDB Rwy 6, Amdt 4 Bennettsville, SC, Marlboro County Jetport-H.E. Avent Field, VOR/DME–A, Amdt 4 Bennettsville, SC, Marlboro County Jetport-H.E. Avent Field, GPS Rwy 24, Orig, Cancelled

Amery, WI, Amery Muni, NDB Rwy 18, Amdt 6

Amery, WI, Amery Muni, RNAV (GPS) Rwy 18, Orig

Amery, WI, Amery Muni, RNAV (GPS) Rwy 36, Orig

[FR Doc. 05–234 Filed 1–5–05; 8:45 am] BILLING CODE 4910–13–P

# DEPARTMENT OF HOMELAND SECURITY

#### **Coast Guard**

33 CFR Part 117

[CGD 11-04-053]

## Drawbridge Operation Regulations; Sacramento River, Sacramento, CA

**AGENCY:** Coast Guard, DHS.

**ACTION:** Notice of temporary deviation from regulations.

SUMMARY: The Commander, Eleventh Coast Guard District, has issued a temporary deviation from the regulation governing the operation of the I Street Drawbridge across the Sacramento River, mile 59.4, at Sacramento, CA. This deviation allows the drawbridge to remain in the closed-to-navigation position during essential operating machinery repair, to prevent unexpected failure of the drawspan.

**DATES:** This deviation is effective from 8 a.m. on January 8, 2005 to 5 p.m. on January 13, 2005.

ADDRESSES: Materials referred to in this document are available for inspection or copying at Commander (oan), Eleventh Coast Guard District, Building 50–3, Coast Guard Island, Alameda, CA 94501–5100, between 8 a.m. and 4 p.m., Monday through Friday, except Federal holidays.

# FOR FURTHER INFORMATION CONTACT:

David H. Sulouff, Chief, Bridge Section, Eleventh Coast Guard District, telephone (510) 437–3516.

SUPPLEMENTARY INFORMATION: The Union Pacific Railroad has requested to secure the I Street Drawbridge, mile 59.4, Sacramento River, at Sacramento, CA, in the closed-to-navigation position from 8 a.m. on January 8, 2005 to 5 p.m. January 13, 2005, during essential operating machinery repair, to prevent unexpected failure of the drawspan. The drawbridge provides 109 ft. vertical clearance in the full open-to-navigation position, and 30 ft. vertical clearance above Mean High Water when closed.

The drawbridge opens on signal from approaching vessels, as required by 33 CFR 117.189.

The proposed work was coordinated with waterway users. It was determined that potential navigational impacts will be reduced if the repairs are performed during January 2005, resulting in Coast Guard approval of the proposed work from 8 a.m. January 8, 2005 to 5 p.m. January 13, 2005.

During these times, the drawspan may be secured in the closed-to-navigation position and need not open for vessels.

The drawspan shall resume normal operation at the conclusion of the essential repair work. Mariners should contact the I Street Drawbridge by telephone at (916) 444–8999, in advance, to determine conditions at the bridge.

The drawspan will be unable to open during the repair. In the event of an emergency, the bridge owner would require 24-hour advance notice to open the bridge. Contact Mr. Steve Strickland at (916) 789–5249 or (916) 952–1894. Vessels that can safely pass through the closed drawbridge may continue to do so at any time. In accordance with 33 CFR 117.35(c), this work will be performed with all due speed to return the drawbridge to normal operation as soon as possible. This deviation from the operating regulations is approved under the provisions of 33 CFR 117.35.

Dated: December 23, 2004.

### Kevin J. Eldridge,

Rear Admiral, U.S. Coast Guard, Commander, Eleventh Coast Guard District.

[FR Doc. 05–232 Filed 1–5–05; 8:45 am] BILLING CODE 4910–15–P

# DEPARTMENT OF HOMELAND SECURITY

# **Coast Guard**

33 CFR Part 165

[COTP Charleston 04-145]

RIN 1625-AA87

# Security Zones; Charleston Harbor, Cooper River, SC

AGENCY: Coast Guard, DHS.

**ACTION:** Temporary final rule; request for comments.

**SUMMARY:** The Coast Guard is establishing a temporary fixed security zone in the waters from the Don Holt, I–526 Bridge, on the Cooper River to the entrance of Foster Creek on the Cooper River. This security zone is necessary to protect the public and port from potential subversive acts during port