

Notice issued by the Department of Transportation on August 26, 2005

Renee V. Wright,

Program Manager, Docket Operations, Federal Register Liaison.

[FR Doc. 05-19700 Filed 9-30-05; 8:45 am]

BILLING CODE 4910-62-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

Advisory Circular 33.4-3, Instructions for Continued Airworthiness; Aircraft Engine High Intensity Radiated Fields (HIRF) and Lightning Protection Features

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of issuance of advisory circular.

SUMMARY: This notice announces the issuance of Advisory Circular (AC) 33.4-3, Instructions for Continued Airworthiness; Aircraft Engine High Intensity Radiated Fields (HIRF) and Lightning Protection Features. This AC sets forth acceptable methods of compliance for aircraft engines with the provisions of § 33.4, Instructions for Continued Airworthiness of Title 14 of the Code of Federal Regulations (14 CFR). This AC provides guidance for developing instructions for continued airworthiness to ensure the continued airworthiness of aircraft engine HIRF and Lightning protection features.

DATES: The Engine and Propeller Directorate issued Advisory Circular 33.4-3 on September 16, 2005.

FOR FURTHER INFORMATION CONTACT: The Federal Aviation Administration, Attn: Gary Horan, Engine and Propeller Standards Staff, ANE-111, 12 New England Executive Park, Burlington, MA 01803-5299; telephone: (781) 238-7164; fax: (781) 238-7199; e-mail: gary.horan@faa.gov.

We have filed in the docket all substantive comments received, and a report summarizing them. If you wish to review the docket in person, you may go to the above address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. If you wish to contact the above individual directly, you can use the above telephone number or e-mail address provided.

How to Obtain Copies: A paper copy of AC 33.4-3 may be obtained by writing to the U.S. Department of Transportation, Subsequent Distribution Office, DOT Warehouse, SVC-121.23, Ardmore East Business Center, 3341 Q 75th Ave., Landover, MD 20785, telephone 301-322-5377, or by faxing

your request to the warehouse at 301-386-5394. The AC will also be available on the Internet at <http://www.faa.gov/>, select "Regulations and Policies" then the link titled "Advisory Circulars."

(Authority: 49 U.S.C. 106(g), 40113, 44701-44702, 44704)

Issued in Burlington, Massachusetts, on September 16, 2005.

Fran A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 05-19598 Filed 9-30-05; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

Agency Information Collection Activity Under OMB Review, Request for Comments; Clearance of a New Information Collection Activity, Air Carriers Listing of Leading Outsource Maintenance Providers

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice and request for comments.

SUMMARY: The FAA invites public comments about our intention to request the Office of Management and Budget's (OMB) approval for a new information collection. The FAA will use the data from the proposed collection to target those leading outsource maintenance providers that may have a higher risk level which in turn would merit an increase of FAA surveillance.

DATES: Please submit comments by October 17, 2005.

FOR FURTHER INFORMATION CONTACT: Judith D. Street, 202-267-9895, Judy.Street@faa.gov, ABA-20, Federal Aviation Administration, 800 Independence Ave., SW., Washington, DC 20591.

SUPPLEMENTARY INFORMATION:

Federal Aviation Administration (FAA)

Title: Air Carriers Listing of Leading Outsource Maintenance Providers.

Type of Request: Approval for an emergency clearance of a new collection.

OMB Control Number: 2120-xxxx.

Form(s): Quarterly Outsource Maintenance Providers Utilization Report.

Affected Public: A Total of 121 Aircraft Operators.

Frequency: This information will be collected quarterly.

Estimated Average Burden Per Response: 6 minutes.

Estimated Annual Burden Hours: An estimated 48 hours annually.

Abstract: The data from this report will be used to target those leading outsource maintenance providers that may have a higher risk level which in turn would merit an increase of FAA surveillance.

ADDRESSES: Send comments to the Office of Information and Regulatory Affairs, Office of Management and Budget, 725 17th Street, NW., Washington, DC 20503, Attention: FAA Desk Officer.

Comments are invited on: Whether the proposed collection of information is necessary for proper performance of the functions of the Department, including whether the information will have practical utility; the accuracy of the Department's estimates of the burden of the proposed information collection; ways to enhance the quality, utility and clarity of the information to be collected; and ways to minimize the burden of the collection of information on respondents, including the use of automated collection techniques or other forms of information technology.

Issued in Washington, DC, on September 27, 2005.

Judith D. Street,

FAA Information Collection Clearance Officer, Information Systems and Technology Services Staff, ABA-20.

[FR Doc. 05-19743 Filed 9-30-05; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Motor Carrier Safety Administration

[Docket No. FMCSA-2005-20105]

Announcement of Establishment of the Federal Motor Carrier Safety Administration Medical Review Board; Request for Nominations

AGENCY: Federal Motor Carrier Safety Administration (FMCSA), DOT.

ACTION: Notice of establishment of the FMCSA Medical Review Board; request for nominations.

SUMMARY: FMCSA announces the establishment of a Medical Review Board as requested by the recent passage of Safe, Accountable, Flexible, and Efficient Transportation Equity Act; A Legacy for Users (SAFETEA-LU). The Medical Review Board will provide scientific advice to The Secretary of Transportation and the Administrator of FMCSA on medical issues including the physical qualification requirements for commercial motor vehicle (CMV) operators. This announcement provides