

a loose bolt of the "V" shape airbrake bellcrank, named hereafter intermediate control lever. The Left Hand (LH) wing lever also presented, to a lesser extent, a loose bolt.

This AD requires inspection of the LH and RH wing airbrake intermediate control levers for loose attaching bolts and subsequent repetitive inspections and corrective actions, as necessary. As a terminating action, replacement of the bolts and their associated washers is required.

These actions are intended to address the identified unsafe condition so as to prevent loss of the airbrake control system which could result in an inadvertent forced landing with consequent sailplane damage and/or passenger injury.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 10 days after February 1, 2008 (the effective date of this AD), inspect the left-hand (LH) and the right-hand (RH) wing airbrake intermediate control levers for loose attaching bolts following Allstar PZL Glider Sp. z o. o. Service Bulletin No. BE-059/SZD-50-3/2007 "PUCHACZ," dated October 15, 2007.

(2) Before further flight after the inspection required in paragraph (f)(1) of this AD if any loose bolt is found, on both wings replace the split helical spring lock washers with tab washers and replace the M8x34 bolts with M8x32 bolts following Allstar PZL Glider Sp. z o. o. Service Bulletin No. BE-059/SZD-50-3/2007 "PUCHACZ," dated October 15, 2007.

(3) No further action is required at this time if no loose bolts were found during the inspection required in paragraph (f)(1) of this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows:

(1) The MCAI and the service information require repetitive inspections if no loose bolts are found during the initial required inspection until the next 1,000-hour time-in-service (TIS) overhaul after the effective date of the AD, at which time replacing the split helical spring lock washers with tab washers and replacing the M8x34 bolts with M8x32 bolts is required.

(2) This AD is considered an interim action because we are not including a repetitive inspection requirement in this AD. The Administrative Procedure Act does not permit the FAA to "bootstrap" a long-term requirement into an urgent safety of flight action where the rule becomes effective at the same time the public has the opportunity to comment. The short-term action and the long-term action are analyzed separately for justification to bypass prior public notice.

(3) After issuing this AD, we may initiate further AD action (notice of proposed rulemaking followed by a final rule) to require the inspection to be repetitive and to require a terminating action. Credit will be given in any subsequent action for the initial inspection done under this AD.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Greg Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-409. Before using any approved AMOC on any glider to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Emergency AD No. 2007-0275-E, dated October 24, 2007; and Allstar PZL Glider Sp. z o. o. Service Bulletin No. BE-059/SZD-50-3/2007 "PUCHACZ," dated October 15, 2007, for related information.

Material Incorporated by Reference

(i) You must use Allstar PZL Glider Sp. z o. o. Service Bulletin No. BE-059/SZD-50-3/2007 "PUCHACZ," dated October 15, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact ALLSTAR PZL GLIDER Sp. z o. o., ul. Cieszyńska 325, 453-300 Bielsko-Biala.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri on January 14, 2008.

John Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-870 Filed 1-18-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2008-027; Airspace Docket No. 08-ASW-3]

Proposed Establishment of Class E5 Airspace; Eagle Pass, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule request for comments.

SUMMARY: This action proposes to establish Class E5 airspace at Eagle Pass, TX. Additional controlled airspace is necessary to accommodate aircraft using new RNAV Global Positioning System (GPS) Standard Instrument Approach Procedures (SIAP). The FAA is proposing this action to enhance the safety and management of Instrument Flight Rules (IFR) aircraft operations at Eagle Pass, TX, Maverick County Memorial International Airport.

DATES: *Effective Dates:* 0901 UTC April 10, 2008. Comments for inclusion in the rules Docket must be received on or before February 25, 2008. The Director of the Federal Register approves this incorporation by reference action under Title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2008-0027/Airspace Docket No. 08-ASW-3, at the beginning of your comments. You may also submit comments through the Internet at <http://regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is on the ground floor of the building at the above address.

FOR FURTHER INFORMATION CONTACT: Joe Yadouga, Central Service Center, System Support Group, Federal Aviation Administration, Southwest Region, Ft. Worth, Texas 76193-0530; telephone (817) 222-5597.

SUPPLEMENTARY INFORMATION:

The Direct Final Rule Procedure

The FAA anticipates that this regulation will not result in adverse or

negative comments, and, therefore, issues it as a direct final rule. Unless a written adverse or negative comment or a written notice of intent to submit an adverse or negative comment is received within the comment period, the regulation will become effective on the date specified above. After the close of the comment period, the FAA will publish a document in the **Federal Register** indicating that no adverse or negative comments were received and confirming the effective date of the rule. If the FAA receives, within the comment period, an adverse or negative comment, or written comment notice of intent to submit such a comment, a document withdrawing the direct final rule will be published in the **Federal Register**, and a notice of proposed rulemaking may be published with a new comment period.

Comments Invited

Although this action is in the form of a direct final rule, and was not preceded by a notice of proposed rulemaking, interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. An electronic copy of this document may be downloaded from <http://www.regulations.gov>. Communications should identify both docket numbers and be submitted in triplicate to the address specified under the caption **ADDRESSES** above or through the Web site. All communications received on or before the closing date for comments will be considered, and this rule may be amended or withdrawn in light of the comments received.

The Rule

This amendment to Title 14, Federal Regulations (14 CFR) part 71 establishes Class E5 airspace at Eagle Pass, TX providing the airspace required to support the new RNAV (GPS) RWY 13/31 approach developed for IFR landings at Maverick County Memorial International Airport. Controlled airspace extending upward from 700 feet above the surface is required to encompass all SIAPs and for the safety of IFR operations at Maverick County Memorial International Airport. Designations for Class E5 airspace areas extending upward from 700 feet above the surface of the earth are published in the FAA Order 7400.9R, signed August 15, 2007 and effective September 15, 2007, which is incorporated by reference in 14 CFR 71.1. Class E5 designations listed in this document will be published subsequently in the Order.

Agency Findings

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among various levels of government. Therefore, it is determined that this final rule does not have federalism implication under Executive Order 13132.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49, of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

This rulemaking is promulgated under the authority described in subtitle VII, Part A, subpart I, section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes Class E5 airspace near Eagle Pass, TX.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

Adoption of the Amendment

■ In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9R, Airspace Designation and Reporting Points, signed August 15, 2007, and effective September 15, 2007, is amended as follows:

Paragraph 6002 Class E5 airspace areas extending upward from 700 feet above the surface of the earth

* * * * *

ASW TX Class E5 Eagle Pass, TX [New]

Maverick County Memorial International Airport
(lat. 28° 51.43'N., long. 100°30.81'W.)

That airspace extending upward from 700 feet above the surface within a 6.5-mile radius of Maverick County Memorial International Airport to exclude the international boundaries of Mexican airspace. This Class E5 airspace is effective during specific dates and times established in advance by Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

* * * * *

Issued in Fort Worth, TX, on January 9, 2008.

Donald R. Smith,

Manager, System Support Group, ATO Central Service Center.

[FR Doc. 08–164 Filed 1–18–08; 8:45 am]

BILLING CODE 4910–13–M

DEPARTMENT OF ENERGY

Federal Energy Regulatory Commission

18 CFR Part 11

[RM08–6–000]

Update of the Federal Energy Regulatory Commission's Fees Schedule for Annual Charges for the Use of Government Lands

January 15, 2008.

AGENCY: Federal Energy Regulatory Commission, DOE.

ACTION: Final rule; update of Federal land use fees.

SUMMARY: In accordance with the Commission's regulations, the