# **NUCLEAR REGULATORY** COMMISSION

# **Advisory Committee on Reactor** Safeguards (ACRS)

# Meeting of the Subcommittee on **Digital Instrumentation and Control** Systems; Notice of Meeting

The ACRS Subcommittee on Digital Instrumentation and Control Systems will hold a meeting on April 17, 2008, Room T-2B3, Two White Flint North, 11545 Rockville Pike, Rockville, Maryland.

The entire meeting will be open to public attendance.

The agenda for the subject meeting shall be as follows:

Thursday, April 17, 2008—8:30 a.m. until the conclusion of business

The Subcommittee will hold discussions with representatives of the NRC staff and the industry regarding digital instrumentation and control systems issues. The Subcommittee will hear presentations by and hold discussions with representatives of the NRC staff, the industry, and other interested persons regarding this matter. The Subcommittee will gather information, analyze relevant issues and facts, and formulate proposed positions and actions, as appropriate, for deliberation by the full Committee.

Members of the public desiring to provide oral statements and/or written comments should notify the Designated Federal Official, Mr. Girija Shukla (telephone 301/415-6855) five days prior to the meeting, if possible, so that appropriate arrangements can be made. Electronic recordings will be permitted.

Further information regarding this meeting can be obtained by contacting the Designated Federal Official between 7:15 a.m. and 5 p.m. (ET). Persons planning to attend this meeting are urged to contact the above named individual at least two working days prior to the meeting to be advised of any potential changes to the agenda.

Dated: April 3, 2008.

### Harold VanderMolen,

Acting Branch Chief, ACRS. [FR Doc. E8-7715 Filed 4-10-08; 8:45 am] BILLING CODE 7590-01-P

## **NUCLEAR REGULATORY** COMMISSION

[Docket No. 72-68; EA-08-069]

In the Matter of Exelon Generation **Company Byron Generating Station Independent Spent Fuel Installation Order Modifying License (Effective** Immediately)

AGENCY: U.S. Nuclear Regulatory Commission.

**ACTION:** Issuance of Order for Implementation of Additional Security Measures and Fingerprinting for Unescorted Access to Exelon Generation Company, LLC.

## FOR FURTHER INFORMATION CONTACT:

L. Raynard Wharton, Senior Project Manager, Licensing and Inspection Directorate, Division of Spent Fuel Storage and Transportation, Office of Nuclear Material Safety and Safeguards (NMSS), U.S. Nuclear Regulatory Commission (NRC), Rockville, MD 20852. Telephone: (301) 492-3316; fax number: (301) 492-3350; e-mail: LRaynard.Wharton@nrc.gov.

#### SUPPLEMENTARY INFORMATION:

#### I. Introduction

Pursuant to 10 CFR 2.106, NRC (or the Commission) is providing notice, in the matter of Byron Generating Station Independent Spent Fuel Storage Installation (ISFSI) Order Modifying License (Effective Immediately).

#### II. Further Information

NRC has issued a general license to Exelon Generating Company, LLC (Exelon), authorizing the operation of an ISFSI, in accordance with the Atomic Energy Act of 1954, as amended, and Title 10 of the Code of Federal Regulations (10 CFR) Part 72. This Order is being issued to Exelon, which has identified near-term plans to store spent fuel in an ISFSI under the general license provisions of 10 CFR Part 72. The Commission(s regulations at 10 CFR 72.212(b)(5) and 10 CFR 73.55(h)(1) require Exelon to maintain safeguards contingency plan procedures to respond to threats of radiological sabotage and to protect the spent fuel against the threat of radiological sabotage, in accordance with 10 CFR Part 73, Appendix C. Specific safeguards requirements are contained in 10 CFR 73.51 or 73.55, as applicable.

Inasmuch as an insider has an opportunity equal to, or greater than, any other person, to commit radiological sabotage, the Commission has determined these measures to be

prudent. Comparable Orders have been issued to all licensees that currently store spent fuel or have identified nearterm plans to store spent fuel in an ISFSI.

On September 11, 2001, terrorists simultaneously attacked targets in New York, NY, and Washington, DC, using large commercial aircraft as weapons. In response to the attacks and intelligence information subsequently obtained, the Commission issued a number of Safeguards and Threat Advisories to its licensees, to strengthen licensees' capabilities and readiness to respond to a potential attack on a nuclear facility. On October 16, 2002, the Commission issued Orders to the licensees of operating ISFSIs, to place the actions taken in response to the Advisories into the established regulatory framework and to implement additional security enhancements that emerged from NRC's ongoing comprehensive review. The Commission has also communicated with other Federal, State, and local government agencies and industry representatives to discuss and evaluate the current threat environment in order to assess the adequacy of security measures at licensed facilities. In addition, the Commission has conducted a comprehensive review of its safeguards and security programs and requirements.

As a result of its consideration of current safeguards and security requirements, as well as a review of information provided by the intelligence community, the Commission has determined that certain additional security measures (ASMs) are required to address the current threat environment, in a consistent manner throughout the nuclear ISFSI community. Therefore, the Commission is imposing requirements, as set forth in Attachments 1 and 2 of this Order, on all licensees of these facilities. These requirements, which supplement existing regulatory requirements, will provide the Commission with reasonable assurance that the public health and safety and common defense and security continue to be adequately protected in the current threat environment. These requirements will remain in effect until the Commission determines otherwise.

The Commission recognizes that Exelon may have already initiated many of the measures set forth in Attachments 1 and 2 to this Order, in response to previously issued advisories, or on their own. It also recognizes that some measures may not be possible nor necessary at some sites, or may need to