

approved in accordance with the procedures specified in paragraph (n) of this AD.

Reporting Requirement

(l) At the applicable time specified in paragraph (l)(1) or (l)(2) of this AD, submit a report of the findings (both positive and negative) of each Stage 1 inspection required by paragraph (g) of this AD to Boeing Commercial Airplanes; Attention: Manager, Airline Support; P.O. Box 3707 MC 04-ER; Seattle, Washington 98124-2207; fax (425) 266-5562. The report must include the inspection results, a description of any discrepancies found, the inspections performed, the airplane serial number, and the number of total accumulated flight cycles on the airplane. Under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

(1) For any inspection done after November 28, 2007: Submit the report within 30 days after the inspection.

(2) For any inspection done before November 28, 2007: Submit the report within 30 days after November 28, 2007.

New Requirements of This AD

Modification

(m) Except as provided by paragraphs (m)(1) and (m)(2) of this AD: At the times specified in paragraph 1.E, "Compliance," of Boeing Alert Service Bulletin 747-53A2559, dated January 8, 2009, modify the frame-to-tension-tie joints at body stations 1120 through 1220; do all related investigative and applicable corrective actions; do the repetitive post-modification detailed inspections for cracking of the tension tie and frame structure and all applicable corrective actions; and do the additional modification. Do all actions in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2559, dated January 8, 2009. Modifying the frame-to-tension-tie joints at body stations 1120 through 1220 terminates the repetitive inspection requirements of paragraphs (g) and (j) of this AD.

(1) Where paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2559, dated January 8, 2009, specifies a compliance time relative to the original issue date of the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Where Boeing Alert Service Bulletin 747-53A2559, dated January 8, 2009, specifies to contact Boeing for repair instructions or additional modification requirements: Before further flight, repair the discrepancy or do the modification using a method approved in accordance with the procedures specified in paragraph (n) of this AD.

Alternative Methods of Compliance (AMOCs)

(n)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14

CFR 39.19. Send information to ATTN: Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6437; fax (425) 917-6590. Or, e-mail information to 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and 14 CFR 25.571, Amendment 45, and the approval must specifically refer to this AD.

(4) AMOCs approved previously in accordance with AD 2007-23-18 are approved as AMOCs for the corresponding requirements of paragraphs (g) and (j) of this AD.

Issued in Renton, Washington, on June 24, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-16463 Filed 7-10-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2009-0552; Airspace Docket No. 09-ANM-7]

Proposed Establishment of Class E Airspace; Ronan, MT

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to establish Class E airspace at Ronan, MT. Additional controlled airspace is necessary to accommodate aircraft using a new Area Navigation (RNAV) Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) at Ronan Airport, Ronan, MT. The FAA is proposing this action to enhance the safety and management of aircraft operations at Ronan Airport.

DATES: Comments must be received on or before August 27, 2009.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590. Telephone (202) 366-9826. You must identify FAA Docket No. FAA-2009-0552; Airspace Docket No. 09-ANM-7, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>.

FOR FURTHER INFORMATION CONTACT:

Eldon Taylor, Federal Aviation Administration, Operations Support Group, Western Service Center, 1601 Lind Avenue, SW., Renton, WA 98057; telephone (425) 203-4537.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2009-0552 and Airspace Docket No. 09-ANM-7) and be submitted in triplicate to the Docket Management System (see **ADDRESSES** section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to FAA Docket No. FAA-2009-0552 and Airspace Docket No. 09-ANM-7." The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the public docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for the address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the Northwest Mountain Regional Office of the Federal Aviation Administration, Air Traffic Organization, Western Service Area, Operations Support Group, 1601 Lind Avenue, SW., Renton, WA 98057.

Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking, (202) 267-9677, for a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

The FAA is proposing an amendment to Title 14 Code of Federal Regulations (14 CFR) part 71 by establishing Class E airspace at Ronan, MT. Controlled airspace extending upward from 700 feet above the surface is necessary to accommodate aircraft using the new RNAV (GPS) SIAP at Ronan Airport, Ronan, MT. This action would enhance the safety and management of aircraft operations at the airport.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9S, signed October 3, 2008, and effective October 31, 2008, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in this Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a

routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106, describes the authority for the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes controlled airspace at Ronan, MT.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the FAA Order 7400.9S, Airspace Designations and Reporting Points, signed October 3, 2008, and effective October 31, 2008, is amended as follows:

Paragraph 6005. Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

ANM MT E5 Ronan, MT [New]

Ronan Airport, MT
(Lat. 47°34'02" N., long. 114°06'04" W.)

That airspace extending upward from 700 feet above the surface within an 8.4-mile radius of Ronan Airport, excluding that airspace within Federal airways.

* * * * *

Issued in Seattle, Washington, on June 30, 2009.

H. Steve Karnes,

Acting Manager, Operations Support Group, Western Service Center.

[FR Doc. E9-16501 Filed 7-10-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 73

[Docket No. FAA-2009-0490; Airspace Docket No. 09-AWP-3]

RIN 2120-AA66

Proposed Establishment of Restricted Area R-2502A; Fort Irwin, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to establish a restricted area (R-2502A) at Fort Irwin, CA, as part of a Department of the Army initiative at the National Training Center (NTC). The NTC is being expanded to meet the critical need of the Army for additional training land and airspace suitable for maneuvering large numbers of military personnel and equipment. Additionally, this action would modify the Silver military operation area (MOA) in the vicinity of the NTC Complex. Unlike restricted areas, which are designated under 14 CFR part 73, MOAs are not rulemaking airspace actions. However, since the proposed R-2502A infringes on the Silver MOA, the FAA is including a description of the Silver MOA change in this rule. The MOA change described here will also be published in the National Flight Data Digest (NFDD). The Army requested these airspace changes to provide the additional special use airspace (SUA) above the expanded ground maneuver area to facilitate realistic combat training at the NTC.

DATES: Comments must be received on or before August 27, 2009.

ADDRESSES: Send comments on the proposal to the U.S. Department of Transportation, Dockets Operations, M-30, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001; telephone: (202) 366-9826. You must identify docket No. FAA-2009-0490 and Airspace Docket No. 09-AWP-3, at the beginning of your comments. You may also submit comments on the Internet at <http://www.regulations.gov>.

FOR FURTHER INFORMATION CONTACT: Ken McElroy, Airspace and Rules Group,