

Models	Serial Nos.
PA-28R-201 .....	28R-7737002 through 28R-7837317; 2837001 through 2837061; and 2844001 through 2844138.
PA-28R-201T .....	28R-7703001 through 28R-7803374 and 2803001 through 2803012.
PA-28RT-201 .....	28R-7918001 through 28R-7918267 and 28R-8018001 through 28R-8218026.
PA-28RT-201T .....	28R-7931001 through 28R-8631005 and 2831001 through 2831038.
PA-32-260 .....	32-03; 32-04; 32-1 through 32-1297; and 32-7100001 through 32-7800008.
PA-32-300 .....	32-15; 32-21; 32-40000 through 32-40974; and 32-7140001 through 32-7940290.
PA-32S-300 .....	32S-15; 32S-40000 through 32S-40974; and 32S-7140001 through 32S-7240137.
PA-32R-300 .....	32R-7680001 through 32R-7880068.
PA-32RT-300 .....	32R-7885002 through 32R-7985106.
PA-32RT-300T .....	32R-7787001 and 32R-7887002 through 32R-7987126.
PA-32R-301 (SP) .....	32R-8013001 through 32R-8613006; 3213001 through 3213028; and 3213030 through 3213041.
PA-32R-301 (HP) .....	3213029; 3213042 through 3213103; 3246001 through 3246217; 3246219; 3246223; 3246218; 3246220 through 3246222; and 3246224 through 3246244.
PA-32R-301T .....	32R-8029001 through 32R-8629008 and 3229001 through 3229003.
PA-32-301 .....	32-8006002 through 32-8606023; 3206001 through 3206019; 3206042 through 3206044; 3206047; 3206050 through 3206055; and 3206060.
PA-32-301T .....	32-8024001 through 32-8424002.
PA-32R-301T .....	3257001 through 3257483.
PA-32-301FT .....	3232001 through 3232074.
PA-32-301XTC .....	3255001 through 3255014; 3255026, 3255015 through 3255025; 3255027; and 3255051.
PA-34-200 .....	34-E4 and 34-7250001 through 34-7450220.
PA-34-200T .....	34-7570001 through 34-8170092.
PA-34-220T .....	34-8133001 through 34-8633031; 3433001 through 3433172; 3448001 through 3448037; 3448038 through 3448079; 3447001 through 3447029; and 3449001 through 3449377.
PA-44-180 .....	44-7995001 through 44-8195026; 4495001 through 4495013; and 4496001 through 4496251.
PA-44-180T .....	44-8107001 through 44-8207020.

**Unsafe Condition**

(d) This AD results from two field reports of incorrectly assembled control wheel shafts. We are issuing this AD to detect and

correct any incorrectly assembled control wheel shafts. This condition, if left uncorrected, could lead to separation of the control wheel shaft, resulting in loss of pitch and roll control.

**Compliance**

(e) To address this problem, you must do the following, unless already done:

Actions	Compliance	Procedures
(1) Inspect the pilot and copilot control wheel columns for correct control wheel shaft installation.	Within 100 hours time-in-service (TIS) after the effective date of this AD or within 60 days after the effective date of this AD, whichever occurs first.	Follow Piper Aircraft, Inc. Mandatory Service Bulletin No. 1197A, dated September 1, 2009.
(2) If during the inspection required in paragraph (e)(1) of this AD an incorrectly installed control wheel shaft is found, replace the appropriate shaft with a new shaft.	Before further flight after any inspection that finds incorrect installation of the control wheel shaft.	Follow Piper Aircraft, Inc. Mandatory Service Bulletin No. 1197A, dated September 1, 2009.
(3) Inspect the universal joint when doing the action required in (e)(2) of this AD, and if any deterioration, excessive wear, or damage is found, replace the universal joint with a new universal joint.	Before further flight after any inspection that finds incorrect installation of the control wheel shaft.	Follow Piper Aircraft, Inc. Mandatory Service Bulletin No. 1197A, dated September 1, 2009.

**Alternative Methods of Compliance (AMOCs)**

(f) The Manager, Atlanta Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *Attn:* Hector Hernandez, Aerospace Engineer, Atlanta Aircraft Certification Office (ACO), 1701 Columbia Avenue, College Park, GA 30337; *telephone:* (404) 474-5587; *fax:* (404) 474-5606. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

**Related Information**

(g) To get copies of the service information referenced in this AD, contact Piper Aircraft,

Inc., 2926 Piper Drive, Vero Beach, Florida 32960; *telephone:* (772) 567-4361; *fax:* (772) 978-6573; *Internet:* <http://www.newpiper.com/company/publications.asp>. To view the AD docket, go to U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, or on the Internet at <http://www.regulations.gov>.

Issued in Kansas City, Missouri, on October 23, 2009.

**Kim Smith,**

*Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E9-26200 Filed 10-29-09; 8:45 am]

**BILLING CODE 4910-13-P**

**SOCIAL SECURITY ADMINISTRATION**

**20 CFR Parts 404, 405, and 416**

[Docket No. SSA-2007-0053]

**Compassionate Allowances for Schizophrenia; Office of the Commissioner, Hearing**

**AGENCY:** Social Security Administration (SSA).

**ACTION:** Announcement of public hearing.

**SUMMARY:** We are considering ways to quickly identify diseases and other serious medical conditions that obviously meet the definition of disability under the Social Security Act (Act) and can be identified with

minimal objective medical information. We are calling this method “Compassionate Allowances.” In December 2007, April 2008, November 2008, and July 2009, we held Compassionate Allowance public hearings. These hearings concerned rare diseases, cancers, traumatic brain injury and stroke, early-onset alzheimer’s and related dementias, respectively. This hearing is the fifth in the series. The purpose of this hearing is to obtain your views about the advisability and possible methods of identifying and implementing compassionate allowances for young adults with Schizophrenia. We plan to address other medical conditions at subsequent hearings.

**DATES:** This hearing will be held on November 18, 2009, between 8:30 a.m. and 5 p.m., Pacific Standard Time (PST), in San Francisco, CA. The hearing will be held at the Parc 55 Hotel in the Cyril Magnin Room. The hotel’s address is 55 Cyril Magnin Street, San Francisco, CA 94102. While the public is welcome to attend the hearing, only invited witnesses will present testimony. You may also watch the proceedings live via Webcast beginning at 9 a.m., Pacific Standard Time (PST). You may access the Webcast line for the hearing on the Social Security Administration Web site at <http://www.socialsecurity.gov/compassionateallowances/hearings.htm>.

**ADDRESSES:** You may submit written comments about the compassionate allowances initiative with respect to young adults with Schizophrenia, as well as topics covered at the hearing by (1) e-mail addressed to [Compassionate.Allowances@ssa.gov](mailto:Compassionate.Allowances@ssa.gov); or (2) mail to Nancy Schoenberg, Acting Director, Office of Compassionate Allowances and Disability Outreach, ODP, ORDP, Social Security Administration, 4671 Annex Building, 6401 Security Boulevard, Baltimore, MD 21235–6401. We welcome your comments, but we may not respond directly to comments sent in response to this notice of the hearing.

**FOR FURTHER INFORMATION CONTACT:** [Compassionate.Allowances@ssa.gov](mailto:Compassionate.Allowances@ssa.gov). You may also mail inquiries about this meeting to Nancy Schoenberg, Acting Director, Office of Compassionate Allowances and Disability Outreach, ODP, ORDP, Social Security Administration, 4671 Annex, 6401 Security Boulevard, Baltimore, MD 21235–6401. For information on eligibility or filing for benefits, call our national toll-free number 1–800–772–1213 or TTY 1–800–325–0778, or visit

Social Security online, at <http://www.socialsecurity.gov>.

#### SUPPLEMENTARY INFORMATION:

##### Background

Under titles II and XVI of the Act, we pay benefits to individuals who meet our rules for entitlement and have medically determinable physical or mental impairments that are severe enough to meet the definition of disability in the Act. The rules for determining disability can be very complicated, but some individuals have such serious medical conditions that their conditions obviously meet our disability standards. To better address the needs of these individuals, we are implementing the Compassionate Allowance initiative to quickly identify diseases and other medical conditions that invariably qualify under the Listing of Impairments based on minimal objective medical information.

##### Will We Respond to Your Comments?

We will carefully consider your comments, although we will not respond directly to comments sent in response to this notice or the hearing.

##### Additional Hearings

We have held four hearings since December 2007. The hearings were on rare diseases, cancers, and traumatic brain injury (TBI) and stroke, early-onset alzheimer’s and related dementias. You may access the transcripts of the hearings at <http://www.socialsecurity.gov/compassionateallowances>. We plan to hold additional hearings on other conditions and will announce those hearings later with notices in the **Federal Register**.

(Catalog of Federal Domestic Assistance Program Nos. 96.001, Social Security—Disability Insurance; 96.006, Supplemental Security Income. (72 FR at 62608).

Dated: October 26, 2009.

**Michael J. Astrue,**

*Commissioner of Social Security.*

[FR Doc. E9–26194 Filed 10–29–09; 8:45 am]

**BILLING CODE 4191–02–P**

## DEPARTMENT OF HEALTH AND HUMAN SERVICES

### 42 CFR Part 84

**RIN 0920–AA33**

### Total Inward Leakage Requirements for Respirators

**AGENCY:** Centers for Disease Control and Prevention, HHS.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** The Centers for Disease Control and Prevention (“CDC”) proposes to establish total inward leakage (TIL) requirements for half-mask air-purifying particulate respirators approved by the National Institute for Occupational Safety and Health (“NIOSH”) of CDC. The proposed new requirements specify TIL minimum performance requirements and testing to be conducted by NIOSH and respirator manufacturers to demonstrate that these respirators, when selected and used correctly, provide effective respiratory protection to intended users against toxic dusts, mists, fumes, fibers, and biological and infectious aerosols (e.g. influenza A(H5N1), severe acute respiratory syndrome (SARS) coronavirus, and *Mycobacterium tuberculosis*).

**DATES:** CDC invites comments on this proposed rule from interested parties. Comments must be received by December 29, 2009.

**ADDRESSES:** You may submit comments, identified by RIN: 0920–AA33, by any of the following methods:

- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *E-mail:* [niocindocket@cdc.gov](mailto:niocindocket@cdc.gov). Include (HHS INSERT RIN NUMBER) and “42 CFR part 84” in the subject line of the message.

- *Mail:* NIOSH Docket Office, Robert A. Taft Laboratories, MS–C34, 4676 Columbia Parkway, Cincinnati, OH 45226.

*Instructions:* All submissions received must include the agency name and docket number or Regulatory Information Number (RIN) for this rulemaking. All comments received will be posted without change to <http://www.regulations.gov>, including any personal information provided. For detailed instructions on submitting comments and additional information on the rulemaking process, see the “Public Participation” heading of the **SUPPLEMENTARY INFORMATION** section of this document.

*Docket:* For access to the docket to read background documents or comments received, go to <http://www.regulations.gov>.

**FOR FURTHER INFORMATION CONTACT:** William Newcomb, NIOSH National Personal Protective Technology Laboratory (“NPPTL”), Pittsburgh, PA, (412) 386–4034 (this is not a toll-free number). Information requests can also be submitted by e-mail to [niocindocket@cdc.gov](mailto:niocindocket@cdc.gov).

**SUPPLEMENTARY INFORMATION:**