

(k) Inspections of Meterpanel Assemblies—Repaired

Borescope-inspect meterpanel assemblies that incorporate SB No. RB.211-72-7998,

that have been previously repaired. Use paragraphs 3.B.(1) through 3.B.(7) of the Accomplishment Instructions of RR ASB No. RB.211-72-AB482, Revision 9, dated July 28,

2003, and the compliance thresholds in Table 5 of this AD to do the inspections.

TABLE 5—METERPANEL ASSEMBLY—REPAIRED

Engine series	Initial inspection	Repetitive inspection	Parts exceeding initial inspection cycles
RB211-524D4, -524G, and -524H..	Within 500 to 700 CSLR	Within 400 CSLI	Within 50 CIS after the effective date of this AD.

(l) Reject Parts

Remove from service, parts that exceed the acceptance criteria.

(m) Mandatory Terminating Action

Replace any front combustion liner assembly that has a P/N listed in paragraph (c) of this AD at the next shop visit.

(1) For RB211-524B-02, -524B3-02, -524B4, -524C2 and -524B2, -524B4, -524C2, and -524D4 series engines, replacing the front combustion liner assembly with a front combustion liner assembly that incorporates the modifications in RR SB No. RB.211-72-9670, Original Issue, dated August 27, 1993; or RR SB No. RB.211-72-9764, Revision 3, dated January 16, 1998, constitutes terminating action to the repetitive inspections in paragraphs (g), (h), (i), (j), and (k) of this AD.

(2) For RB211-524G and -524H engines, replacing the front combustion liner assembly with a front combustion liner assembly that incorporates the modifications in RR SB No. RB.211-72-9764, Revision 3, dated January 16, 1998, constitutes terminating action to the repetitive inspections in paragraphs (f), (g), (h), (i), and (j) of this AD.

(n) Definition of Shop Visit

For the purpose of this AD, a shop visit is any time that the 04 module is removed for refurbishment or overhaul.

(o) Related Information

Contact Alan Strom, Aerospace Engineer, Engine Certification Office, FAA, 12 New England Executive Park, Burlington, MA 01803; phone: (781) 238-7143; fax: (781) 238-7199; email: alan.strom@faa.gov, for more information about this AD.

(p) Material Incorporated by Reference

You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference (IBR) of the following service information under 5 U.S.C. 552(a) and 1 CFR part 51 on the date specified:

(1) Rolls-Royce plc Alert Service Bulletin No. RB.211-72-AB482, Revision 9, July 28, 2003, approved for IBR February 9, 2005 (70 FR 680, January 5, 2005).

(2) Rolls-Royce plc Service Bulletin No. RB.211-72-9670, Original Issue, August 27, 1993, approved for IBR February 9, 2005 (70 FR 680, January 5, 2005).

(3) Rolls-Royce plc Service Bulletin No. RB.211-72-9764, Revision 3, January 16,

1998, approved for IBR February 9, 2005 (70 FR 680, January 5, 2005).

(4) For service information identified in this AD, contact Rolls-Royce plc, P.O. Box 31, Derby, DE24 8BJ, United Kingdom; phone: 011-44-1332-242424; fax: 011-44-1332-249936.

(5) You may review copies of the service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call (781) 238-7125.

(6) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Burlington, Massachusetts, on December 28, 2011.

Peter A. White,

Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2012-134 Filed 1-6-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2011-0540; Airspace Docket No. 11-ASO-20]

Establishment of Class E Airspace; Inverness, FL

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class E Airspace at Inverness, FL, to accommodate the new Area Navigation (RNAV) Global Positioning System (GPS) Standard Instrument Approach Procedures serving Inverness Airport. This action enhances the safety and airspace management of Instrument Flight Rules (IFR) operations within the National Airspace System. This action also makes a minor adjustment to the geographic coordinates of the airport.

DATES: Effective 0901 UTC, April 5, 2012. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-6364.

SUPPLEMENTARY INFORMATION:**History**

On October 28, 2011, the FAA published in the **Federal Register** a notice of proposed rulemaking to establish Class E airspace at Inverness, FL (76 FR 66871) Docket No. FAA-2011-0540. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received. Subsequent to publication, the FAA found that the geographic coordinates for Inverness Airport needed to be adjusted. This action makes that adjustment. Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9V dated August 9, 2011, and effective September 15, 2011, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

The Rule

This amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 establishes the Class E airspace extending upward from 700 feet above the surface at Inverness, FL to provide the controlled airspace required to accommodate the new Area Navigation (RNAV) Global Positioning System (GPS) Standard Instrument Approach Procedures developed for Inverness Airport. This action is necessary for the safety and management of IFR operations at the airport. This action also adjusts the geographic coordinates

of the airport to be in concert with the FAA's aeronautical database.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore, (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

This rulemaking is promulgated under the authority described in subtitle VII, part A, subpart I, section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes controlled airspace at Inverness Airport, Inverness, FL.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9V, Airspace

Designations and Reporting Points, dated August 9, 2011, effective September 15, 2011, is amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

ASO FL E5 Inverness, FL [New]

Inverness Airport, FL
(Lat. 28°48'13" N, long. 82°19'06" W.)

That airspace extending upward from 700 feet above the surface within a 6.5-mile radius of Inverness Airport.

Issued in College Park, Georgia, on December 28, 2011.

Jack Schroeter,

*Acting Manager, Operations Support Group,
Eastern Service Center, Air Traffic
Organization.*

[FR Doc. 2012–55 Filed 1–6–12; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30820; Amdt. No. 3459]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This rule establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective January 9, 2012. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director

of the Federal Register as of January 9, 2012.

ADDRESSES: Availability of matter incorporated by reference in the amendment is as follows:

For Examination

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which the affected airport is located;

3. The National Flight Procedures Office, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Availability—All SIAPs are available online free of charge. Visit nfdc.faa.gov to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from:

1. FAA Public Inquiry Center (APA–200), FAA Headquarters Building, 800 Independence Avenue SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

FOR FURTHER INFORMATION CONTACT:

Richard A. Dunham III, Flight Procedure Standards Branch (AFS–420) Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK 73125) telephone: (405) 954–4164.

SUPPLEMENTARY INFORMATION: This rule amends Title 14, Code of Federal Regulations, Part 97 (14 CFR part 97) by amending the referenced SIAPs. The complete regulatory description of each SIAP is listed on the appropriate FAA Form 8260, as modified by the National Flight Data Center (FDC)/Permanent Notice to Airmen (P–NOTAM), and is incorporated by reference in the amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of Title 14 of the Code of Federal Regulations.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic