### (k) Repair

(1) If any cracking is found during any inspection required by paragraph (j)(2) of this AD: Before further flight, repair the cracking using a method approved in accordance with the procedures specified in paragraph (m) of this AD.

(2) If any holes with galling, corrosion, or damage due to fastener removal are found during any inspection required by paragraph (j)(2) of this AD: Before further flight, repair the holes, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 757–54–0028, Revision 1, dated August 25, 1994.

### (l) Credit for Previous Actions

(1) This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Service Bulletin 757–54–0035, Revision 4, dated June 18, 2009; or Revision 5, dated June 9, 2011; which are not incorporated by reference in this AD.

(2) This paragraph provides credit for the actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD using Boeing Service Bulletin 757–54–0035, Revision 4, dated June 18, 2009; or Revision 5, dated June 9, 2011; which are not incorporated by reference in this AD.

(3) This paragraph provides credit for the actions required by paragraph (j) of this AD, if those actions were performed before the effective date of this AD using Boeing Service Bulletin 757–54–0003, dated December 14, 1984; or Boeing Service Bulletin 757–54–0028, dated March 31, 1994; which are not incorporated by reference in this AD.

## (m) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: *9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.* 

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(4) AMOCs approved for AD 2004–12–07, Amendment 39–13666 (69 FR 33561, June 16, 2004), are approved as AMOCs for paragraphs (g) and (h) of this AD, except for AMOCs that approved a revised compliance time.

### (n) Related Information

(1) For more information about this AD, contact Nancy Marsh, Aerospace Engineer, Airframe Branch, ANM–120S, Seattle Aircraft Certification Office (ACO), FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: 425–917–6440; fax: 425–917–6590; email: Nancy.Marsh@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; phone: 206–544– 5000, extension 1; fax: 206–766–5680; Internet: *https://www.myboeingfleet.com*. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on April 4, 2013.

### Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

BILLING CODE 4910–13–P

### DEPARTMENT OF HOMELAND SECURITY

### Coast Guard

33 CFR 101, 104, 105, 106

[Docket No. USCG-2007-28915]

### Transportation Worker Identification Credential (TWIC)—Reader Requirements

AGENCY: Coast Guard, DHS.

**ACTION:** Notice of public meeting on proposed rulemaking; request for comments.

**SUMMARY:** The Coast Guard announces a public meeting to take place on May 9, 2013, in Chicago, Illinois to receive comments on a notice of proposed rulemaking published in the **Federal Register** on March 22, 2013, under the title "Transportation Worker Identification Credential (TWIC)— Reader Requirements." The Coast Guard encourages members of the public to attend this meeting and provide oral comments on the notice of proposed rulemaking on TWIC reader requirements.

**DATES:** A public meeting will be held on Thursday, May 9, 2013, from 1:00 p.m. to 5:00 p.m. to provide an opportunity for oral comments. Coast Guard personnel will accept written comments and related materials at the public meeting as well. Written comments may also be submitted in response to the notice of proposed rulemaking referenced in the **SUPPLEMENTARY INFORMATION** section. The comment period for the notice of proposed rulemaking will close on May 21, 2013. All written comments and related materials submitted before or after the meeting must either be submitted to our online docket via *http:// www.regulations.gov* on or before May 21, 2013, or reach the Docket Management Facility by that date.

ADDRESSES: The public meeting will be held at the Chicago Marriott O'Hare, 8535 West Higgins Road, Chicago, Illinois 60631. The building is accessible by taxi, public transit, and privately-owned conveyance.

This meeting is open to the public. Please note that the session may adjourn early if all business, concerns, and questions are addressed. You may submit written comments identified by docket number USCG-2007-28915 before or after the meeting using any one of the following methods:

(1) Federal eRulemaking Portal: http://www.regulations.gov.

(2) Fax: 202-493-2251.

(3) *Mail:* Docket Management Facility (M–30), U.S. Department of Transportation, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590– 0001.

(4) *Hand delivery:* Same as mail address above, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The telephone number is 202–366–9329.

To avoid duplication, please use only one of these four methods. Our online docket for this notice is available on the Internet at *http://www.regulations.gov* under docket number USCG-2007-28915.

FOR FURTHER INFORMATION CONTACT: If you have questions concerning the meeting, please call or email LCDR Gregory Callaghan, Commandant (CG– FAC–2), Coast Guard; telephone 202– 372–1168, email

*Gregory.A.Callaghan@uscg.mil.* If you have questions on viewing or submitting material to the docket, call Ms. Barbara Hairston, Program Manager, Docket Operations, telephone 202–366–9826. **SUPPLEMENTARY INFORMATION:** 

### Background and Purpose

On March 22, 2013, the Coast Guard published a notice of proposed rulemaking (NPRM) in the **Federal Register** (78 FR 17781), in which we proposed to require owners and operators of certain vessels and facilities regulated by the Coast Guard to use electronic readers designed to work with the Transportation Worker Identification Credential (TWIC) as an access control measure. The NPRM also proposed additional requirements associated with electronic TWIC readers, including recordkeeping requirements for those owners and operators required to use an electronic TWIC reader, and security plan amendments to incorporate TWIC reader requirements. The TWIC program, including the TWIC reader requirements proposed in the NPRM, is an important component of the Coast Guard's multi-layered system of access control requirements and other measures designed to enhance maritime security.

As authorized by the Maritime Transportation Security Act of 2002<sup>1</sup> (MTSA), the Transportation Security Administration (TSA) established the TWIC program to address identity management shortcomings and vulnerabilities identified in the nation's transportation system and to comply with the MTSA statutory requirements. On January 25, 2007, the Department of Homeland Security (DHS), through the Coast Guard and TSA, promulgated regulations that require mariners and other individuals granted unescorted access to secure areas of MTSAregulated vessels or facilities to undergo a security threat assessment by TSA and obtain a TWIC.<sup>2</sup>

This NPRM that is the subject of this public meeting, which would require owners and operators of certain types of vessels and facilities to use electronic TWIC readers, would advance the goals of the TWIC program. In crafting the proposals in the NPRM, the Coast Guard conducted a risk-based analysis of MTSA-regulated vessels and facilities to categorize them into one of three risk groups, labeled A, B, and C. Risk Group A is comprised of vessels and facilities that present the highest risk of being involved in a transportation security incident (TSI).<sup>3</sup> The NPRM proposes TWIC reader requirements for vessels and facilities in Risk Group A. Under the NPRM, vessels and facilities in Risk Groups B and C present progressively lower risks, and would continue to

follow existing regulatory requirements for visual TWIC inspection.

The Coast Guard believes that in addition to receiving written comments on the NPRM, a public meeting would benefit the impacted community by providing another forum to raise relevant issues. Also, the Security and Accountability For Every (SAFE) Port Act of 2006 <sup>4</sup> requires the Coast Guard to hold at least one public hearing before promulgating final TWIC reader regulations (*see* 46 U.S.C. 70105(k)(3)). This public meeting will further enable the Coast Guard to craft policy informed by the public.

You may view the NPRM, written comments, and supporting documents in the online docket by going to *http://* www.regulations.gov and using "USCG-2007–28915" as your search term. Locate the NPRM among the search results and use the filters on the left side of the page to search for specific types of documents. If you do not have access to the Internet, you may view the docket by visiting the Docket Management Facility in Room W12–140 on the ground floor of the Department of Transportation West Building, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Coast Guard has an agreement with the Department of Transportation to use its Docket Management Facility.

We encourage you to participate by submitting comments either orally at the meeting or in writing. If you bring written comments to the meeting, you may submit them to Coast Guard personnel specified at the meeting to receive written comments. These comments will be submitted to our online public docket. All comments received will be posted without change to http://www.regulations.gov and will include any personal information you have provided.

Anyone can search the electronic form of comments received into any of our dockets by the name of the individual submitting the comment (or signing the comment, if submitted on behalf of an association, business, labor union, or other entity). You may review a Privacy Act notice regarding our public dockets in the January 17, 2008, issue of the **Federal Register** (73 FR 3316).

# Information on Services for Individuals With Disabilities

For information on facilities or services for individuals with disabilities

or to request special assistance at the public meeting, contact LCDR Gregory Callaghan at the telephone number or email address indicated under the **FOR FURTHER INFORMATION CONTACT** section of this notice.

### **Public Meeting**

The Coast Guard will hold a public meeting regarding the "Transportation Worker Identification Credential (TWIC)-Reader Requirements" NPRM (78 FR 17781) on Thursday, May 9, 2013 from 1:00 p.m. to 5:00 p.m., at the Chicago Marriott O'Hare, 8535 West Higgins Road, Chicago, Illinois 60631. The building is accessible by taxi, public transit, and privately-owned conveyance. Please note that the session may adjourn early if all business, concerns, and questions are addressed. We will post a written summary of the meeting and oral comments in the docket.

### Authority

This notice is issued under the authority of 46 U.S.C. 70105(k)(3) and 5 U.S.C. 552(a).

Dated: April 8, 2013.

### A.E. Tucci,

Captain, U.S. Coast Guard, Chief, Office of Port and Facility Compliance (CG–FAC). [FR Doc. 2013–08735 Filed 4–12–13; 8:45 am] BILLING CODE 9110–04–P

### DEPARTMENT OF VETERANS AFFAIRS

### 38 CFR Part 17

RIN 2900-AO51

### Removal of Penalty for Breaking Appointments

**AGENCY:** Department of Veterans Affairs. **ACTION:** Proposed rule.

**SUMMARY:** The Department of Veterans Affairs (VA) proposes to remove a regulation that states that a veteran who misses two medical appointments without providing 24 hours' notice and a reasonable excuse is deemed to have refused VA medical care. The current regulation states that no further treatment will be furnished to a veteran deemed to have refused care except in emergency situations, unless the veteran agrees to cooperate by keeping future appointments. VA believes that the current regulation is incompatible with regulatory changes implemented after the regulation was promulgated, is not in line with current practice, and is inconsistent with VA's patient-centered approach to medical care.

<sup>&</sup>lt;sup>1</sup>Public Law 107–295, 116 Stat. 2064 (Nov. 2, 2002).

<sup>&</sup>lt;sup>2</sup> Transportation Worker Identification Credential (TWIC) Implementation in the Maritime Sector; Hazardous Materials Endorsement for a Commercial Driver's License, 72 FR 3492 (Jan. 25, 2007).

<sup>&</sup>lt;sup>3</sup> A transportation security incident is a security incident resulting in a significant loss of life, environmental damage, transportation system disruption, or economic disruption in a particular area, as defined in 46 U.S.C. 70101 (49 CFR 1572.103).

<sup>&</sup>lt;sup>4</sup> Public Law 109–347, 120 Stat. 1884 (Oct. 13, 2006).