

(a) Comments Due Date

We must receive comments by April 28, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Costruzioni Aeronautiche Tecnam srl Model P2006T airplanes, all serial numbers, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 71: Power Plant.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a cracked engine mount. We are issuing this AD to detect and correct cracked or deformed engine mounts, which could lead to engine damage, possibly resulting in damage to the airplane and injury to the occupants.

(f) Actions and Compliance

Unless already done, do the following actions as specified in paragraphs (f)(1) through (f)(3) of this AD:

(1) *For airplanes with 600 hours time-in-service (TIS) or more as of the effective date of this AD:* Within the next 25 hours TIS after the effective date of this AD or within the next 30 days after the effective date of this AD, whichever occurs first, inspect the left hand and right hand engine mounts, part number (P/N) 26-7-1200-000, for cracks and deformation following Costruzioni Aeronautiche TECNAM Service Bulletin No. SB 138-CS, Rev. 0, dated November 25, 2013.

(2) *For airplanes with less than 600 hours TIS as of the effective date of this AD:* After accumulating 600 hours TIS but before exceeding 625 hours TIS, inspect the left hand and right hand engine mounts, P/N 26-7-1200-000, for cracks and deformation following Costruzioni Aeronautiche TECNAM Service Bulletin No. SB 138-CS, Rev. 0, dated November 25, 2013.

(3) If a crack or any other deformation is found during the inspection required by paragraph (f)(1) or (f)(2) of this AD, before further flight, you must contact Costruzioni Aeronautiche Tecnam srl to obtain FAA-approved repair instructions approved specifically for compliance with this AD and incorporate those instructions. You can find contact information for Costruzioni Aeronautiche Tecnam srl in paragraph (h) of this AD. Use the occurrence report in Costruzioni Aeronautiche TECNAM Service Bulletin No. SB 138-CS, Rev. 0, dated November 25, 2013.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to

ATTN: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090; email: albert.mercado@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(h) Related Information

MCAI European Aviation Safety Agency (EASA) AD No.: 2014-0001, dated January 6, 2014, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0156. For service information related to this AD, contact Costruzioni Aeronautiche Tecnam Airworthiness Office, Via Maiorise-81043 Capua (CE) Italy; telephone: +39 0823 620134; fax: +39 0823 622899; email: m.oliva@tecnam.com or g.paduano@tecnam.com; Internet: www.tecnam.com/it-IT/documenti/service-bulletins.aspx. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on March 7, 2014.

Steven W. Thompson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-05612 Filed 3-13-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2013-0986; Airspace Docket No. 13-AGL-25]

Proposed Establishment of Class E Airspace; Bois Blanc Island, MI

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to establish Class E airspace at Bois Blanc Island, MI. Controlled airspace is necessary to accommodate new Standard Instrument Approach Procedures (SIAP) at Bois Blanc Island Airport. The FAA is taking this action to enhance the safety and management of Instrument Flight Rules (IFR) operations for SIAPs at the airport.

DATES: Comments must be received on or before April 28, 2014.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2013-0986/Airspace Docket No. 13-AGL-25, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FOR FURTHER INFORMATION CONTACT: Raul Garza, Jr., Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone: 817-321-7654.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall

regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2013-0986/Airspace Docket No. 13-AGL-25." The postcard will be date/time stamped and returned to the commenter.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Central Service Center, 2601 Meacham Blvd., Fort Worth, TX 76137.

Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

This action proposes to amend Title 14, Code of Federal Regulations (14 CFR), Part 71 by establishing Class E airspace extending upward from 700 feet above the surface within a 6.3-mile radius of Bois Blanc Island Airport, Bois Blanc, MI, to accommodate new standard instrument approach procedures. Controlled airspace is needed for the safety and management of IFR operations at the airport.

Class E airspace areas are published in Paragraph 6005 of FAA Order 7400.9X, dated August 7, 2013 and effective September 15, 2013, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would establish controlled airspace at Bois Blanc Island Airport, Bois Blanc Island, MI.

Environmental Review

This proposal will be subject to an environmental analysis in accordance with FAA Order 1050.1E, "Environmental Impacts: Policies and Procedures" prior to any FAA final regulatory action.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR Part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.9X, Airspace Designations and Reporting Points, dated August 7, 2013 and effective September 15, 2013, is amended as follows:

Paragraph 6005 Class E Airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

AGL MI E5 Bois Blanc Island, MI [New]

Bois Blanc Island Airport, MI
(Lat. 45°45'59" N., long. 084°30'14" W.)

That airspace extending upward from 700 feet above the surface within a 6.3-mile radius of Bois Blanc Island Airport.

Issued in Fort Worth, TX, on March 4, 2014.

Kent M. Wheeler,

*Acting Manager, Operations Support Group,
ATO Central Service Center.*

[FR Doc. 2014-05688 Filed 3-13-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF LABOR

Employment and Training Administration

20 CFR Part 655

RIN 1205-ZA00

Wage Methodology for the Temporary Non-Agricultural Employment H-2B Program

AGENCY: Employment and Training Administration, Labor.

ACTION: Notification of Status of the 2011 H-2B Wage Rule.

SUMMARY: The Department of Labor (DOL) is providing notice to the regulated community of the status of Wage Methodology for the Temporary Non-agricultural Employment H-2B Program, published January 19, 2011 in the **Federal Register**. DOL intends to publish a notice of proposed rulemaking on the proper wage methodology for the H-2B program, working off of the 2011 Wage Rule as a starting point.

DATES: March 14, 2014.

FOR FURTHER INFORMATION CONTACT: For further information, contact William L. Carlson, Ph.D., Administrator, Office of Foreign Labor Certification, ETA, U.S. Department of Labor, 200 Constitution Avenue NW., Room C-4312, Washington, DC 20210; Telephone (202) 693-3010 (this is not a toll-free number). Individuals with hearing or