

Standard No. 118 *Power-Operated Window, Partition, and Roof Panel System*: reprogramming the power-operated window, partition, and roof panel systems by using the Examiner Smart Diagnostic System to change the country code options.

Standard No. 138 *Tire Pressure Monitoring Systems*: installation of the U.S.-model tire pressure control unit, antenna, and sensors. In addition, programming of the associated control units by using the Examiner Smart Diagnostic System to change the country code options.

Standard No. 208 *Occupant Crash Protection*: installation of U.S.-model seat occupancy detection control units and seat frame sensors and replacement of the air bag ECUs. In addition, reprogramming of all associated control systems with U.S.-model software and reprogramming of the driver's seat controller to activate the safety belt warning buzzer using an Examiner Smart Diagnostic System.

The petitioner additionally states that a vehicle identification plate must be affixed to the vehicle near the left windshield pillar to meet the requirements of 49 CFR part 565.

All comments received before the close of business on the closing date indicated above will be considered, and will be available for examination in the docket at the above addresses both before and after that date. To the extent possible, comments filed after the closing date will also be considered. Notice of final action on the petition will be published in the **Federal Register** pursuant to the authority indicated below.

Authority: 49 U.S.C. 30141(a)(1)(A), (a)(1)(B), and (b)(1); 49 CFR 593.7; delegation of authority at 49 CFR 1.95 and 501.8.

Jeffrey M. Giuseppe,
Director, Office of Vehicle Safety Compliance.
[FR Doc. 2016-01270 Filed 1-21-16; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2015-0122; Notice 1]

Van Hool N.V., Receipt of Petition for Decision of Inconsequential Noncompliance

AGENCY: National Highway Traffic Safety Administration (NHTSA), Department of Transportation (DOT).

ACTION: Receipt of petition.

SUMMARY: Van Hool N.V. (Van Hool), has determined that certain model year

(MY) 2015–2016 Van Hool Double Deck buses do not fully comply with paragraph S5.3.4 of Federal Motor Vehicle Safety Standard (FMVSS) No. 121, *Air Brake Systems*. Van Hool filed a report dated November 6, 2015, pursuant to 49 CFR part 573, *Defect and Noncompliance Responsibility and Reports*. Van Hool then petitioned NHTSA under 49 CFR part 556 requesting a decision that the subject noncompliance is inconsequential to motor vehicle safety.

DATES: The closing date for comments on the petition is February 22, 2016.

ADDRESSES: Interested persons are invited to submit written data, views, and arguments on this petition. Comments must refer to the docket and notice number cited in the title of this notice and submitted by any of the following methods:

- **Mail:** Send comments by mail addressed to: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Deliver:** Deliver comments by hand to: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590. The Docket Section is open on weekdays from 10 a.m. to 5 p.m. except Federal Holidays.

- **Electronically:** Submit comments electronically by: logging onto the Federal Docket Management System (FDMS) Web site at <http://www.regulations.gov/>. Follow the online instructions for submitting comments. Comments may also be faxed to (202) 493-2251.

Comments must be written in the English language, and be no greater than 15 pages in length, although there is no limit to the length of necessary attachments to the comments. If comments are submitted in hard copy form, please ensure that two copies are provided. If you wish to receive confirmation that comments you have submitted by mail were received, please enclose a stamped, self-addressed postcard with the comments. Note that all comments received will be posted without change to <http://www.regulations.gov/>, including any personal information provided.

The petition, supporting materials, and all comments received before the close of business on the closing date indicated above will be filed in the docket and will be considered. All comments and supporting materials received after the closing date will also

be filed and will be considered to the extent possible.

When the petition is granted or denied, notice of the decision will also be published in the **Federal Register** pursuant to the authority indicated at the end of this notice.

All documents submitted to the docket may be viewed by anyone at the address and times given above. The documents may also be viewed on the Internet at <http://www.regulations.gov> by following the online instructions for accessing the dockets. The docket ID number for this petition is shown at the heading of this notice.

DOT's complete Privacy Act Statement is available for review in the **Federal Register** published on April 11, 2000, (65 FR 19477–78).

SUPPLEMENTARY INFORMATION:

I. Overview

Pursuant to 49 U.S.C. 30118(d) and 30120(h) (see implementing rule at 49 CFR part 556), Van Hool submitted a petition for an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential to motor vehicle safety.

This notice of receipt of Van Hool's petition is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of the petition.

II. Vehicles Involved

Affected are approximately 48 MY 2015–2016 Van Hool Double Deck buses that were manufactured between December 13, 2014 and October 22, 2015.

III. Noncompliance

Van Hool explains that the noncompliance is that brake release times slightly exceed the requirements as specified in paragraph S5.3.4 of FMVSS No. 121.

IV. Rule Text

Paragraph S5.3.4 of FMVSS No. 121 requires in pertinent part:

S5.3.4 *Brake Release Time*. Each service brake system shall meet the requirements of S5.3.1 (a) through (b) . . .

V. Summary of Van Hool's Petition

Van Hool described the subject noncompliance and stated its belief that the noncompliance is inconsequential to motor vehicle safety based on the following reasoning:

(1) Based on the results of testing that Van Hool conducted on some of the affected buses, it determined that the brake release times, on average,

exceeded the FMVSS No. 121 requirement by only 0.03 of a second on the front axle, by 0.05 of a second on the tag axle, and by 0.10 of a second on the drive axle.

(2) Van Hool determined that this noncompliance may be due to the change of fitting for this type of vehicle. These new fittings for the Double Deck buses were introduced in production in September 2014. The classic brass couplings were replaced with push-in tube connections made of composite material to remedy certain complaints of air loss. The effect of minimal loss of internal air flow was misjudged, which caused the brake release time to exceed the requirements.

However, Van Hool believes that there is no safety issue, nor unnecessary brake drag during acceleration after brake release due to the reaction time of the driver (moving foot from brake pedal to throttle pedal) and the reaction time of the complete driveline being longer than the brake release time.

(3) Van Hool stated its belief that because the brake actuation time on the subject buses fulfilled the requirements as specified in paragraph S5.3.3 of FMVSS No. 121, that the noncompliance has no effect on the brake performance. Van Hool found that its testing showed a margin on the required brake actuation time of 11% for the front axle, 20% for the drive axle and 17% for the tag axle. For this reason Van Hool is convinced that the noncompliance will not show significant differences in dynamic brake test and will have no influence on the motor vehicle safety. Thus, Van Hool did not repeat the dynamic brake test. Also, the dynamic brake test was not repeated on any of the subject vehicles because Van Hool's dynamic brake test showed a minimum 25% margin for the brake stopping distance requirement.

(4) Van Hool made reference to previous inconsequential noncompliance petitions that it believes are similar to its petition and that were granted by NHTSA.

Van Hool additionally informed NHTSA that the noncompliance has been corrected on vehicles in subsequent production and that all future vehicles will be in full compliance with FMVSS No. 121.

In summation, Van Hool believes that the described noncompliances are inconsequential to motor vehicle safety, and that its petition, to exempt Van Hool from providing recall notification of noncompliances as required by 49 U.S.C. 30118 and remedying the recall noncompliance as required by 49 U.S.C. 30120 should be granted.

NHTSA notes that the statutory provisions (49 U.S.C. 30118(d) and 30120(h)) that permit manufacturers to file petitions for a determination of inconsequentiality allow NHTSA to exempt manufacturers only from the duties found in sections 30118 and 30120, respectively, to notify owners, purchasers, and dealers of a defect or noncompliance and to remedy the defect or noncompliance. Therefore, any decision on this petition only applies to the subject buses that Van Hool no longer controlled at the time it determined that the noncompliance existed. However, any decision on this petition does not relieve equipment distributors and dealers of the prohibitions on the sale, offer for sale, or introduction or delivery for introduction into interstate commerce of the noncompliant buses under their control after Van Hool notified them that the subject noncompliance existed.

Authority: 49 U.S.C. 30118, 30120; Delegations of authority at 49 CFR 1.95 and 501.8.

Jeffrey M. Giuseppe,
Director, Office of Vehicle Safety Compliance.
[FR Doc. 2016-01168 Filed 1-21-16; 8:45 am]
BILLING CODE 4910-59-P

DEPARTMENT OF VETERANS AFFAIRS

Privacy Act of 1974; System of Records

AGENCY: Department of Veterans Affairs (VA).

ACTION: Notice of Amendment to Systems of Records.

SUMMARY: As required by the Privacy Act of 1974 (5 U.S.C. 552a(e)(4)), notice is hereby given that the Department of Veterans Affairs (VA) is amending the system of records entitled "Customer User Provisioning System (CUPS)-VA" (87VA005OP). VA is re-publishing the system notice in its entirety.

DATES: Comments on this new system of records must be received no later than February 22, 2016. If no public comment is received during the period allowed for comment or unless otherwise published in the **Federal Register** by VA, the new system will become effective February 22, 2016.

ADDRESSES: Written comments concerning the proposed amended system of records may be submitted by: mail or hand-delivery to Director, Regulations Management (02REG), Department of Veterans Affairs, 810 Vermont Avenue NW., Room 1068, Washington, DC 20420; fax to (202)

273-9026; or email to <http://www.Regulations.gov>. All comments received will be available for public inspection in the Office of Regulation Policy and Management, Room 1063B, between the hours of 8:00 a.m. and 4:30 p.m., Monday through Friday (except holidays). Please call (202) 461-4902 (this is not a toll-free number) for an appointment.

FOR FURTHER INFORMATION CONTACT: Andrea Birkland, Chief, Systems Access Management, Enterprise Operations, Department of Veterans Affairs, 1615 Woodward Street, Austin, Texas 78772, telephone (512) 326-6394.

SUPPLEMENTARY INFORMATION: The Department is proposing to amend its system of records entitled "Customer User Provisioning System (CUPS)" by updating the system manager and address to Deputy Director, Security Systems, 1615 Woodward Street, Austin, Texas 78772. The telephone number is (512) 326-6021; updating the system location name from Corporate Data Center Operations (CDCO) to Enterprise Operations (EO); and changing the information contact to Andrea Birkland, Chief, Systems Access Management, Department of Veterans Affairs, 1615 Woodward Street, Austin, Texas 78772, telephone (512) 326-6394.

Signing Authority

The Secretary of Veterans Affairs, or designee, approved this document and authorized the undersigned to sign and submit the document to the Office of the Federal Register for publication electronically as an official document of the Department of Veterans Affairs. Robert L. Nabors II, Chief of Staff, approved this document on January 11, 2016, for publication.

Dated: January 12, 2016.

Kathleen M. Manwell,
Program Analyst, VA Privacy Service, Office of Privacy and Records Management, Department of Veterans Affairs.

87VA005OP

SYSTEM NAME:

Customer User Provisioning System (CUPS)-VA.

SYSTEM LOCATION:

The automated records are maintained by the Enterprise Operations (EO), 1615 Woodward Street, Austin, TX 78772. The paper records will be maintained at each VA field station that has a responsibility for CUPS input.

CATEGORIES OF INDIVIDUALS COVERED BY THE SYSTEM:

All Department of Veterans Affairs employees, employees of other