

TABLE 1 TO PARAGRAPH (h) OF THIS AD—REPLACEMENT COMPLIANCE TIME—Continued

Total flight cycles accumulated on the Teleflex cable having P/N 72830–20 (since first installation on an airplane) as of the effective date of this AD	Compliance time
Equal to or more than 6,000 total flight cycles, but fewer than 7,000 total flight cycles.	Within 200 flight cycles or 6 months after the effective date of this AD, whichever occurs first.
Equal to or more than 7,000 total flight cycles .....	Within 100 flight cycles or 3 months after the effective date of this AD, whichever occurs first.

**(i) Parts Installation Limitations**

As of the effective date of this AD, no person may install, on any airplane, a Teleflex cable having P/N 72830–20, unless the cable has accumulated fewer than 5,000 total flight cycles since its first installation on an airplane.

**(j) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1112; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or EADS CASA’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

**(k) Related Information**

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014–0262, dated December 5, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–8465.

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on July 6, 2016.

(i) Airbus Military Alert Operators Transmission AOT–CN235–76–0001, dated May 27, 2014.

(ii) Reserved.

(4) The following service information was approved for IBR on July 25, 2001 (66 FR 33014, June 20, 2001).

(i) CASA COM 235–140, Revision 01, dated March 21, 2000.

(ii) Reserved.

(5) For service information identified in this AD, contact EADS–CASA, Military Transport Aircraft Division (MTAD), Integrated Customer Services (ICS), Technical Services, Avenida de Aragón 404, 28022 Madrid, Spain; telephone +34 91 585 55 84; fax +34 91 585 55 05; email [MTA.TechnicalService@casa.eads.net](mailto:MTA.TechnicalService@casa.eads.net); Internet <http://www.eads.net>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 20, 2016.

**Victor Wicklund,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2016–12594 Filed 5–31–16; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 71**

**[Docket No. FAA–2016–0526; Airspace Docket No. 16–ASW–3]**

**Amendment of Class E Airspace; Taos, NM**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action modifies Class E airspace extending upward from 700 feet above the surface at Taos Regional Airport, Taos, NM. Decommissioning of non-directional radio beacon (NDB) and cancellation of the NDB approaches due to advances in Global Positioning System (GPS) capabilities have made this action necessary for the safety and management of Instrument Flight Rules (IFR) operations at Taos Regional Airport.

**DATES:** Effective 0901 UTC, January 5, 2017. The Director of the Federal Register approves this incorporation by reference action under Title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.9Z, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: 202–267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.9Z at NARA, call 202–741–6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**FOR FURTHER INFORMATION CONTACT:** Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222–5711.

**SUPPLEMENTARY INFORMATION:**

**Authority for This Rulemaking**

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator.

Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would amend Class E airspace at Taos Regional Airport, Taos, NM.

### History

On March 7, 2016, the FAA published in the **Federal Register** a notice of proposed rulemaking (NPRM) to modify Class E airspace extending upward from 700 feet above the surface at Taos Regional Airport, Taos, NM (81 FR 11695). Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. One comment was received from Mr. Robert Pigott, Aeronautical Information Services, requesting clarification of the overlapping 1,200 foot airspace to the west of Taos Regional Airport. This airspace existed prior to the proposed amendment and was not changed by the amendment. The 1,200 foot airspace exists to protect the departures and climb out requirements to the west due to high terrain east of the airport and allows departing aircraft to reach controlled airspace, and was developed in accordance with FAA Joint Order 7400.2K, Procedures for Handling Airspace Matters. The FAA found no reason to change the 1,200 foot airspace at this time.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9Z, dated August 6, 2015, and effective September 15, 2015, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

### Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, and effective September 15, 2015. FAA Order 7400.9Z is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.9Z lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

### The Rule

This amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 modifies Class E airspace extending upward from 700 feet above the surface at Taos Regional Airport, Taos, NM. After review, the FAA found that with the decommissioning of NDBs, removal of NDB approaches, and implementation of area navigation (RNAV) instrument approaches the extension to the northwest from the 6.5-mile radius to 9.4 miles of the Class E airspace extending upward from 700 feet above the surface was no longer required in accordance with airspace requirements specified in FAA Joint Order 7400.2K.

### Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5-6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

### Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

### Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

### PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for Part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

#### § 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, and effective September 15, 2015, is amended as follows:

*Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth*

\* \* \* \* \*

#### ASW NM E5 Taos, NM [Amended]

Taos Regional Airport, NM  
(Lat. 36°27'29" N., long. 105°40'21" W.)

That airspace extending upward from 700 feet above the surface within a 6.5-mile radius of Taos Regional Airport; and that airspace extending upward from 1,200 feet above the surface beginning at lat. 36°07'00" N., long. 105°47'42" W., thence via the 21.3-mile arc of Taos Regional Airport clockwise to lat. 36°48'00" N., long. 105°47'35" W., thence to lat. 36°30'00" N., long. 105°30'02" W., thence to the point of beginning.

Issued in Fort Worth, Texas, on May 18, 2016.

**Walter Tweedy,**

*Acting Manager, Operations Support Group,  
ATO Central Service Center.*

[FR Doc. 2016-12639 Filed 5-31-16; 8:45 am]

**BILLING CODE 4910-13-P**

### DEPARTMENT OF TRANSPORTATION

#### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2016-0525; Airspace Docket No. 16-AGL-1]

#### Amendment of Class E Airspace for the Following South Dakota Towns; Belle Fourche, SD; Madison, SD; Mobridge, SD; and Vermillion, SD

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action modifies Class E airspace extending upward from 700 feet above the surface at Belle Fourche Municipal Airport, Belle Fourche, SD; Madison Municipal Airport, Madison, SD; Mobridge Municipal Airport, Mobridge, SD; and Harold Davidson Field, Vermillion, SD. The