

(b) NHTSA stated in a 2005 FMVSS No. 101 rulemaking that the reason for including vehicles over 10,000 pounds GVWR in the application of the standard is that drivers of heavier vehicles need to see and identify their displays just like drivers of lighter vehicles. See 70 FR 48295, 48298 (Aug. 17, 2005). Drivers of commercial vehicles conduct pre-trip daily inspections. For vehicles with pneumatic brake systems, the in-cab air brake checks for warning light and buzzer, at 60 PSI, would familiarize the driver with the specific telltale displayed and audible warning in the event a low-air condition occurred during operation.

(c) There are two scenarios when a low brake air pressure condition could exist: a parked vehicle and a moving vehicle. In both conditions, the driver would be alerted to a low-air condition by the following means:

- Red contrasting color of the ISO brake malfunction telltale.
- Audible alert to the driver as long as the vehicle has low air.
- Dual indicator air pressure gauge for the primary and secondary air reservoirs clearly indicating the level of air pressure in the system.
- Red contrasting color on the air gauges indicating pressure below 60 PSI.

The functionality of both the parking brake system and the service brake system remains unaffected by using the ISO symbol for brake malfunction instead of “Brake Air” for the telltale in the subject vehicles.

(d) NHTSA Precedents—Autocar Industries notes that NHTSA has previously granted petitions for decisions of inconsequential noncompliance for similar brake telltale issues. See Docket No. NHTSA–2012–0004, 78 FR 69931 (November 21, 2013) (grant of petition for Ford Motor Company); Docket No. NHTSA–2014–0046, 79 FR 78559 (December 30, 2014) (grant of petition for Chrysler Group, LLC); and Docket No. NHTSA–2016–0103, 82 *Federal Register* 17084 (April 7, 2017) (grant of petition for Daimler Trucks North America). In all of these instances, the vehicles at issue did not have the exact requirements listed in FMVSS No. 101 table 2. The available warnings were deemed sufficient to provide the necessary driver warning. Autocar Industries respectfully suggests that the same is true for the subject vehicles: the red “BRAKE PRESSURE” telltale, the audible alert, and the contrasting colors on the air pressure gauges are fully sufficient to warn the driver of a low brake air pressure situation.

Autocar Industries concluded by expressing the belief that the subject noncompliance is inconsequential as it relates to motor vehicle safety, and that its petition to be exempted from providing notification of the noncompliance, as required by 49 U.S.C. 30118, and a remedy for the noncompliance, as required by 49 U.S.C. 30120, should be granted.

To view Autocar Industries’ petition analyses in its entirety you can visit <https://www.regulations.gov> by following the online instructions for accessing the dockets and by using the docket ID number for this petition shown in the heading of this notice.

NHTSA notes that the statutory provisions (49 U.S.C. 30118(d) and 30120(h)) that permit manufacturers to file petitions for a determination of inconsequentiality allow NHTSA to exempt manufacturers only from the duties found in sections 30118 and 30120, respectively, to notify owners, purchasers, and dealers of a defect or noncompliance and to remedy the defect or noncompliance. Therefore, any decision on this petition only applies to the subject vehicles that Autocar Industries no longer controlled at the time it determined that the noncompliance existed. However, any decision on this petition does not relieve vehicle distributors and dealers of the prohibitions on the sale, offer for sale, or introduction or delivery for introduction into interstate commerce of the noncompliant vehicles under their control after Autocar Industries notified them that the subject noncompliance existed.

Authority: 49 U.S.C. 30118, 30120; delegations of authority at 49 CFR 1.95 and 501.8.

Jeffrey M. Giuseppe,
Director, Office of Vehicle Safety Compliance.
[FR Doc. 2017–17330 Filed 8–15–17; 8:45 am]

BILLING CODE 4910–59–P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA–2017–0065]

Autocar, LLC, Receipt of Petition for Decision of Inconsequential Noncompliance

AGENCY: National Highway Traffic Safety Administration (NHTSA), Department of Transportation (DOT).

ACTION: Receipt of petition.

SUMMARY: Autocar, LLC (Autocar), has determined that certain model year

(MY) 2014–2018 Autocar Xpeditor trucks do not fully comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 101, *Controls and Displays*. Autocar filed a noncompliance report dated June 14, 2017, and subsequently petitioned NHTSA on June 19, 2017, for a decision that the subject noncompliance is inconsequential as it relates to motor vehicle safety.

DATES: The closing date for comments on the petition is September 15, 2017.

ADDRESSES: Interested persons are invited to submit written data, views, and arguments on this petition. Comments must refer to the docket and notice number cited in the title of this notice and submitted by any of the following methods:

- **Mail:** Send comments by mail addressed to U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** Deliver comments by hand to U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590. The Docket Section is open on weekdays from 10 a.m. to 5 p.m. except Federal Holidays.

- **Electronically:** Submit comments electronically by logging onto the Federal Docket Management System (FDMS) Web site at <https://www.regulations.gov/>. Follow the online instructions for submitting comments.

- Comments may also be faxed to (202) 493–2251.

Comments must be written in the English language, and be no greater than 15 pages in length, although there is no limit to the length of necessary attachments to the comments. If comments are submitted in hard copy form, please ensure that two copies are provided. If you wish to receive confirmation that comments you have submitted by mail were received, please enclose a stamped, self-addressed postcard with the comments. Note that all comments received will be posted without change to <https://www.regulations.gov>, including any personal information provided.

All comments and supporting materials received before the close of business on the closing date indicated above will be filed in the docket and will be considered. All comments and supporting materials received after the closing date will also be filed and will be considered to the fullest extent possible.

When the petition is granted or denied, notice of the decision will also

be published in the **Federal Register** pursuant to the authority indicated at the end of this notice.

All comments, background documentation, and supporting materials submitted to the docket may be viewed by anyone at the address and times given above. The documents may also be viewed on the Internet at <https://www.regulations.gov> by following the online instructions for accessing the dockets. The docket ID number for this petition is shown in the heading of this notice.

DOT's complete Privacy Act Statement is available for review in a **Federal Register** notice published on April 11, 2000, (65 FR 19477-78).

SUPPLEMENTARY INFORMATION:

I. Overview: Autocar, LLC (Autocar), has determined that certain MY 2014-2018 Autocar Xpeditor trucks do not fully comply with Table 2 of Federal Motor Vehicle Safety Standard (FMVSS) No. 101, *Controls and Displays*. Autocar filed a noncompliance report dated June

14, 2017, pursuant to CFR part 573, *Defect and Noncompliance Responsibility and Reports*, and petitioned NHTSA on June 19, 2017, pursuant to 49 U.S.C. 30118(d) and 30120(h) and 49 CFR part 556, for an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential as it relates to motor vehicle safety.

This notice of receipt of their petition is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of the petition.

II. Vehicles Involved: Approximately 5,545 MY 2014-2018 Autocar Xpeditor trucks, manufactured between September 3, 2013 and June 2, 2017, are potentially involved.

III. Noncompliance: Autocar explains that the noncompliance is that the Low Brake Air Pressure telltale for air brake system displays the word "BRAKE




PRESSURE" and the Canadian Motor Vehicle Safety Standard (CMVSS) 101 specified symbol, rather than the words "Brake Air," as specified in Table 2 of FMVSS No. 101. Autocar states that the telltale is accompanied by an audible alert and pressure gauges.

IV. Rule Text: Paragraph S5 of FMVSS No. 101 provides: "Each passenger car, multipurpose passenger vehicle, truck and bus that is fitted with a control, a telltale, or an indicator listed in Table 1 or Table 2 must meet the requirements of this standard for the location, identification, color, and illumination of that control, telltale or indicator."

Paragraph S5.2.1 of FMVSS No. 101 provides, in pertinent part: ". . . each control, telltale and indicator that is listed in column 1 of Table 1 or Table 2 must be identified by the symbol specified for it in column 2 or the word or abbreviation specified for it in column 3 of Table 1 or Table 2."

Table 2 appears as follows:

**Table 2
Identifiers for
Controls, Telltales and Indicators with
No Color or Illumination Requirements**

Column 1 ITEM	Column 2 SYMBOL	Column 3 WORD(S) OR ABBREVIATION
Hand Throttle Control	—	Throttle
Engine Start Control	—	Engine Start ₁
Manual Choke Control	—	Choke
Odometer	—	Kilometers or km, if kilometers are shown. Otherwise, no identifier is required. ₂
Horn		Horn
Master Lighting Switch		Lights
Headlamps and Taillamps Control	—	— _{4,5}
Low Brake Air Pressure Telltale (for vehicles subject to FMVSS 121)	—	Brake Air
Seat Belt Unfastened Telltale		Fasten Belts or Fasten Seat Belts

Notes:

- Use when engine control is separate from the key locking system.
- Any combination of upper- or lowercase letters may be used.
- Framed areas may be filled.
- If a line appears in Column 2 and Column 3, the Control, Telltale or Indicator is required to be identified, however the form of the identification is the manufacturer's option.
- Separate identification not required if function is combined with Master Lighting Switch.

V. Summary of Autocar's Petition: Autocar described the subject noncompliance and stated its belief that the noncompliance is inconsequential as it relates to motor vehicle safety.

In support of its petition, Autocar submitted the following reasoning:

(a) Autocar notes that the purpose of the low brake air pressure telltale is to alert the driver to a low air condition, consistent with the requirements of FMVSS No. 121, S5.1.5 (warning signal). The words "BRAKE PRESSURE" instead of "Brake Air," the CMVSS required symbol, and an audible alert that occurs in the subject vehicles would alert the driver to an air issue with the brake system. Once alerted, the driver can check the actual air pressure by reading the primary and secondary air gauges and seeing the contrasting color on the gauges indicating low pressure.

(b) NHTSA stated in a 2005 FMVSS No. 101 rulemaking that the reason for including vehicles over 10,000 pounds GVWR in the application of the standard is that drivers of heavier vehicles need to see and identify their displays just like drivers of lighter vehicles. See 70 FR 48295, 48298 (Aug. 17, 2005). Drivers of commercial vehicles conduct pre-trip daily inspections. For vehicles with pneumatic brake systems, the in-cab air brake checks for warning light and buzzer, at 60 PSI, would familiarize the driver with the specific telltale displayed and audible warning in the event a low-air condition occurred during operation.

(c) There are two scenarios when a low brake air pressure condition could exist: A parked vehicle and a moving vehicle. In both conditions, the driver would be alerted to a low-air condition by the following means:

- Red contrasting color of the telltale indicating "BRAKE PRESSURE"
- Audible alert to the driver as long as the vehicle has low air
- Air pressure gauges for the primary and secondary air reservoirs clearly indicating the level of air pressure in the system
- Red contrasting color on the air gauges indicating pressure below 60 PSI

The functionality of both the parking brake system and the service brake system remains unaffected by using "BRAKE PRESSURE" instead of "Brake Air" for the telltale in the subject vehicles.

(d) NHTSA Precedents—Autocar notes that NHTSA has previously granted petitions for decisions of inconsequential noncompliance for

similar brake telltale issues. See Docket No. NHTSA–2012–0004, 78 FR 69931 (November 21, 2013) (grant of petition for Ford Motor Company); Docket No. NHTSA–2014–0046, 79 FR 78559 (December 30, 2014) (grant of petition for Chrysler Group, LLC); and Docket No. NHTSA–2016–0103, 82 **Federal Register** 17084 (April 7, 2017) (grant of petition for Daimler Trucks North America). In all of these instances, the vehicles at issue did not have the exact requirements listed in FMVSS No. 101 table 2. The available warnings were deemed sufficient to provide the necessary driver warning. Autocar respectfully suggests that the same is true for the subject vehicles: the red "BRAKE PRESSURE" telltale, the audible alert, and the contrasting colors on the air pressure gauges are fully sufficient to warn the driver of a low brake air pressure situation.

Autocar concluded by expressing the belief that the subject noncompliance is inconsequential as it relates to motor vehicle safety, and that its petition to be exempted from providing notification of the noncompliance, as required by 49 U.S.C. 30118, and a remedy for the noncompliance, as required by 49 U.S.C. 30120, should be granted.

To view Autocar's petition analyses in its entirety you can visit <https://www.regulations.gov> by following the online instructions for accessing the dockets and by using the docket ID number for this petition shown in the heading of this notice.

NHTSA notes that the statutory provisions (49 U.S.C. 30118(d) and 30120(h)) that permit manufacturers to file petitions for a determination of inconsequentiality allow NHTSA to exempt manufacturers only from the duties found in sections 30118 and 30120, respectively, to notify owners, purchasers, and dealers of a defect or noncompliance and to remedy the defect or noncompliance. Therefore, any decision on this petition only applies to the subject vehicles that Autocar no longer controlled at the time it determined that the noncompliance existed. However, any decision on this petition does not relieve vehicle distributors and dealers of the prohibitions on the sale, offer for sale, or introduction or delivery for introduction into interstate commerce of the noncompliant vehicles under their control after Autocar notified them that the subject noncompliance existed.

Authority: 49 U.S.C. 30118, 30120; delegations of authority at 49 CFR 1.95 and 501.8.

Jeffrey M. Giuseppe,

Director, Office of Vehicle Safety Compliance.

[FR Doc. 2017–17331 Filed 8–15–17; 8:45 am]

BILLING CODE 4910–59–P

DEPARTMENT OF VETERANS AFFAIRS

Advisory Committee: VA National Academic Affiliations Council Notice of Meeting

The Department of Veterans Affairs (VA) gives notice under the Federal Advisory Committee Act that the VA National Academic Affiliations Council (NAAC) will meet via conference call on September 12, 2017, from 11:00 a.m. to 1:00 p.m. EST. The meeting is open to the public.

The purpose of the Council is to advise the Secretary on matters affecting partnerships between VA and its academic affiliates.

On September 12, 2017, the Council will explore current regulatory proposals to limit the duration of administrative leave available to Federal employees and the possible impact on VA's educational mission; discuss the prohibition on VA employees engaging in teaching activities with for-profit educational institutions; prioritize previous Council recommendations for renewed policy focus; and receive updates on: VA's graduate medical education expansion initiative, the NAAC's Diversity and Inclusion Subcommittee, and VA's August 2017 Health Professions Education Summit in Iron Mountain, MI. The Council will receive public comments from 12:45 p.m. to 1:00 p.m. EST.

Interested persons may attend and/or present oral statements to the Council. The dial in number to attend the conference call is: 1–800–767–1750. At the prompt, enter access code 45206 then press #. Individuals seeking to present oral statements are invited to submit a 1–2 page summary of their comments at the time of the meeting for inclusion in the official meeting record. Oral presentations will be limited to five minutes or less, depending on the number of participants. Additionally, interested parties may also provide written comments for review by the Council prior to the meeting or at any time, via email to Steve.Trynosky@va.gov, or by mail to Stephen K. Trynosky J.D., M.P.H., M.M.A.S., Designated Federal Officer, Office of Academic Affiliations (10A2D), 810 Vermont Avenue NW., Washington, DC