

**(c) Applicability**

This AD applies to the Bombardier, Inc., airplanes identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category.

(1) Bombardier, Inc., Model CL-600-2A12 (CL-601) airplanes, having serial numbers (S/Ns) 3001 through 3066 inclusive.

(2) Bombardier, Inc., Model CL-600-2B16 (CL-601-3A and CL-601-3R Variants) airplanes, having S/Ns 5001 through 5194 inclusive.

(3) Bombardier, Inc., Model CL-600-2B16 (CL-604 Variant) airplanes having S/Ns 5301 through 5665 inclusive, and S/Ns 5701 through 5990 inclusive.

**(d) Subject**

Air Transport Association (ATA) of America Code 05, Periodic inspections.

**(e) Reason**

This AD was prompted by a determination that the bushing holes on the engine mount rib may not conform to the engineering drawings and that certain inspections of the engine mount rib must be included in the airworthiness limitations section (ALS) of the Instructions for Continued Airworthiness (ICA). We are issuing this AD to detect and correct failure of an engine mount rib. Failure of an engine mount rib could compromise the structural integrity of the engine mount and could lead to subsequent detachment of an engine.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Maintenance or Inspection Program Revision**

Within 60 days after the effective date of this AD: Revise the maintenance or inspection program, as applicable, to incorporate inspections for fatigue cracking of the engine mount rib and corrective actions, as applicable, in accordance with a method approved by the Manager, New York ACO Branch, FAA.

Note 1 to paragraph (g) of this AD: Guidance can be found in Tasks 54-10-00-106 and 54-50-00-103 of Chapter 5 of the Bombardier Time Limits/Maintenance Checks (TLMC) Manual PSP 601-5 (for Model CL-600-2A12 (CL-601 Variant) airplanes); Bombardier TLMC Manual PSP 601A-5 (for CL-600-2B16 (CL-601-3A and CL-601-3R Variants) airplanes); Bombardier TLMC Manual CL-604 (for Model CL-600-2B16 (CL-604 Variant) airplanes, S/Ns 5301 through 5665 inclusive); and Bombardier TLMC Manual CL-605 (for Model CL-600-2B16 (CL-604 Variant) airplanes, S/Ns 5701 through 5990).

**(h) No Alternative Actions and/or Intervals**

After the maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) and/or intervals may be used, unless the actions and/or intervals are approved as an AMOC in accordance with the procedures specified in paragraph (i)(1) of this AD.

**(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

**(j) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2015-09R1, dated June 29, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0338.

(2) For more information about this AD, contact Aziz Ahmed, Aerospace Engineer, Airframe and Mechanical Systems Section, New York Aircraft ACO Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7329; fax 516-794-5531.

**(k) Material Incorporated by Reference**

None.

Issued in Renton, Washington, on November 7, 2017.

**Dionne Palermo,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2017-24737 Filed 11-17-17; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2017-0649; Airspace Docket No. 17-ASW-11]

**Establishment of Class E Airspace; Boothville, LA**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action establishes Class E airspace extending upward from 700 feet above the surface at Boothville Heliport, Boothville, LA. Controlled airspace is necessary to accommodate new special instrument approach procedures developed at Boothville Heliport, for the safety and management of instrument flight rules (IFR) operations at the heliport.

**DATES:** Effective 0901 UTC, February 1, 2018. The Director of the Federal Register approves this incorporation by reference action under Title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11B, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11B at NARA, call (202) 741-6030, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**FOR FURTHER INFORMATION CONTACT:** Walter Tweedy, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5900.

**SUPPLEMENTARY INFORMATION:****Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the

authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes Class E airspace extending upward from 700 feet above the surface at Boothville Heliport, Boothville, LA in support of IFR operations at the heliport.

#### History

The FAA published in the **Federal Register** (82 FR 36105, August 3, 2017), Docket No. FAA-2017-0649 a notice of proposed rulemaking to establish Class E airspace extending upward from 700 feet above the surface at Boothville Heliport, Boothville, LA. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

#### Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.11B, Airspace Designations and Reporting Points, dated August 3, 2017, and effective September 15, 2017. FAA Order 7400.11B is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11B lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

#### The Rule

This amendment to Title 14 Code of Federal Regulations (14 CFR) part 71 establishes Class E airspace extending upward from 700 feet above the surface within a 6.4-mile radius of Boothville Heliport, Boothville, LA, to accommodate new special instrument approach procedures. Controlled airspace is needed for the safety and management of IFR operations at the airport.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.11B, dated August 3, 2017, and effective September 15, 2017, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

#### Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established

body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5-6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

#### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

#### Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

#### **PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS**

■ 1. The authority citation for 14 CFR part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

##### **§ 71.1 [Amended]**

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.11B, Airspace Designations and Reporting Points, dated August 3, 2017, and effective September 15, 2017, is amended as follows:

*Paragraph 6005 Class E Airspace Areas Extending Upward from 700 feet or More Above the Surface of the Earth.*

\* \* \* \* \*

#### **ASW LA E5 Boothville, LA [New]**

Boothville Heliport, LA (Lat. 29°21'15" N., long. 89°26'09" W.)

That airspace extending upward from 700 feet above the surface within a 6.4-mile radius of Boothville Heliport.

Issued in Fort Worth, Texas on November 9, 2017.

#### **Wayne Eckenrode,**

*Acting Manager, Operations Support Group, ATO Central Service Center.*

[FR Doc. 2017-24868 Filed 11-17-17; 8:45 am]

**BILLING CODE 4910-13-P**

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 97**

[Docket No. 31163; Amdt. No. 3773]

#### **Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This rule establishes, amends, suspends, or removes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures (ODPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective November 20, 2017. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of November 20, 2017.

**ADDRESSES:** Availability of matters incorporated by reference in the amendment is as follows:

#### **For Examination**

1. U.S. Department of Transportation, Docket Ops-M30, 1200 New Jersey Avenue SE., West Bldg., Ground Floor, Washington, DC 20590-0001.