

heads; an inspection of the fastener holes revealed that cracks were found in the skin on two airplanes. We are issuing this AD to detect and correct cracking in the wing upper skin and forward drag fittings, which could lead to a compromised upper link and reduced structural integrity of the engine strut.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

Except as required by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 757-57A0073 RB, dated July 14, 2017, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757-57A0073 RB, dated July 14, 2017.

**Note 1 to paragraph (g) of this AD:** Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 757-57A0073, dated July 14, 2017, which is referred to in Boeing Alert Requirements Bulletin 757-57A0073 RB, dated July 14, 2017.

#### (h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Requirements Bulletin 757-57A0073 RB, dated July 14, 2017, uses the phrase "the original issue date of the requirements bulletin," this AD requires using "the effective date of this AD."

(2) Where Boeing Alert Requirements Bulletin 757-57A0073 RB, dated July 14, 2017, specifies contacting Boeing, this AD requires repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(3) Where Boeing Alert Requirements Bulletin 757-57A0073 RB, dated July 14, 2017, specifies a dye-penetrant inspection for cracks in the fillet between head and shank on the removed fasteners," this AD allows a detailed inspection for cracks in the fillet between head and shank on the removed fasteners, as an optional method of compliance with the dye-penetrant inspection.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: [9-ANM-LAACO-AMOC-Requests@faa.gov](mailto:9-ANM-LAACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

#### (j) Related Information

(1) For more information about this AD, contact Chandra Ramdoss, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5239; fax: 562-627-5210; email: [chandraduth.ramdoss@faa.gov](mailto:chandraduth.ramdoss@faa.gov).

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 757-57A0073 RB, dated July 14, 2017.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 24, 2018.

**James Cashdollar,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018-16499 Filed 8-3-18; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2018-0137; Airspace Docket No. 18-ACE-2]

RIN-2120-AA66

#### Amendment and Establishment of Class E Airspace; Columbus, NE

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action modifies Class E airspace designated as a surface area and makes the airspace full-time and removes the airspace part-time status and language from the airspace legal description, amends Class E airspace extending upward from 700 feet above the surface, and establishes Class E airspace designated as an extension to the Class E surface area at Columbus Municipal Airport, Columbus, NE. This action is at the request of Minneapolis Air Route Traffic Control Center (ARTCC) and the result of an FAA airspace review. Additionally, the geographic coordinates of the airport are updated to coincide with the FAA's aeronautical database. This action is necessary for the safety and management of instrument flight rules (IFR) operations at this airport.

**DATES:** Effective 0901 UTC, November 8, 2018. The Director of the Federal Register approves this incorporation by reference action under Title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11B, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11B at NARA, call (202) 741-6030, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**FOR FURTHER INFORMATION CONTACT:** Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5711.

**SUPPLEMENTARY INFORMATION:**

**Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends Class E airspace designated as a surface area, amends Class E airspace extending upward from 700 feet above the surface, and establishes Class E airspace designated as an extension to the Class E surface area at Columbus Municipal Airport, Columbus, NE to support IFR operations at the airport.

**History**

The FAA published a notice of proposed rulemaking (NPRM) in the *Federal Register* (83 FR 13438; March 29, 2018) for Docket No. FAA-2018-0137 to amend Class E airspace designated as a surface area and make the airspace full-time and remove the airspace part-time status and language from the airspace legal description, amend Class E airspace extending upward from 700 feet above the surface, and establish Class E airspace designated as an extension to the Class E surface area at Columbus Municipal Airport, Columbus, NE. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Subsequent to publication, the FAA discovered the following typographical errors: In the Class E airspace designated as a surface area airspace legal description, the airspace radius should be 4.2 vice 4.7; and the geographic coordinates for Columbus Municipal Airport in the classes of airspace shown should be (lat. 41°26'55" N, long. 97°20'27" W) vice (lat. 41°26'55" N, long. 97°20'34" W). These errors are corrected with this action.

Class E airspace designations are published in paragraph 6002, 6004, and

6005, respectively, of FAA Order 7400.11B, dated August 3, 2017, and effective September 15, 2017, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

**Availability and Summary of Documents for Incorporation by Reference**

This document amends FAA Order 7400.11B, Airspace Designations and Reporting Points, dated August 3, 2017, and effective September 15, 2017. FAA Order 7400.11B is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11B lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

**The Rule**

The FAA amends Title 14, Code of Federal Regulations (14 CFR) part 71 by: Amending the Class E airspace designated as a surface area to within a 4.2-mile radius (reduced from a 4.7-mile radius) at Columbus Municipal Airport, Columbus, NE; removing the Columbus VOR/DME and the extensions to the southeast and northwest of the airport as they are no longer needed to define this boundary; making the airspace full-time and removing the part-time status and language from the airspace legal description; and updating the geographic coordinates of the airport to coincide with the FAA's aeronautical database;

Establishing Class E airspace designated as an extension to the Class E surface area at Columbus Municipal Airport within 2.4 miles each side of the Columbus VOR/DME 150° radial from the 4.2-mile radius of the airport to 7.0 miles southeast of the airport, and within 2.4 miles each side of the Columbus VOR/DME 309° radial from the 4.2-mile radius of the airport to 7.7 miles northwest of the airport; and

Amending Class E airspace extending upward from 700 feet above the surface to within a 6.7-mile radius (reduced from a 7.7-mile radius) of Columbus Municipal Airport; removing the Columbus Municipal ILS Localizer, Platte Center NDB, and the associated northwest extension; amending the extension to the southeast to within 2.4 miles (increased from 1.6 miles) each side of the Columbus VOR/DME 150° (previously 157°) radial from the 6.7-mile radius to 7.0 miles (decreased from 11 miles) southeast of the airport; adding an extension 2.4 miles each side of the Columbus VOR/DME 309° radial extending from the 6.7-mile radius to 7.7 miles northeast of the airport; and

updating the geographic coordinates of the airport to coincide with the FAA's aeronautical database.

The NPRM incorrectly stated the geographic coordinates of the airport noted in the classes of airspace and are corrected in this rule to (lat. 41°26'55" N, long. 97°20'27" W).

Airspace reconfiguration is necessary due to a request from Minneapolis ARTCC, to bring the airspace into compliance with FAA Order 7400.2L, Procedures for Handling Airspace, and to support the safety and management of IFR operations at the airport.

**Regulatory Notices and Analyses**

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**Environmental Review**

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5-6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

**Lists of Subjects in 14 CFR Part 71**

Airspace, Incorporation by reference, Navigation (air).

**Adoption of the Amendment**

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

**PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS**

■ 1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

**§ 71.1 [Amended]**

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.11B, Airspace Designations and Reporting Points, dated August 3, 2017, and effective September 15, 2017, is amended as follows:

*Paragraph 6002 Class E Airspace Areas Designated as Surface Areas.*

\* \* \* \* \*

**ACE NE E2 Columbus, NE [Amended]**

Columbus Municipal Airport, NE  
(Lat. 41°26'55" N, long. 97°20'27" W)

Within a 4.2 mile radius of Columbus Municipal Airport.

*Paragraph 6004 Class E Airspace Areas Designated as an Extension to a Class D or Class E Surface Area.*

\* \* \* \* \*

**ACE MO E4 Columbus, NE [New]**

Columbus Municipal Airport, NE  
(Lat. 41°26'55" N, long. 97°20'27" W)

Columbus VOR/DME  
(Lat. 41°27'00" N, long. 97°20'27" W)

That airspace extending upward from the surface within 2.4 miles each side of the Columbus VOR/DME 150° radial extending from the 4.2-mile radius of Columbus Municipal Airport to 7.0 miles southeast of the airport, and within 2.4 miles each side of the Columbus VOR/DME 309° radial extending from the 4.2-mile radius of Columbus Municipal Airport to 7.7 miles northwest of the airport.

*Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.*

\* \* \* \* \*

**ACE NE E5 Columbus, NE [Amended]**

Columbus Municipal Airport, NE  
(Lat. 41°26'55" N, long. 97°20'27" W)

Columbus VOR/DME  
(Lat. 41°27'00" N, long. 97°20'27" W)

That airspace extending upward from 700 feet above the surface within a 6.7-mile radius of Columbus Municipal Airport and within 2.4 miles each side of the Columbus VOR/DME 150° radial extending from the 6.7-mile radius to 7.0 miles southeast of the airport and within 2.4 miles each side of the Columbus VOR/DME 309° radial extending from the 6.7-mile radius to 7.7 miles northwest of the airport.

Issued in Fort Worth, Texas, on July 17, 2018.

Walter Tweedy,

*Acting Manager, Operations Support Group,  
ATO Central Service Center.*

[FR Doc. 2018–16679 Filed 8–3–18; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF HOMELAND SECURITY**

**Coast Guard**

**33 CFR Part 165**

**[Docket Number USCG–2018–0615]**

**RIN 1625–AA00**

**Safety Zone; Fireworks Display, Little Egg Harbor, Long Beach, NJ**

**AGENCY:** Coast Guard, DHS.

**ACTION:** Temporary final rule.

**SUMMARY:** The Coast Guard is establishing a temporary safety zone on the waters of Little Egg Harbor off Long Beach, NJ, from 8:30 p.m. through 9:30 p.m. on August 7, 2018, during the Long Beach National Night Out Fireworks Display. The safety zone is necessary to ensure the safety of participant vessels, spectators, and the boating public during the event. This regulation prohibits persons and non-participant vessels from entering, transiting through, anchoring in, or remaining within the safety zone unless authorized by the Captain of the Port (COTP) Delaware Bay or a designated representative.

**DATES:** This rule is effective from 8:30 p.m. through 9:30 p.m. on August 7, 2018.

**ADDRESSES:** To view documents mentioned in this preamble as being available in the docket, go to <http://www.regulations.gov>, type USCG–2018–0615 in the “SEARCH” box and click “SEARCH.” Click on Open Docket Folder on the line associated with this rule.

**FOR FURTHER INFORMATION CONTACT:** If you have questions on this rule, call or email MST1 Edmund Ofalt, U.S. Coast Guard, Sector Delaware Bay, Waterways Management Division; telephone (215) 271–4814, email [Edmund.J.Ofalt@uscg.mil](mailto:Edmund.J.Ofalt@uscg.mil).

**SUPPLEMENTARY INFORMATION:**

**I. Table of Abbreviations**

CFR Code of Federal Regulations  
DHS Department of Homeland Security  
FR Federal Register  
NPRM Notice of proposed rulemaking  
§ Section

U.S.C. United States Code

**II. Background Information and Regulatory History**

The Coast Guard is issuing this temporary rule without prior notice and opportunity to comment pursuant to authority under section 4(a) of the Administrative Procedure Act (APA) (5 U.S.C. 553(b)). This provision authorizes an agency to issue a rule without prior notice and opportunity to comment when the agency for good cause finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under 5 U.S.C. 553(b)(B), the Coast Guard finds that good cause exists for not publishing a notice of proposed rulemaking (NPRM) with respect to this rule because it is impracticable and contrary to the public interest to do so. There is insufficient time to allow for a reasonable comment period prior to the date of the event. The rule must be in force by August 7, 2018, to serve its purpose of ensuring the safety of spectators and the general public from hazards associated with the fireworks display. Hazards include accidental discharge of fireworks, dangerous projectiles, and falling hot embers or other debris.

Under 5 U.S.C. 553(d)(3), the Coast Guard finds that good cause exists for making this rule effective less than 30 days after publication in the **Federal Register**. Delaying the effective date of this rule would be impracticable and contrary to the public interest because immediate action is needed to mitigate the potential safety hazards associated with a fireworks display in this location.

**III. Legal Authority and Need for Rule**

The Coast Guard is issuing this rule under authority in 33 U.S.C. 1231. The Captain of the Port Delaware Bay (COTP) has determined that potential hazards associated with the fireworks display on August 7, 2018, will be a safety concern for anyone within a 200-yard radius of the fireworks barge, which will be anchored in approximate position 39°37'08.34" N, 074°12'25.60" W. This rule is needed to protect persons, vessels and the public within the safety zone during the fireworks display.

**IV. Discussion of the Rule**

This rule establishes a temporary safety zone from 8:30 p.m. to 9:30 p.m. on August 7, 2018, on the waters of Little Egg Harbor off Long Beach, NJ, during a fireworks display from a barge. The event is scheduled to take place at 8:45 p.m. on August 7, 2018. The safety zone will extend 200 yards around the barge, which will be anchored at