

part to Boeing within 30 days after the effective date of this AD.

(4) Where "CONDITION 5" of Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019, uses the phrase "suspect lot number cannot be determined," or "suspect lot number that cannot be determined," this AD requires using, "lot number cannot be determined," or "lot number that cannot be determined;" respectively.

(5) Where flag note (a) of Figure 5, Figure 6, Figure 7, and Figure 8, of Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019, specifies "Only required if the main slat track assembly has a suspect lot number," this AD requires using, "Only required if the main slat track assembly has a suspect lot number or a lot number that cannot be determined."

#### (i) Paperwork Reduction Act Burden Statement

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

#### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

#### (k) Related Information

For more information about this AD, contact Greg Rutar, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3529; email: [Greg.Rutar@faa.gov](mailto:Greg.Rutar@faa.gov).

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on June 5, 2019.

**Michael Kaszycki,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019-12221 Filed 6-7-19; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2018-1073; Airspace Docket No. 18-AEA-17]

RIN 2120-AA66

#### Amendment of VOR Federal Airways V-8, V-92, V-214, and V-438 in the Vicinity of Grantsville, MD

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action modifies VHF Omnidirectional Range (VOR) Federal airways V-8, V-92, V-214, and V-438 due to the planned decommissioning of the Grantsville, MD, VOR/DME navigation aid which provides

navigation guidance for segments of the routes. The Grantsville VOR/DME is being decommissioned as part of the FAA's VOR Minimum Operational Network (MON) program.

**DATES:** Effective date 0901 UTC, August 15, 2019. The Director of the Federal Register approves this incorporation by reference action under Title 1 Code of Federal Regulations part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11C, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11C at NARA, call (202) 741-6030, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**FOR FURTHER INFORMATION CONTACT:** Paul Gallant, Airspace Policy Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

#### SUPPLEMENTARY INFORMATION:

##### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it modifies the National Airspace System as necessary to preserve the safe and efficient flow of air traffic.

##### History

The FAA published a notice of proposed rulemaking for Docket No.

FAA–2018–1073 in the **Federal Register** (84 FR 3730; February 13, 2019), amending VOR Federal airways V–8, V–92, V–214, and V–438 due to planned decommissioning of the Grantsville, MD, VOR/DME navigation aid.

Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal. No comments were received.

VOR Federal airways are published in paragraph 6010(a) of FAA Order 7400.11C dated August 13, 2018, and effective September 15, 2018, which is incorporated by reference in 14 CFR 71.1. The VOR Federal airways listed in this document will be subsequently published in the Order.

#### Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.11C, Airspace Designations and Reporting Points, dated August 13, 2018, and effective September 15, 2018. FAA Order 7400.11C is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11C lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

#### The Rule

The FAA is amending Title 14 Code of Federal Regulations (14 CFR) part 71 by amending the descriptions of VOR Federal airways V–8, V–92, V–214, and V–438, due to the planned decommissioning of the Grantsville, MD, VOR/DME. The VOR Federal airway changes are outlined below.

**V–8:** V–8 currently consists of two sections with a gap in between. The first section extends between the intersection of radials from the Seal Beach, CA, VORTAC, and the Ventura, CA, VOR/DME (*i.e.*, the charted DOYLE, CA, fix), and the Flag City, OH, VORTAC. The second section extends between the Briggs, OH, VOR/DME, and the Washington, DC, VOR/DME. The FAA is removing the airway segments that extend between the Briggs, OH, VOR/DME, and the Martinsburg, WV, VORTAC. As amended, that portion of V–8 between the DOYLE, CA, fix, and the Flag City, OH, VORTAC remains unchanged. The second section of the airway extends between the Martinsburg, WV, VORTAC and the Washington, DC, VOR/DME.

**V–92:** V–92 currently consists of two sections. The first section extends between the Chicago Heights, IL, VORTAC and the Goshen, IN, VORTAC. The second section extends between the Newcomerstown, OH, VOR/DME and the Armel, VA, VOR/DME. This action

removes the airway segments between the Bellaire, OH, VOR/DME and the Armel, VA, VOR/DME. As amended, V–92 extends between Chicago Heights, IL, and Goshen, IN; and between Newcomerstown, OH and Bellaire, OH.

**V–214:** V–214 currently extends, in two sections, between the Kokomo, IN, VORTAC and the Muncie, IN, VOR/DME; and between the intersection of radials from the Appleton, OH, VORTAC and the Zanesville, OH, VOR/DME (*i.e.*, the charted GLOOM, OH, fix) and the Teterboro, NJ, VOR/DME. This action removes the segments between the Bellaire, OH, VOR/DME and the Martinsburg, WV, VORTAC. As amended, V–214 consists of three separate sections:

The first section extends between Kokomo, IN and Goshen, IN (no change from current configuration). The second section extends between the intersection of radials from the Appleton, OH, VORTAC and the Zanesville, OH, VOR/DME, and the Bellaire, OH, VOR/DME. The third section extends between the Martinsburg, WV, VORTAC and the Teterboro, NJ, VOR/DME.

**V–438:** V–438 currently extends between the Grantsville, MD, VOR/DME and the intersection of radials from the Hagerstown, MD, VOR, and the Martinsburg, WV, VORTAC (*i.e.*, the charted LUCKE, VA, fix). This action removes the airway segment between the Grantsville, MD, VOR/DME and the Hagerstown, MD, VOR. The amended V–438 extends between the Hagerstown, MD, VOR, and the LUCKE, VA, fix.

#### Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### Environmental Review

The FAA has determined that this action of modifying VOR Federal airways V–8, V–92, V–214, and V–438

due to the planned decommissioning of the Grantsville, MD VOR/DME, qualifies for categorical exclusion under the National Environmental Policy Act and its implementing regulations at 40 CFR part 1500, and in accordance with FAA Order 1050.1F, Environmental Impacts: Policies and Procedures, paragraph 5–6.5a, which categorically excludes from further environmental impact review rulemaking actions that designate or modify classes of airspace areas, airways, routes, and reporting points (see 14 CFR part 71, Designation of Class A, B, C, D, and E Airspace Areas; Air Traffic Service Routes; and Reporting Points). As such, this action is not expected to result in any potentially significant environmental impacts. In accordance with FAA Order 1050.1F, paragraph 5–2 regarding Extraordinary Circumstances, the FAA has reviewed this action for factors and circumstances in which a normally categorically excluded action may have a significant environmental impact requiring further analysis. The FAA has determined that no extraordinary circumstances exist that warrant preparation of an environmental assessment or environmental impact study.

#### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

#### Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

#### **PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS**

■ 1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

#### **§ 71.1 [Amended]**

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.11C, Airspace Designations and Reporting Points, dated August 13, 2018, and effective September 15, 2018, is amended as follows:

*Paragraph 6010(a) Domestic VOR Federal Airways.*

\* \* \* \* \*

#### **V–8 [Amended]**

From INT Seal Beach, CA, 266° and Ventura, CA, 144° radials; Seal Beach; Paradise, CA; 35 miles, 7 miles wide (3 miles SE and 4 miles NW of centerline) Hector, CA;

Goffs, CA; INT Goffs 033° and Morman Mesa, NV, 196° radials; Morman Mesa; Bryce Canyon, UT; Hanksville, UT; Grand Junction, CO; Rifle, CO; Kremmling, CO; Mile High, CO; Akron, CO; Hayes Center, NE; Grand Island, NE; Omaha, NE; Des Moines, IA; Iowa City, IA; Moline, IL; Joliet, IL; Chicago Heights, IL; Goshen, IN; to Flag City, OH. From Martinsburg, WV; to Washington, DC. The portion outside the United States has no upper limit.

#### V-92 [Amended]

From Chicago Heights, IL; to Goshen, IN. From Newcomerstown, OH; to Bellaire, OH.

#### V-214 [Amended]

From Kokomo IN, Marion, IN; to Muncie, IN. From INT Appleton, OH, 236° and Zanesville, OH, 274° radials; Zanesville; to Bellaire, OH. From Martinsburg, WV; INT Martinsburg 094° and Baltimore, MD, 300° radials; Baltimore; INT Baltimore 093° and Dupont, DE, 223° radials; Dupont; Yardley, PA; to Teterboro, NJ.

#### V-438 [Amended]

From Hagerstown, MD, to the INT of Hagerstown 157° and the Martinsburg, WV, 130° radials.

\* \* \* \* \*

Issued in Washington, DC, on June 3, 2019.

#### Gemechu Gelgelu,

*Acting Manager, Airspace Policy Group.*

[FR Doc. 2019-12036 Filed 6-7-19; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 97

[Docket No. 31254; Amdt. No. 3854]

#### Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This rule amends, suspends, or removes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide for the safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective June 10, 2019. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of June 10, 2019.

**ADDRESSES:** Availability of matter incorporated by reference in the amendment is as follows:

#### For Examination

1. U.S. Department of Transportation, Docket Ops-M30, 1200 New Jersey Avenue SE, West Bldg., Ground Floor, Washington, DC 20590-0001;

2. The FAA Air Traffic Organization Service Area in which the affected airport is located;

3. The office of Aeronautical Navigation Products, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

#### Availability

All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit the National Flight Data Center online at [nfdc.faa.gov](http://nfdc.faa.gov) to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from the FAA Air Traffic Organization Service Area in which the affected airport is located.

#### FOR FURTHER INFORMATION CONTACT:

Thomas J. Nichols, Flight Procedures and Airspace Group, Flight Technologies and Procedures Division, Flight Standards Service, Federal Aviation Administration. Mailing Address: FAA Mike Monroney Aeronautical Center, Flight Procedures and Airspace Group, 6500 South MacArthur Blvd., Registry Bldg. 29, Room 104, Oklahoma City, OK 73125. Telephone: (405) 954-4164.

**SUPPLEMENTARY INFORMATION:** This rule amends Title 14, Code of Federal Regulations, Part 97 (14 CFR part 97) by amending the referenced SIAPs. The complete regulatory description of each SIAP is listed on the appropriate FAA Form 8260, as modified by the National Flight Data Center (NFDC)/Permanent Notice to Airmen (P-NOTAM), and is incorporated by reference under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR 97.20. The large number of SIAPs,

their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained on FAA form documents is unnecessary.

This amendment provides the affected CFR sections, and specifies the SIAPs and Takeoff Minimums and ODPs with their applicable effective dates. This amendment also identifies the airport and its location, the procedure and the amendment number.

#### Availability and Summary of Material Incorporated by Reference

The material incorporated by reference is publicly available as listed in the **ADDRESSES** section.

The material incorporated by reference describes SIAPs, Takeoff Minimums and ODPs as identified in the amendatory language for part 97 of this final rule.

#### The Rule

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP and Takeoff Minimums and ODP as amended in the transmittal. For safety and timeliness of change considerations, this amendment incorporates only specific changes contained for each SIAP and Takeoff Minimums and ODP as modified by FDC permanent NOTAMs.

The SIAPs and Takeoff Minimums and ODPs, as modified by FDC permanent NOTAM, and contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these changes to SIAPs and Takeoff Minimums and ODPs, the TERPS criteria were applied only to specific conditions existing at the affected airports. All SIAP amendments in this rule have been previously issued by the FAA in a FDC NOTAM as an emergency action of immediate flight safety relating directly to published aeronautical charts.

The circumstances that created the need for these SIAP and Takeoff Minimums and ODP amendments require making them effective in less than 30 days.

Because of the close and immediate relationship between these SIAPs, Takeoff Minimums and ODPs, and safety in air commerce, I find that notice and public procedure under 5 U.S.C.