

(i) Parts Prohibition

As of the effective date of this AD, do not install an MR damper rod end P/N M006–01H004–041, M006–01H004–045, or M006–01H004–053 on any helicopter, unless it is marked with a black dot indicating that it has passed inspections specified by Leonardo Helicopters BT 139–450.

(j) No Reporting Requirement

Although the service information referenced in EASA AD 2018–0112R1 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For more information about this AD, contact Matt Fuller, AD Program Manager, General Aviation & Rotorcraft Unit, Airworthiness Products Section, Operational Safety Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222–5110; email matthew.fuller@faa.gov.

(2) Leonardo Helicopters Alert Service Bulletin No. 139–450, Revision D, dated May 28, 2019, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39–0331–225074; fax +39–0331–229046; or at <https://customerportal.leonardocompany.com/en-US/>. You may view this referenced service information at the contact information specified in paragraph (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD 2018–0112R1, dated June 4, 2018.

(ii) [Reserved]

(3) For EASA AD 2018–0112R1, contact EASA, Konrad-Adenauer-Ufer 3, 50668

Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0283.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 8, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–26973 Filed 12–13–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF HOMELAND SECURITY**Coast Guard****33 CFR Part 165**

[Docket Number USCG–2021–0911]

RIN 1625–AA11

Safety Zone; Oil Pipeline Repairs; San Pedro Bay, CA

AGENCY: Coast Guard, Department of Homeland Security (DHS).

ACTION: Temporary final rule.

SUMMARY: The Coast Guard is establishing a temporary safety zone for the oil pipeline repair operations in the vicinity of a damaged pipeline, off the coast of Orange County and near San Pedro Bay, CA. The safety zone is necessary to reduce significant hazards to vessels, the harbor, and the public during ongoing pipeline repair and oil recovery operations. Entry of persons or vessels into this temporary safety zone is prohibited unless specifically authorized by the Captain of the Port, Los Angeles-Long Beach, or her designated representative.

DATES: This rule is effective without actual notice from December 14, 2021, until January 17, 2022. For purposes of enforcement, actual notice will be used from December 9, 2021, through December 14, 2021.

ADDRESSES: To view documents mentioned in this preamble as being

available in the docket, go to <https://www.regulations.gov>, type USCG–2021–0911 in the “SEARCH” box and click “SEARCH.” Click on Open Docket Folder on the line associated with this rule.

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or email LCDR Maria Wiener, Waterways Management, U.S. Coast Guard Sector Los Angeles-Long Beach; telephone (310) 357–1603, email Maria.C.Wiener@uscg.mil.

SUPPLEMENTARY INFORMATION:**I. Table of Abbreviations**

CFR Code of Federal Regulations
DHS Department of Homeland Security
FR Federal Register
NPRM Notice of proposed rulemaking
§ Section
U.S.C. United States Code

II. Background Information and Regulatory History

The Coast Guard is issuing this temporary rule without prior notice and opportunity to comment pursuant to authority under section 4(a) of the Administrative Procedure Act (APA) (5 U.S.C. 553(b)). This provision authorizes an agency to issue a rule without prior notice and opportunity to comment when the agency for good cause finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under 5 U.S.C. 553(b)(B), the Coast Guard finds that good cause exists for not publishing a notice of proposed rulemaking (NPRM) with respect to this rule to ensure the safety of response personnel and mariners during repairs of the damaged pipeline, as well as the potential oil recovery of said pipeline. It is impracticable to publish an NPRM, because we must establish this safety zone by December 9, 2021, due to immediate action needed to minimize potential danger to the public during oil recovery operations for the discharge of oil from pipeline.

Under 5 U.S.C. 553(d)(3), the Coast Guard finds that good cause exists for making this rule effective less than 30 days after publication in the **Federal Register**. Delaying the effective date of this rule would be contrary to public interest because immediate action is needed to respond to the potential safety hazards associated with the pipeline repair operations for the damaged pipeline.

III. Legal Authority and Need for Rule

The Coast Guard is issuing this rule under authority in 46 U.S.C. 70034 (previously 33 U.S.C. 1231). The Captain of the Port (COTP), Los

Angeles-Long Beach has determined that potential hazards associated with the pipeline repair and potential oil recovery operations in the vicinity of the damaged pipeline will be a safety concern for anyone within the following coordinates: 33°39.320' N, 118°06.851' W; 33°39.141' N, 118°06.247' W; 33°38.632' N, 118°06.453' W; 33°38.809' N, 118°07.064' W. This rule is necessary to safeguard the public during repair operations in response to an emergency situation; it would be impracticable for the Coast Guard to provide a public comment period on the rule because the response and repair efforts are ongoing.

IV. Discussion of the Rule

This rule establishes a safety zone effective from December 9, 2021, until January 17, 2022. The safety zone will encompass all navigable waters from the surface to the sea floor in an area bound by the following coordinates: 33°39.320' N, 118°06.851' W; 33°39.141' N, 118°06.247' W; 33°38.632' N, 118°06.453' W; 33°38.809' N, 118°07.064' W. No vessel or person will be permitted to enter the safety zone without obtaining permission from the COTP or a designated representative.

V. Regulatory Analyses

We developed this rule after considering numerous statutes and Executive orders related to rulemaking. Below we summarize our analyses based on a number of these statutes and Executive orders, and we discuss First Amendment rights of protestors.

A. Regulatory Planning and Review

Executive Orders 12866 and 13563 direct agencies to assess the costs and benefits of available regulatory alternatives and, if regulation is necessary, to select regulatory approaches that maximize net benefits. This rule has not been designated a “significant regulatory action,” under Executive Order 12866. Accordingly, this rule has not been reviewed by the Office of Management and Budget (OMB), and pursuant to OMB guidance it is exempt from the requirements of Executive order.

This regulatory action determination is based on the size, location, and duration, and time-of-day of the safety zone. Vessel traffic will be able to safely transit around this safety zone, which will impact a small designated area of Newport Beach in the vicinity of the repair operations. Moreover, the Coast Guard will issue a Broadcast Notice to Mariners via VHF-FM marine channel 16 about the zone, and the rule will allow vessels to seek permission to enter the zone.

B. Impact on Small Entities

The Regulatory Flexibility Act of 1980, 5 U.S.C. 601–612, as amended, requires Federal agencies to consider the potential impact of regulations on small entities during rulemaking. The term “small entities” comprises small businesses, not-for-profit organizations that are independently owned and operated and are not dominant in their fields, and governmental jurisdictions with populations of less than 50,000. The Coast Guard certifies under 5 U.S.C. 605(b) that this rule will not have a significant economic impact on a substantial number of small entities.

While some owners or operators of vessels intending to transit the safety zone may be small entities, for the reasons stated in section V.A above, this rule will not have a significant economic impact on any vessel owner or operator.

Under section 213(a) of the Small Business Regulatory Enforcement Fairness Act of 1996 (Pub. L. 104–121), we want to assist small entities in understanding this rule. If the rule would affect your small business, organization, or governmental jurisdiction and you have questions concerning its provisions or options for compliance, please call or email the person listed in the **FOR FURTHER INFORMATION CONTACT** section.

Small businesses may send comments on the actions of Federal employees who enforce, or otherwise determine compliance with, Federal regulations to the Small Business and Agriculture Regulatory Enforcement Ombudsman and the Regional Small Business Regulatory Fairness Boards. The Ombudsman evaluates these actions annually and rates each agency’s responsiveness to small business. If you wish to comment on actions by employees of the Coast Guard, call 1–888–REG–FAIR (1–888–734–3247). The Coast Guard will not retaliate against small entities that question or complain about this rule or any policy or action of the Coast Guard.

C. Collection of Information

This rule will not call for a new collection of information under the Paperwork Reduction Act of 1995 (44 U.S.C. 3501–3520).

D. Federalism and Indian Tribal Governments

A rule has implications for federalism under Executive Order 13132, Federalism, if it has a substantial direct effect on the States, on the relationship between the National Government and the States, or on the distribution of

power and responsibilities among the various levels of government. We have analyzed this rule under that order and have determined that it is consistent with the fundamental federalism principles and preemption requirements described in Executive Order 13132.

Also, this rule does not have tribal implications under Executive Order 13175, Consultation and Coordination with Indian Tribal Governments, because it does not have a substantial direct effect on one or more Indian tribes, on the relationship between the Federal Government and Indian tribes, or on the distribution of power and responsibilities between the Federal Government and Indian tribes.

E. Unfunded Mandates Reform Act

The Unfunded Mandates Reform Act of 1995 (2 U.S.C. 1531–1538) requires Federal agencies to assess the effects of their discretionary regulatory actions. In particular, the Act addresses actions that may result in the expenditure by a State, local, or tribal government, in the aggregate, or by the private sector of \$100,000,000 (adjusted for inflation) or more in any one year. Though this rule will not result in such an expenditure, we do discuss the effects of this rule elsewhere in this preamble.

F. Environment

We have analyzed this rule under Department of Homeland Security Directive 023–01, Rev. 1, associated implementing instructions, and Environmental Planning COMDTINST 5090.1 (series), which guide the Coast Guard in complying with the National Environmental Policy Act of 1969 (42 U.S.C. 4321–4370f), and have determined that this action is one of a category of actions that do not individually or cumulatively have a significant effect on the human environment. This rule involves a safety zone effective on December 9, 2021 until January 17, 2022, within the following coordinates: 33°39.320' N, 118°06.851' W; 33°39.141' N, 118°06.247' W; 33°38.632' N, 118°06.453' W; 33°38.809' N, 118°07.064' W. It is categorically excluded from further review under paragraph L60(c) of Appendix A, Table 1 of DHS Instruction Manual 023–01–001–01, Rev. 1.

G. Protest Activities

The Coast Guard respects the First Amendment rights of protesters. Protesters are asked to call or email the person listed in the **FOR FURTHER INFORMATION CONTACT** section to coordinate protest activities so that your message can be received without

jeopardizing the safety or security of people, places or vessels.

List of Subjects in 33 CFR Part 165

Harbors, Marine safety, Navigation (water), Reporting and recordkeeping requirements, Security measures, Waterways.

For the reasons discussed in the preamble, the Coast Guard amends 33 CFR part 165 as follows:

PART 165—REGULATED NAVIGATION AREAS AND LIMITED ACCESS AREAS

- 1. The authority citation for part 165 continues to read as follows:

Authority: 46 U.S.C. 70034, 70051; 33 CFR 1.05–1, 6.04–1, 6.04–6, and 160.5; Department of Homeland Security Delegation No. 00170.1, Revision No. 01.2.

- 2. Add § 165.T11–086 to read as follows:

§ 165.T11–086 Safety Zone; Oil Pipeline Repairs, San Pedro Bay, CA.

(a) *Location.* The safety zone encompasses all navigable waters from the surface to the sea floor in an area of the following coordinates: 33°39.320' N, 118°06.851' W; 33°39.141' N, 118°06.247' W; 33°38.632' N, 118°06.453' W; 33°38.809' N, 118°07.064' W.

(b) *Definitions.* For the purposes of this section, *designated representative* means a Coast Guard Patrol Commander, including a Coast Guard coxswain, petty officer, or other officer operating a Coast Guard vessel and a Federal, State, and local officer designated by or assisting the Captain of the Port Los Angeles-Long Beach

(COTP) in the enforcement of the safety zone.

(c) *Regulations.* (1) Under the general safety zone regulations in § 165.23, you may not enter the safety zone described in paragraph (a) of this section unless authorized by the COTP or the COTP's designated representative.

(2) To seek permission to enter, hail Coast Guard Sector Los Angeles-Long Beach on VHF–FM Channel 16 or call the 24-hour Command Center at (310) 521–3801. Those in the safety zone must comply with all lawful orders or directions given to them by the COTP or the COTP's designated representative.

(d) *Enforcement period.* This section will be enforced from December 9, 2021, until January 17, 2022, between 12:00 a.m. and 11:59 p.m. each day, or as announced via local Broadcast Notice to Mariners.

Dated: December 8, 2021.

R.E. Ore,

Captain, U.S. Coast Guard, Captain of the Port, Los Angeles-Long Beach.

[FR Doc. 2021–26982 Filed 12–13–21; 8:45 am]

BILLING CODE 9110–04–P

POSTAL SERVICE

39 CFR Part 20

International Competitive Services Product and Price Changes Correction

AGENCY: Postal Service™.

ACTION: Final rule; correction.

SUMMARY: The Postal Service published a final notice in the **Federal Register**, on

November 30, 2021, regarding the revisions to *Mailing Standards of the United States Postal Service*, International Mail Manual (IMM®), to reflect the prices, product features, and classification changes to Competitive Services and other minor changes, as established by the Governors of the Postal Service effective January 9, 2022. That document contained an error in the Certificate of Mailing Individual Pieces chart in that it incorrectly listed the firm mailing sheet (PS Form 3665), per piece (minimum 3) First-Class Mail International only with the price for all other qualifying classes of mail. There is no price change to First Class Mail International only. This document serves to correct the error by replacing First Class Mail International only to reflect all other qualifying classes of mail.

DATES: *Effective date:* January 9, 2022.

FOR FURTHER INFORMATION CONTACT: Dale Kennedy at 202–268–6592 or Kathy Frigo at 202–268–4178.

SUPPLEMENTARY INFORMATION:

Correction

On page 67863, column 3 under Certificate of Mailing Individual Pieces, revise the third line titled Firm mailing sheet (PS Form 3665), per piece (minimum 3) First-Class Mail International only to reflect Firm mailing sheet (PS Form 3665), per piece (minimum 3) All other qualifying classes of mail as follows:

- Certificate of mailing service: Prices for competitive international certificate of mailing service will be as follows:

CERTIFICATE OF MAILING

	Fee
Individual pieces:	
Individual article (PS Form 3817)	\$1.65
Duplicate copy of PS Form 3817 or PS Form 3665 (per page)	1.65
Firm mailing sheet (PS Form 3665), per piece (minimum 3)	
All other qualifying classes of mail	0.57
Bulk quantities:	
For first 1,000 pieces (or fraction thereof)	9.35
Each additional 1,000 pieces (or fraction thereof)	1.20
Duplicate copy of PS Form 3606	1.65

Ruth Stevenson,

Chief Counsel, Ethics and Legal Compliance.

[FR Doc. 2021–26971 Filed 12–13–21; 8:45 am]

BILLING CODE P