

Safety Agency (EASA) AD 2023–0052, dated March 14, 2023 (EASA AD 2023–0052).

(h) Exceptions to EASA AD 2023–0052

(1) Where EASA AD 2023–0052 refers to its effective date, this AD requires using the effective date of this AD.

(2) This AD does not adopt the “Remarks” section of EASA AD 2023–0052.

(3) Where the service information referenced in EASA AD 2023–0052 specifies repeating a step and recording certain values, replace the text “Do step 1 b again and record the capacitance values and then every 10 minutes for 60 min.” with “Repeat step 1 b and record the capacitance values every 10 minutes for 60 minutes.”

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2023–0052 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (j)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(k) Additional Information

For more information about this AD, contact Tim Dowling, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite

410, Westbury, NY 11590; phone: 206–231–3667; email: Timothy.P.Dowling@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A330–28–3141, dated December 16, 2022.

(ii) European Union Aviation Safety Agency (EASA) AD 2023–0052, dated March 14, 2023.

(3) For EASA AD 2023–0052, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; website airbus.com.

(5) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on July 13, 2023.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–15253 Filed 7–19–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–1501; Project Identifier MCAI–2023–00647–T]

RIN 2120–AA64

Airworthiness Directives; Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus Canada Limited Partnership Model BD–500–1A10 and BD–500–1A11 airplanes. This proposed AD was prompted by a report the engine fire extinguishing control and indication system did not illuminate correctly. This proposed AD would require installing a software update to the integrated cockpit control panel (ICCP) remote data concentrator (RDC), as specified in a Transport Canada AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by September 5, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2023–1501; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For material that is proposed for IBR in this NPRM, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888–663–3639; email: TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca; website: tc.canada.ca/en/aviation. It is also available at regulations.gov under Docket No. FAA–2023–1501.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

FOR FURTHER INFORMATION CONTACT: William Reisenauer, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email: 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2023-1501; Project Identifier MCAI-2023-00647-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to William Reisenauer,

Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email: 9-avs-nyaco-cos@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF-2023-28, dated May 4, 2023 (Transport Canada AD CF-2023-28) (also referred to as the MCAI), to correct an unsafe condition for certain Airbus Canada Limited Partnership Model BD-500-1A10 and BD-500-1A11 airplanes. The MCAI states a deficiency in the design of the engine fire extinguishing control and indication system was discovered. After the loss of one hot battery DC bus, the AVAIL legend on BTL 1 and BTL 2 push button annunciators (PBAs) will not illuminate green upon pressing the corresponding ENG FIRE PBA. This condition affects both L ENG FIRE and R ENG FIRE PBAs on the overhead panel. The misleading indication given by the AVAIL legend on BTL 1 and BTL 2 PBAs will affect the crew’s assessment of the situation. The crew may hesitate to extinguish an engine fire despite having access to a functional engine fire extinguishing system, or may reselect the FIRE PBA, resulting in loss of the ability to isolate and extinguish the fire.

The FAA is proposing this AD to address the unsafe condition on these products. You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1501.

Related Service Information Under 1 CFR Part 51

Transport Canada AD CF-2023-28 specifies procedures for installing the software update to the integrated cockpit control panel (ICCP) remote data concentrator (RDC) to restore the intended functionality of the PBA green indications.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES** section.

FAA’s Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in Transport Canada AD CF-2023-28 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate Transport Canada AD CF-2023-28 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with Transport Canada AD CF-2023-28 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Service information required by Transport Canada AD CF-2023-28 for compliance will be available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1501 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 76 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 6 work-hours × \$85 per hour = \$510	Up to \$7,500	Up to \$8,010	Up to \$608,760.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.): Docket No. FAA–2023–1501; Project Identifier MCAI–2023–00647–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by September 5, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Canada Limited Partnership (Type Certificate previously held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Model BD–500–1A10 and BD–500–1A11 airplanes, certificated in any category, as identified in Transport Canada AD CF–2023–28, dated May 4, 2023 (Transport Canada AD CF–2023–28).

(d) Subject

Air Transport Association (ATA) of America Code: 26, Fire protection.

(e) Unsafe Condition

This AD was prompted by a report the engine fire extinguishing control and indication system did not illuminate correctly. The FAA is issuing this AD to address the misleading indication given by the AVAIL legend on BTL 1 and BTL 2 Push Button Annunciators (PBAs) that will affect the crew's assessment of the situation. The unsafe condition, if not addressed, could result in the crew hesitating to extinguish an engine fire despite having access to a functional engine fire extinguishing system, or may reselect the FIRE PBA, resulting in loss of the ability to isolate and extinguish the fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Transport Canada AD CF–2023–28.

(h) Exceptions to Transport Canada AD CF–2023–28

Where Transport Canada AD CF–2023–28 refers to its effective date, this AD requires using the effective date of this AD.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested

using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada; or Airbus Canada Limited Partnership's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (i)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Additional Information

For more information about this AD, contact William Reisenauer, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email: 9-avs-nyaco-cos@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Transport Canada AD CF–2023–28, dated May 4, 2023.

(ii) [Reserved]

(3) Transport Canada AD CF–2023–28, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888–663–3639; email: *TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca*; website: *tc.canada.ca/en/aviation*.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the

National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on July 13, 2023.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–15274 Filed 7–19–23; 8:45 am]

BILLING CODE 4910–13–P

FEDERAL TRADE COMMISSION

16 CFR Part 312

RIN 3084–AB58

Children’s Online Privacy Protection Rule Proposed Parental Consent Method; Application of the ESRB Group for Approval of Parental Consent Method

AGENCY: Federal Trade Commission.

ACTION: Request for public comment.

SUMMARY: The Federal Trade Commission (FTC or Commission) requests public comment concerning the proposed parental consent method submitted by the Entertainment Software Rating Board, Yoti Ltd. and Yoti (USA) Inc., and SuperAwesome Ltd. (“the ESRB group”), under the Voluntary Commission Approval Processes provision of the Children’s Online Privacy Protection Rule.

DATES: Written comments must be received on or before August 21, 2023.

ADDRESSES: Interested parties may file a comment online or on paper, by following the instructions in the **SUPPLEMENTARY INFORMATION** section below. Write “Application for Parental Consent Method, Project No. P235402” on your comment and file your comment online through <https://www.regulations.gov>.

If you prefer to file a comment in hard copy, please write “Application for Parental Consent Method, Project No. P235402” on your comment and on the envelope and mail your comment to the following address: Federal Trade Commission, Office of the Secretary, 600 Pennsylvania Avenue NW, Suite CC–5610 (Annex P), Washington, DC 20580.

FOR FURTHER INFORMATION CONTACT:

Peder Magee, Attorney, (202–326–3538), or James Trilling, Attorney, (202–326–3497), Division of Privacy and Identity Protection, Federal Trade Commission, Washington, DC 20580.

SUPPLEMENTARY INFORMATION:

Section A. Background

On October 20, 1999, the Commission issued its final Rule¹ pursuant to the Children’s Online Privacy Protection Act, 15 U.S.C. 6501 *et seq.*, which became effective on April 21, 2000.² On December 19, 2012, the Commission amended the Rule, and these amendments became effective on July 1, 2013.³ The Rule requires certain website operators, among other things, to post privacy policies, provide notice, and obtain verifiable parental consent, prior to collecting, using, or disclosing personal information from children under the age of 13. The Rule enumerates methods for obtaining verifiable parental consent, while also allowing interested parties to file a written request for Commission approval of parental consent methods not currently enumerated.⁴ To be considered, parties must submit a detailed description of the proposed parental consent method, together with an analysis of how the method meets the requirements for parental consent described in 16 CFR 312.5(b)(1).

Pursuant to 16 CFR 312.12(a), the ESRB group has submitted a proposed parental consent method to the Commission for approval. The ESRB group proposes a consent mechanism that uses facial age estimation technology, which analyzes the geometry of the consenting person’s face to confirm the person is an adult. The full text of its application is available on the Commission’s website at www.ftc.gov and on the docket for this project at www.regulations.gov.

Section B. Questions on the Parental Consent Method

The Commission is seeking comment on the proposed parental consent method and is particularly interested in receiving comment on the questions that follow. These questions are designed to assist the Commission’s consideration of the application and should not be construed as a limitation on the issues on which public comment may be submitted. Responses to these questions should cite the number of the question being answered. For all comments submitted, please provide any data, statistics, or any other evidence, upon which those comments are based.

1. Is this method already covered by existing methods enumerated in 16 CFR 312.5(b)(2)?

2. If this is a new method, provide comments on whether the proposed

parental consent method meets the requirements for parental consent laid out in 16 CFR 312.5(b)(1). Specifically, the Commission is looking for comments on whether the proposed parental consent method is reasonably calculated, considering available technology, to ensure that the person providing consent is the child’s parent.

3. Does this proposed method pose a risk to consumers’ personal information, including consumers’ biometric information? If so, is that risk outweighed by the benefit to consumers and businesses of using this method?

4. Does this proposed method pose a risk of disproportionate error rates or other outcomes for particular demographic groups? If so, is that risk outweighed by the benefit to consumers and businesses of using this method?

Section C. Invitation To Comment

You can file a comment online or on paper. For the Commission to consider your comment, we must receive it on or before August 21, 2023. Write “Application for Parental Consent Method, Project No. P235402” on your comment. Your comment—including your name and your state—will be placed on the public record of this proceeding, including the <https://www.regulations.gov> website.

Because of the agency’s heightened security screening, postal mail addressed to the Commission is subject to delay. We strongly encourage you to submit your comments online through the <https://www.regulations.gov> website. To make sure the Commission considers your online comment, please follow the instructions on the web-based form.

If you file your comment on paper, write “Application for Parental Consent Method, Project No. P235402” on your comment and on the envelope, and mail your comment to the following address: Federal Trade Commission, Office of the Secretary, 600 Pennsylvania Avenue NW, Suite CC–5610 (Annex P), Washington, DC 20580.

Because your comment will be placed on the publicly accessible website at <https://www.regulations.gov>, you are solely responsible for making sure that your comment does not include any sensitive or confidential information. In particular, your comment should not include any sensitive personal information, such as your or anyone else’s Social Security number; date of birth; driver’s license number or other state identification number, or foreign country equivalent; passport number; financial account number; or credit or debit card number. You are also solely responsible for making sure that your

¹ 64 FR 59888 (1999).

² 16 CFR part 312.

³ 78 FR 3972 (2013).

⁴ 16 CFR 312.12(a); 78 FR at 3991–3992, 4013.