

mm), NHTSA explained that the increase in lens area is necessary because wide vehicles “are susceptible to build up of grime” and “an increase in lens area would enhance vehicle conspicuity and contribute to safety.”

Winnebago says that around July 2022, it was informed by a lamp supplier that there were concerns about the compliance of turn signals installed in certain Winnebago vehicles. Specifically, with the “minimum effective projected luminous area requirements of FMVSS No. 108,” Winnebago says they investigated the turn signals in the subject vehicles and confirmed that the “effective projected luminous lens area” is 6,361 square millimeters and thus, approximately 1,139 square millimeters smaller than the required minimum lens area.

Winnebago says that other than the size of the effective projected luminous lens area for the turn signals in the subject vehicles, the turn signals are otherwise fully compliant with all applicable performance requirements. Winnebago states that the turn signals at issue “have been in use for more than 15 years” and “is not aware of any crashes, injuries, customer complaints or field reports in connection with this noncompliance.” Winnebago states its belief that although the turn signal lens area is slightly smaller than the required minimum, they are still “likely to be imperceptible to both vehicle occupants and approaching drivers, and do not have an effect on the conspicuity of the motorhomes on which they are installed.”

Winnebago states its belief that NHTSA increased the required minimum lens area for turn signals in wide vehicles due to the concern of buildup of grime and dirt. Winnebago claims that the turn signals on motorhomes “are generally well maintained by their owners compared to other classes of wide vehicles. Thus, a slightly smaller turn signals would not reasonably result in a buildup of dirt and grime on turn signals . . .”

Winnebago concludes by stating its belief that the subject noncompliance is inconsequential to motor vehicle safety and its petition for relief from providing notice and remedy for the noncompliance be granted.

NHTSA notes that the statutory provisions (49 U.S.C. 30118(d) and 30120(h)) that permit manufacturers to file petitions for a determination of inconsequentiality allow NHTSA to exempt manufacturers only from the duties found in sections 30118 and 30120, respectively, to notify owners, purchasers, and dealers of a defect or noncompliance and to remedy the

defect or noncompliance. Therefore, any decision on this petition only applies to the subject motorhomes that Winnebago no longer controlled at the time it determined that the noncompliance existed. However, any decision on this petition does not relieve vehicle distributors and dealers of the prohibitions on the sale, offer for sale, or introduction or delivery for introduction into interstate commerce of the noncompliant motorhomes under their control after Winnebago notified them that the subject noncompliance existed.

(Authority: 49 U.S.C. 30118, 30120; delegations of authority at 49 CFR 1.95 and 501.8)

Otto G. Matheke III,

Director, Office of Vehicle Safety Compliance.

[FR Doc. 2023–16312 Filed 7–31–23; 8:45 am]

BILLING CODE 4910–59–P

DEPARTMENT OF THE TREASURY

Office of Foreign Assets Control

Notice of OFAC Sanctions Actions

AGENCY: Office of Foreign Assets Control, Treasury.

ACTION: Notice.

SUMMARY: The U.S. Department of the Treasury’s Office of Foreign Assets Control (OFAC) is publishing the names of persons that have been placed on OFAC’s Specially Designated Nationals and Blocked Persons List based on OFAC’s determination that one or more applicable legal criteria were satisfied. All property and interests in property subject to U.S. jurisdiction of these persons are blocked, and U.S. persons are generally prohibited from engaging in transactions with them.

DATES: See **SUPPLEMENTARY INFORMATION** section for applicable date(s).

FOR FURTHER INFORMATION CONTACT: OFAC: Andrea Gacki, Director, tel.: 202–622–2490; Associate Director for Global Targeting, tel.: 202–622–2420; Assistant Director for Licensing, tel.: 202–622–2480; Assistant Director for Regulatory Affairs, tel.: 202–622–4855; or the Assistant Director for Sanctions Compliance & Evaluation, tel.: 202–622–2490.

SUPPLEMENTARY INFORMATION:

Electronic Availability

The Specially Designated Nationals and Blocked Persons List and additional information concerning OFAC sanctions programs are available on OFAC’s website (<https://ofac.treasury.gov>).

Notice of OFAC Actions

On December 16, 2019, OFAC determined that the property and interests in property subject to U.S. jurisdiction of the following persons are blocked under the relevant sanctions authority listed below.

Individuals:

1. LOMURO, Martin Elia (a.k.a. LOMORO, Martin Elia; a.k.a. LOMORO, Martin Elias), Juba, South Sudan; DOB 28 Dec 1957; citizen South Sudan; alt. citizen Sudan; Gender Male; Passport D00002571 (South Sudan); alt. Passport D00009058 (Sudan) (individual) [SOUTH SUDAN].

Designated pursuant to Section 1(a)(i)(C) of Executive Order 13664 of April 3, 2014, “Blocking Property of Certain Persons With Respect to South Sudan” 79 FR 19283 (April 7, 2014) (E.O. 13664) for being responsible for or complicit in, or having engaged in, directly or indirectly, in or in relation to South Sudan, actions or policies that have the purpose or effect of expanding or extending the conflict in South Sudan or obstructing reconciliation or peace talks or processes.

2. JUUK, Kuol Manyang (a.k.a. JUUK CHAW, Kuol Manyang), Juba, South Sudan; DOB 01 Jan 1945; POB Mathiang Village, South Sudan; nationality South Sudan; Gender Male; Passport D00002510 (South Sudan) (individual) [SOUTH SUDAN].

Designated pursuant to Section 1(a)(i)(C) of E.O. 13664 for being responsible for or complicit in, or having engaged in, directly or indirectly, in or in relation to South Sudan, actions or policies that have the purpose or effect of expanding or extending the conflict in South Sudan or obstructing reconciliation or peace talks or processes.

Dated: July 27, 2023.

Andrea M. Gacki,

Director, Office of Foreign Assets Control, U.S. Department of the Treasury.

[FR Doc. 2023–16279 Filed 7–31–23; 8:45 am]

BILLING CODE 4810–AL–P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

Senior Executive Service Performance Review Board

AGENCY: Internal Revenue Service (IRS), Department of the Treasury.

ACTION: Notice.

SUMMARY: To announce a list of senior executives who comprise a standing roster that will serve on IRS’s Fiscal Year 2023 Senior Executive Service (SES) Performance Review Boards.

DATES: This list is effective September 1, 2023.

FOR FURTHER INFORMATION CONTACT: Sharnetta A. Walton, Director, Office of Executive Services at (202) 317–3817 or Rachel Winningham, Deputy Director,