This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2024-2666; Project Identifier MCAI-2024-00261-T]

RIN 2120-AA64

Airworthiness Directives; Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus Canada Limited Partnership Model BD-500-1A11 airplanes. This proposed AD was prompted by an investigation of an inservice hydraulic fluid leakage event that indicated the potential use of an uncalibrated torque wrench when tightening the union fittings at the pressure and return interfaces of all three rudder hydraulic power control units (PCUs). This proposed AD would require properly torquing the rudder PCU hydraulic fittings and applying the torque seal on the rudder PCU hydraulic fittings, as specified in a Transport Canada AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products. **DATES:** The FAA must receive comments on this proposed AD by February 3, 2025.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

• Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.

• *Fax:* 202–493–2251.

• *Mail:* U.S. Department of Transportation, Docket Operations, M–

30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA–2024–2666; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference: • For Transport Canada material identified in this proposed AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888–663–3639; email *TC.AirworthinessDirectives- Consignesdenavigabilite.TC@tc.gc.ca.* You may find this material on the Transport Canada website at *tc.canada.ca/en/aviation.* It is also available at *regulations.gov* under Docket No. FAA–2024–2666.

• You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

FOR FURTHER INFORMATION CONTACT: Brenda Buitrago Perez, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email *9-avsnyaco-cos@faa.gov.*

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA–2024–2666; Project Identifier MCAI–2024–00261–T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments. Federal Register Vol. 89, No. 245 Friday, December 20, 2024

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Brenda Buitrago Perez, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228 7300; email 9-avs-nyaco-cos@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF-2024-13, dated April 29, 2024 (Transport Canada AD CF-2024-13) (also referred to as the MCAI), to correct an unsafe condition for certain Airbus Canada Limited Partnership Model BD-500-1A11 airplanes. The MCAI states an investigation of an in-service leakage event indicated the potential use of an uncalibrated torque wrench when tightening the union fittings at the pressure and return interfaces of all three rudder PCUs. If not corrected, this condition could cause the union fittings to come loose and leak, resulting in the

Proposed Rules

potential loss of one or more hydraulic systems.

The FAA is proposing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2024–2666.

Material Incorporated by Reference Under 1 CFR Part 51

Transport Canada AD CF-2024-13 specifies procedures for properly torquing the rudder PCU hydraulic fittings and applying the torque seal on the rudder PCU hydraulic fittings, which includes cleaning any leaks at the coil B-nut connections, performing a visual inspection for hydraulic leaks for all rudder PCU coil tube fittings and repair. The repair includes tightening the nut to the specified torque, testing for leakage limits, and replacing any defective components. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in Transport Canada AD CF–2024–13 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to

use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate Transport Canada AD CF-2024–13 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with Transport Canada AD CF-2024-13 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Material required by Transport Canada AD CF-2024-13 for compliance will be available at regulations.gov under Docket No. FAA-2024-2666 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 5 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 9 work-hours \times \$85 per hour = Up to \$765	Up to \$0*	Up to \$765	Up to \$3,825.

* The FAA has received no definitive data on which to base the cost estimates for the replacement cost.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.): Docket No. FAA– 2024–2666; Project Identifier MCAI– 2024–00261–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by February 3, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Canada Limited Partnership (Type Certificate previously held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Model BD–500– 1A11 airplanes, certificated in any category, as identified in Transport Canada AD CF– 2024–13, dated April 29, 2024 (Transport Canada AD CF–2024–13).

(d) Subject

Air Transport Association (ATA) of America Code 29, Hydraulic Power.

(e) Unsafe Condition

This AD was prompted by an investigation of an in-service leakage event that indicated the use potential of an uncalibrated torque wrench when tightening the union fittings at the pressure and return interfaces of all three rudder hydraulic power control units (PCUs). The FAA is issuing this AD to address union fittings that could come loose and leak when improperly torqued. The unsafe condition, if not addressed, could result in the potential loss of one or more hydraulic systems.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Transport Canada AD CF–2024–13.

(h) Exception to Transport Canada AD CF-2024–13

(1) Where Transport Canada AD CF-2024-13 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where Transport Canada AD CF–2024– 13 refers to hours air time, this AD requires using flight hours.

(3) Where the material referenced in Transport Canada AD CF-2024-13 specifies to "perform a visual inspection for hydraulics leaks for all Rudder PCUs coil tube fitting (Upper, Middle and Lower)" this AD requires replacing that text with "perform a visual inspection for hydraulics leaks for all Rudder PCUs coil tube fitting (Upper, Middle and Lower), and if any leak is found, the leak must be repaired before further flight."

(i) No Reporting Requirement

Although the material referenced in Transport Canada AD CF–2024–13 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, AIR-520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, AIR–520, Continued Operational Safety Branch, FAA; or Transport Canada; or Airbus Canada Limited Partnership's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Additional Information

For more information about this AD, contact Brenda Buitrago Perez, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228 7300; email *9-avs-nyaco-cos*@ *faa.gov.*

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Transport Canada AD CF–2024–13, dated April 29, 2024.

(ii) [Reserved]

(3) For Transport Canada material identified in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888– 663–3639; email *TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca.* You may find this Transport Canada material on the Transport Canada website at *tc.canada.ca/en/aviation.*

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ ibr-locations or email fr.inspection@nara.gov.

Issued on December 16, 2024.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2024–30310 Filed 12–19–24; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF DEFENSE

Office of the Secretary

32 CFR Part 310

[Docket ID: DoD-2024-OS-0137]

RIN 0790-AL80

Privacy Act of 1974; Implementation

AGENCY: Office of the Secretary of Defense, Department of Defense (DoD).

ACTION: Proposed rule.

SUMMARY: The Department of Defense (Department or DoD) is giving concurrent notice of a modified system of records titled "Defense Sexual Assault Incident Database," DHRA 06, and this rulemaking, which exempts portions of this system of records from certain provisions of the Privacy Act to avoid interference during the conduct of criminal, civil, or administrative actions or investigations.

DATES: Send comments on or before February 18, 2025.

ADDRESSES: You may submit comments, identified by docket number, Regulation Identifier Number (RIN), and title, by any of the following methods.

* Federal Rulemaking Portal: https:// www.regulations.gov. Follow the instructions for submitting comments.

* *Mail:* Department of Defense, Office of the Assistant to the Secretary of Defense for Privacy, Civil Liberties, and Transparency, Regulatory Directorate, 4800 Mark Center Drive, Attn: Mailbox 24, Suite 05F16, Alexandria, VA 22350– 1700.

Instructions: All submissions received must include the agency name and docket number or RIN for this **Federal Register** document. The general policy for comments and other submissions from members of the public is to make these submissions available for public viewing on the internet at *https:// www.regulations.gov* as they are received without change, including any personal identifiers or contact information.

FOR FURTHER INFORMATION CONTACT: Ms. Rahwa Keleta, *OSD.DPCLTD@mail.mil;* (703) 571–0070.

SUPPLEMENTARY INFORMATION:

I. Background

In accordance with the Privacy Act of 1974, the Office of the Secretary of Defense is modifying and reissuing a system of records titled "Defense Sexual Assault Incident Database," DHRA 06. This system of records was originally established to centralize case-level sexual assault data involving a member of the Armed Forces, in a manner consistent with law and DoD regulations for Unrestricted and Restricted reporting and to facilitate reports to Congress on claims of retaliation in connection with an Unrestricted Report of sexual assault made by or against a member of the Armed Forces.

II. Privacy Act Exemption

The Privacy Act permits Federal agencies to exempt eligible records in a system of records from certain